

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Arncliffe Public School (7401)
Region : Sydney
State Electorate : Rockdale
Local Government Area : Rockdale

Initial Survey : Noel Arnold & Associates : 29 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Aug - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/General Learning - 1879 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - Entry Vestibule

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Movement

No Asbestos

B00A - R0006 - Principal

No Asbestos

B00A - R0007 - Clerical Office/Workroom

No Asbestos

B00A - R0008 - Movement

No Asbestos

B00A - R0009 - Duplicating Workroom

No Asbestos

B00A - R0010 - Security Store

No Asbestos

B00A - R0011 - General Storeroom

No Asbestos

B00A - R0012 - Home Base

No Asbestos

B00A - R0013 - Withdrawal Space - 1hb

No Asbestos

B00A - R0014 - Withdrawal Space - 1hb

No Asbestos

B00A - R0015 - Home Base

No Asbestos

B00A - R0016 - Personal Effects Storage

No Asbestos

B00A - R0020 - Movement

No Asbestos

B00A - R0021 - Movement

No Asbestos

B00A - R0022 - Stairs

No Asbestos

B00A - R0023 - Stairs

No Asbestos

B00A - R1001 - Personal Effects Storage

No Asbestos

B00A - R1002 - Special Programs Room

No Asbestos

B00A - R1003 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R1004 - Home Base

No Asbestos

B00A - R1005 - Withdrawal Space - 1hb

No Asbestos

B00A - R1006 - Withdrawal Space - 1hb

No Asbestos

B00A - R1007 - Home Base

No Asbestos

B00A - R1009 - Stairs

No Asbestos

B00A - R1010 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning/Library - 1861 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00B - M0001 - Security Store**

No Asbestos

B00B - M0002 - Library Office/Workroom

No Asbestos

B00B - M0003 - Movement

No Asbestos

B00B - M0004 - Movement

No Asbestos

B00B - M0005 - Stairs

No Asbestos

B00B - M0006 - Stairs

No Asbestos

B00B - R0001 - Interview

No Asbestos

B00B - R0002 - Reading Area

No Asbestos

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - Cleaning Supplies

No Asbestos

B00B - R0005 - Entry Vestibule

No Asbestos

B00B - R0006 - Movement

No Asbestos

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Movement

No Asbestos

B00B - R0009 - Home Base

No Asbestos

B00B - R0010 - Clerical Office/Workroom

No Asbestos

B00B - R0011 - Security Store

No Asbestos

B00B - R0012 - Reading Area

No Asbestos

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - Stairs

No Asbestos

B00B - R1001 - Home Base

No Asbestos

B00B - R1002 - Movement

No Asbestos

B00B - R1003 - Plant

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R1004 - Movement

No Asbestos

B00B - R1005 - Home Base

No Asbestos

B00B - R1006 - Staff Room Annexe

No Asbestos

B00B - R1007 - Home Base

No Asbestos

B00B - R1008 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1879 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00C - R0001 - Handwashing Facilities**

Wall Linings Internal	Flat AC Sheeting	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
7401/B00C/R0004/Wall Linings Internal/S12					Chrysotile (white asbestos)	

B00C - R0002 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	10m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
7401/B00C/R0004/Wall Linings Internal/S12					Chrysotile (white asbestos)	

B00C - R0003 - General Storeroom

No Asbestos

B00C - R0004 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	10m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
7401/B00C/R0004/Wall Linings Internal/S12					Chrysotile (white asbestos)	

B00C - R0005 - Sick Bay

Wall Linings Internal	Flat AC Sheeting	6m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
7401/B00C/R0004/Wall Linings Internal/S12					Chrysotile (white asbestos)	

B00C - R0006 - Staff Kitchen

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Movement

No Asbestos

B00C - R0009 - Staff Room

Floor Coverings Res/Textile	Vinyl Tiles					
7401/B00C/R0009/Floor Coverings Res/Textile/S2					No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1879 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00H/Eaves Linings/S7					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No access available to access underfloor void area					

Interior

B00D - R0001 - Home Base

No Asbestos

B00D - R0004 - Movement

No Asbestos

B00D - R0009 - Home Base

No Asbestos

B00D - R0010 - Home Base

No Asbestos

B00D - R0011 - Home Base

No Asbestos

B00D - R0012 - Movement

No Asbestos

B00D - R0013 - General Assistant/Bulk Store

No Asbestos

B00D - R0014 - Withdrawal Space - 2hb

No Asbestos

B00D - R0015 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities/General Learning - 1879 - Timber (Timber)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00F - R0001 - Movement**

No Asbestos

B00F - R0002 - Security Store

Wall Linings Internal	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected

B00F - R0003 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected

B00F - R0004 - Home Base

Wall Linings Internal	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected

B00F - R0005 - General Storeroom

Wall Linings Internal	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected

B00F - R0006 - Toilets - Girls

Wall Linings Internal	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0007 - Toilets - Boys

Wall Linings Internal	Flat AC Sheeting 7401/B00F/R0007/Wall Linings Internal/S1	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0008 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other/General Learning - 1879 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Low Priority (2-3)
	7401/B00G/Underfloor Voids/S8					Chrysotile (white asbestos)

Interior**B00G - R0001 - Other - Regional Use**

No Asbestos

B00G - R0002 - Other - Regional Use

No Asbestos

B00G - R0003 - Other - Regional Use

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0004 - Other - Regional Use

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0005 - Other - Regional Use

No Asbestos

B00G - R0006 - Other - Regional Use

Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0007 - Other - Regional Use

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0008 - Other - Regional Use

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0009 - Other - Regional Use

No Asbestos

B00G - R0010 - Other - Regional Use

Ceiling Structures/Linings	Flat AC Sheeting	44m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0011 - Other - Regional Use

No Asbestos

B00G - R0012 - Other - Regional Use

No Asbestos

B00G - R0013 - Other - Regional Use

Ceiling Structures/Linings	Flat AC Sheeting	85m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Floor Coverings Res/Textile	Vinyl Tiles					
	7401/B00G/R0015/Floor Coverings Res/Textile/S5					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00G - R0014 - Other - Regional Use						
No Asbestos						
B00G - R0015 - Other - Regional Use						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles					
	7401/B00G/R0015/Floor Coverings Res/Textile/S5			No Asbestos Detected		
B00G - R0016 - Other - Regional Use						
No Asbestos						
B00G - R0017 - Other - Regional Use						
No Asbestos						
B00G - R0018 - Other - Regional Use						
No Asbestos						
B00G - R0019 - Other - Regional Use						
No Asbestos						
B00G - R0020 - Stairs						
No Asbestos						
B00G - R0021 - Stairs						
No Asbestos						
B00G - R1001 - Movement						
No Asbestos						
B00G - R1002 - Practical Activities - 1hb						
Ceiling Structures/Linings	Flat AC Sheeting	131m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles					
	7401/B00G/R0015/Floor Coverings Res/Textile/S5			No Asbestos Detected		
B00G - R1003 - Special Programs Room						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00G - R1004 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	7401/B00G/R1002/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles					
	7401/B00G/R0015/Floor Coverings Res/Textile/S5			No Asbestos Detected		
B00G - R1005 - Staff Room Annexe						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles					
	7401/B00G/R0015/Floor Coverings Res/Textile/S5			No Asbestos Detected		
B00G - R1006 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	7401/B00G/R0015/Floor Coverings Res/Textile/S5				No Asbestos Detected	
B00G - R1007 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
B00G - R1008 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00G/R1002/Ceiling Structures/Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
B00G - R1009 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	7401/B00G/R1002/Ceiling Structures/Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
B00G - R1010 - Stairs						
No Asbestos						
B00G - R9001 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other-D.E.C. Admin - 1879 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 7401/B00H/Eaves Linings/S7	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No access possible into underfloor void area					

Interior**B00H - M1001 - Other - D.E.T. Admin**

No Asbestos

B00H - M1002 - Other - D.E.T. Admin

No Asbestos

B00H - R0001 - Other - D.E.T. Admin

No Asbestos

B00H - R0002 - Other - D.E.T. Admin

No Asbestos

B00H - R0003 - Other - D.E.T. Admin

No Asbestos

B00H - R0004 - Other - D.E.T. Admin

No Asbestos

B00H - R0005 - Other - D.E.T. Admin

No Asbestos

B00H - R0006 - Other - D.E.T. Admin

No Asbestos

B00H - R0007 - Other - D.E.T. Admin

No Asbestos

B00H - R0008 - Other - D.E.T. Admin

No Asbestos

B00H - R0009 - Other - D.E.T. Admin

No Asbestos

B00H - R0010 - Other - D.E.T. Admin

No Asbestos

B00H - R0011 - Other - D.E.T. Admin

No Asbestos

B00H - R0012 - Other - D.E.T. Admin

No Asbestos

B00H - R0013 - Other - D.E.T. Admin

No Asbestos

B00H - R0014 - Other - D.E.T. Admin

No Asbestos

B00H - R0015 - Other - D.E.T. Admin

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
7401/B00H/R0016/Ceiling Structures/Linings/S10						

B00H - R0016 - Other - D.E.T. Admin

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
7401/B00H/R0016/Ceiling Structures/Linings/S10						

B00H - R0017 - Other - D.E.T. Admin

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7401/B00H/R0016/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
B00H - R0018 - Other - D.E.T. Admin						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7401/B00H/R0016/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
B00H - R0019 - Other - D.E.T. Admin						
No Asbestos						
B00H - R0020 - Other - D.E.T. Admin						
No Asbestos						
B00H - R0021 - Other - D.E.T. Admin						
No Asbestos						
B00H - R0022 - Other - D.E.T. Admin						
No Asbestos						
B00H - R0023 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1001 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1002 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1003 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1004 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1005 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1006 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1007 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1008 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1009 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1010 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1011 - Other - D.E.T. Admin						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7401/B00H/R1011/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
B00H - R1012 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1013 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1014 - Other - D.E.T. Admin						
No Asbestos						
B00H - R1015 - Other - D.E.T. Admin						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 1879 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00I - R0001 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Sheet					
	7401/B00I/R0001/Floor Coverings Res/Textile/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00I/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00I - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00I/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					
	7401/B00I/R0004/Wall Linings Internal/S11					No Asbestos Detected

B00I - R0003 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00I/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00I - R0004 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	77m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00I/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00I - R0005 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00I/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00I - R0006 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00I/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Sheet					
	7401/B00I/R0001/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00I - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00I/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00I - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7401/B00I/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00J - Communal Facilities - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00J - R0001 - Canteen**

No Asbestos

B00J - R0002 - Canteen Office/Store

No Asbestos

B00J - R0003 - Communications Room

No Asbestos

B00J - R0004 - P.E. Store

No Asbestos

B00J - R0005 - Toilets - Boys/Disabled Cubicle

No Asbestos

B00J - R0006 - Main Switch Board

No Asbestos

B00J - R0007 - Garden Store

No Asbestos

B00J - R0008 - Hall Chair Store

No Asbestos

B00J - R0009 - Shower/Change

No Asbestos

B00J - R0010 - Movement

No Asbestos

B00J - R0011 - Raised Platform

No Asbestos

B00J - R0012 - Movement

No Asbestos

B00J - R0013 - Movement

No Asbestos

B00J - R0014 - Communal Space

No Asbestos

B00J - R0015 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Administration - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0002 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0003 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0004 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0005 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0006 - Security Store

No Asbestos

B00K - R0007 - Sick Bay

No Asbestos

B00K - R0008 - Access Shower/Toilet

No Asbestos

B00K - R0009 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0010 - Staff Toilet

No Asbestos

B00K - R0011 - Cleaning Distributed Store

No Asbestos

B00K - R0012 - Duplicating Workroom

No Asbestos

B00K - R0013 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0014 - Movement

No Asbestos

B00K - R0015 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - Practical Activities - 1hb

No Asbestos

B00M - R0002 - Home Base Store

No Asbestos

B00M - R0003 - Home Base

No Asbestos

B00M - R0004 - Isolation Space

No Asbestos

B00M - R0005 - Practical Activities - 1hb

No Asbestos

B00M - R0006 - Home Base Store

No Asbestos

B00M - R0007 - Home Base

No Asbestos

B00M - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 750 - D11542 - Learning Unit - ESL : Placement Date - 3/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

OS 603 - D14930 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/12/2005

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

7401_ASB_010713_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017