


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Belmont Public School (1183)
Region : Hunter/Central Coast
State Electorate : Swansea
Local Government Area : Lake Macquarie

Initial Survey : Noel Arnold & Associates : 14 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00A - Library - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00A - R0001 - Reading Area

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0002 - Library Office/Workroom

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0003 - Security Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00B - Administration/Special Purpose - 1965 - Brick/Block (Brick/Block)

Exterior

| | | | | | | |
|------------------|----------------------------|------|--------------|--------------------|---------|------------------------------------|
| Eaves Linings | Flat AC Sheeting | 10m2 | North, South | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 1183/B00B/Eaves Linings/S1 | | | | | Chrysotile (white asbestos) |
| Ceiling Voids | Requires Inspection | | | | | |
| Underfloor Voids | Requires Inspection | | | | | |

Interior

B00B - R0001 - Kiln Room

| | | | | | | |
|----------------------------|---|-----|------------|--------------------|---------|------------------------------------|
| In-fill-panel above Door | Flat AC Sheeting | 1m2 | East | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 1183/B00B/R0001/Panel above Door/S2 | | | | | Chrysotile (white asbestos) |
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 1183/B00B/R0002/Ceiling Structures/Linings/S3 | | | | | Chrysotile (white asbestos) |

B00B - R0002 - General Storeroom

| | | | | | | |
|----------------------------|---|-----|------------|--------------------|---------|------------------------------------|
| In-fill-panel above Door | Flat AC Sheeting | 1m2 | West | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 1183/B00B/R0001/Panel above Door/S2 | | | | | Chrysotile (white asbestos) |
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 1183/B00B/R0002/Ceiling Structures/Linings/S3 | | | | | Chrysotile (white asbestos) |

B00B - R0003 - General Assistant/Bulk Store

| | | | | | | |
|----------------------------|---|------|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 16m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 1183/B00B/R0002/Ceiling Structures/Linings/S3 | | | | | Chrysotile (white asbestos) |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00C - Pupil Facilities - 1998 - Brick/Block (Brick/Block)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00C - R0001 - Toilets - Boys

No Asbestos

B00C - R0002 - Kiln Room

No Asbestos

B00C - R0003 - Toilets - Girls

No Asbestos

B00C - R0004 - Canteen

No Asbestos

B00C - R0005 - Canteen Office/Store

No Asbestos

B00C - R0006 - Movement

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00D - General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00D - R0001 - Toilets - Boys

No Asbestos

B00D - R0002 - Cleaning Distributed Store

No Asbestos

B00D - R0003 - Toilets - Girls

No Asbestos

B00D - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Practical Activities - 1hb

No Asbestos

B00D - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0009 - Practical Activities - 1hb

No Asbestos

B00D - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0013 - Practical Activities - 1hb

No Asbestos

B00D - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0015 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0017 - Practical Activities - 1hb

No Asbestos

B00D - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0020 - Movement

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00E - R0001 - Practical Activities - 1hb

No Asbestos

B00E - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Practical Activities - 1hb

No Asbestos

B00E - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0009 - Cleaning Distributed Store

No Asbestos

B00E - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0011 - Practical Activities - 1hb

No Asbestos

B00E - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0013 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0015 - Practical Activities - 1hb

No Asbestos

B00E - R0016 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0018 - Movement

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00F - General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00F - R0001 - Disabled Toilet

No Asbestos

B00F - R0002 - Cleaning Distributed Store

No Asbestos

B00F - R0003 - Security Store

No Asbestos

B00F - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Practical Activities - 1hb

No Asbestos

B00F - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0012 - Practical Activities - 1hb

No Asbestos

B00F - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0014 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0015 - Practical Activities - 1hb

No Asbestos

B00F - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0019 - Practical Activities - 1hb

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|--|----------------------|--------|--------------------|--|-------------|------------------|
| Sample No | | | | | Test Result | |
| B00F - R0020 - Home Base Store | | | | | | |
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found | | | | | |
| B00F - R0021 - Home Base Store | | | | | | |
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found | | | | | |
| B00F - R0022 - Distribution Board | | | | Note: No inspection of live electrical installation. | | |
| No Asbestos | | | | | | |
| B00F - R0023 - Practical Activities - 1hb | | | | | | |
| No Asbestos | | | | | | |
| B00F - R0024 - Home Base | | | | | | |
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found | | | | | |
| B00F - R0025 - Withdrawal Space - 1hb | | | | | | |
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found | | | | | |
| B00F - R0026 - Home Base | | | | | | |
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found | | | | | |
| B00F - R0027 - Practical Activities - 1hb | | | | | | |
| No Asbestos | | | | | | |
| B00F - R0028 - Home Base Store | | | | | | |
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found | | | | | |
| B00F - R0029 - Movement | | | | | | |
| No Asbestos | | | | | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00G - General Learning/Special Purpose Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Access Shower/Toilet

No Asbestos

B00G - R0003 - Main Switch Board

No Asbestos

B00G - R0004 - Special Programs Room

No Asbestos

B00G - R0005 - Special Programs Store

No Asbestos

B00G - R0006 - Withdrawal Space - 2hb

No Asbestos

B00G - R0007 - Practical Activities - 1hb

No Asbestos

B00G - R0008 - Home Base

No Asbestos

B00G - R0009 - Home Base Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B0AA - Administration - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B0AA - R0001 - Entry Vestibule

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0002 - Duplicating Workroom

No Asbestos

B0AA - R0003 - Sick Bay

No Asbestos

B0AA - R0004 - Sick Bay - Shower/Toilet

No Asbestos

B0AA - R0005 - Interview

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0006 - Deputy Principal

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0007 - Deputy Principal

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0008 - Staff Room Annexe

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0009 - Staff Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0010 - Cleaning Distributed Store

No Asbestos

B0AA - R0011 - Main Switch Board

No Asbestos

B0AA - R0012 - Staff Toilet

No Asbestos

B0AA - R0013 - Staff Toilet

No Asbestos

B0AA - R0014 - Staff Toilet

No Asbestos

B0AA - R0015 - Communications Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0016 - Security Store

No Asbestos

B0AA - R0017 - Principal

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0018 - Clerical Office

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0019 - Movement

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B0AA - R0020 - Movement

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

B0AB - Communal Facilities - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B0AB - R0001 - Garden Store

No Asbestos

B0AB - R0002 - Cleaning Supplies

No Asbestos

B0AB - R0003 - Hall Chair Store

No Asbestos

B0AB - R0004 - Sports Store

No Asbestos

B0AB - R0005 - General Assistant/Bulk Store

No Asbestos

B0AB - R0006 - Toilets - Girls

No Asbestos

B0AB - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0AB - R0008 - Communications Cupboard

No Asbestos

B0AB - R0009 - Movement

No Asbestos

B0AB - R0010 - Movement

No Asbestos

B0AB - R0011 - Raised Platform

No Asbestos

B0AB - R0012 - Communal Space

No Asbestos

B0AB - R0013 - Toilets - Boys

No Asbestos

B0AB - R0014 - Hall Chair Store

No Asbestos

B0AB - R0015 - Hall Chair Store

No Asbestos

B0AB - R0016 - Hall Chair Store

No Asbestos

B0AB - R0017 - Cleaning Distributed Store

No Asbestos

B0AB - R0018 - Disabled Toilet

No Asbestos

B0AB - R0019 - Movement

No Asbestos

B0AB - R0020 - Movement

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017