


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bingara Central School (1234)
Region : New England
State Electorate : Northern Tablelands
Local Government Area : Gwydir

Initial Survey : Noel Arnold & Associates : 21 - May - 2008
Reviewed By : Grencap-NAA : 04 - May - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1955 - Brick/Block (Brick/Block)**Exterior**

Ceiling Void No Asbestos Found

Interior**B00A - R0001 - Raised Platform (27.09 m2)**

No Asbestos

B00A - R0002 - Communal Space (138.54 m2)

No Asbestos

B00A - R0003 - Staff Room (63.72 m2)

No Asbestos

B00A - R0004 - Movement (11.88 m2)

No Asbestos

B00A - R0005 - Main Switch Board (2.41 m2)

Electrical Backing Board	Resinous Board					
	1234/B00K/R0004/Electrical Backing Board/S8					No Asbestos Detected

B00A - R0006 - Practical Activities - 1hb (2.15 m2)

No Asbestos

B00A - R0007 - Toilets - Boys/Girls (1.56 m2)

No Asbestos

B00A - R0008 - Home Base (64.24 m2)

No Asbestos

B00A - R0011 - General Storeroom (2.51 m2)

No Asbestos

B00A - R0012 - General Storeroom (1.3 m2)

Floor Coverings Res/Textile	Vinyl Tiles	1.3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00A/R0012/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
	1234/B00A/R0012/Floor Coverings Res/Textile/S28					No Asbestos Detected

B00A - R0013 - Interview (15.41 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	15.37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00A/R0012/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
	1234/B00A/R0012/Floor Coverings Res/Textile/S28					No Asbestos Detected

B00A - R0015 - Movement (2.05 m2)

No Asbestos

B00A - R0016 - Entry Vestibule (13.32 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	13.39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00A/R0012/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
	1234/B00A/R0012/Floor Coverings Res/Textile/S28					No Asbestos Detected

B00A - R0017 - Clerical Office (23.69 m2)

No Asbestos

B00A - R0018 - Duplicating Workroom (17.11 m2)

No Asbestos

B00A - R0019 - Security Store (12.48 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
B00A - R0020 - Movement (4.75 m2)						
No Asbestos						
B00A - R0021 - Principal (22.16 m2)						
No Asbestos						
B00A - R0022 - Staff Room Annexe (14.44 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	1234/B00A/R0036/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00A - R0023 - Special Programs Room (62.1 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	1234/B00A/R0023/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00A - R0025 - Personal Effects Storage (8.82 m2)						
No Asbestos						
B00A - R0026 - General Storeroom (6.43 m2)						
No Asbestos						
B00A - R0030 - Movement (1.52 m2)						
No Asbestos						
B00A - R0031 - General Storeroom (13.92 m2)						
No Asbestos						
B00A - R0032 - Special Programs Room (47.26 m2)						
No Asbestos						
B00A - R0033 - Home Base (52.24 m2)						
No Asbestos						
B00A - R0034 - Movement (10.23 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)
B00A - R0035 - Cleaning Supplies (6.13 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	1234/B00A/R0035/Floor Coverings Res/Textile/S13					No Asbestos Detected
B00A - R0036 - Deputy Principal (17.15 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	1234/B00A/R0036/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00A - R0037 - Sick Bay - Shower/Toilet (4.64 m2)						
No Asbestos						
B00A - R0038 - Sick Bay - Shower/Toilet (4.66 m2)						
No Asbestos						
B00A - R0039 - Sick Bay - Shower/Toilet (3.41 m2)						
No Asbestos						
B00A - R0040 - Sick Bay (12.36 m2)						
No Asbestos						
B00A - R0041 - Movement (5.36 m2)						
No Asbestos						
B00A - R0042 - Staff Toilet (6.73 m2)						
No Asbestos						
B00A - R0043 - Movement (12.15 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00A - R0044 - Movement (112.52 m2)

No Asbestos

B00A - R0045 - Covered Area (7.93 m2)

No Asbestos

B00A - R0046 - Home Base (84.51 m2)

No Asbestos

B00A - R0047 - Home Base (85.53 m2)

No Asbestos

B00A - R0048 - Home Base (58.33 m2)

No Asbestos

B00A - R0049 - Home Base (64.42 m2)

No Asbestos

B00A - R0050 - Home Base (61.8 m2)

No Asbestos

B00A - R0051 - Movement (64.38 m2)

No Asbestos

B00A - R0052 - External Movement (293.28 m2)

No Asbestos

B00A - R0053 - External Movement (79.11 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities/Mechanical Services - 1955 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00B - R0001 - Drinking Facilities (2.66 m2)

No Asbestos

B00B - R0002 - Dust Extraction Space (11.43 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Technological & Applied Studies - 1993 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00C - R0001 - Movement (29.28 m2)

No Asbestos

B00C - R0002 - Workshop Area (57.98 m2)

No Asbestos

B00C - R0003 - Welding Area (8.95 m2)

No Asbestos

B00C - R0004 - Materials Store (3.09 m2)

No Asbestos

B00C - R0005 - Kiln Room (5.61 m2)

No Asbestos

B00C - R0006 - Materials Store (31.94 m2)

Floor Coverings Res/Textile	Vinyl Sheet
-----------------------------	-------------

1234/B00C/R0006/Floor Coverings Res/Textile/S17

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Agricultural Science - 1955 - Timber (Timber)

Exterior

Packing	Flat AC Sheeting 1234/B00D/Packing Around West Door/S5	No Asbestos Detected				
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00D - R0001 - Animal Space (48.11 m2)

No Asbestos

B00D - R0002 - Animal Space (12.08 m2)

No Asbestos

B00D - R0003 - Class Tools Storage (12.33 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1913 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	Packing		1234/B00E/Underfloor Voids - Packing to Floor Joists/S18			No Asbestos Detected
Ceiling Voids - Raked Ceiling	No Asbestos Found					

Interior

B00E - R0001 - Movement (15.87 m2)

No Asbestos

B00E - R0002 - Computer Learning Space (42.19 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library - 1970 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- ceiling to under side of roof

Underfloor Voids - Slab on Ground
No Asbestos Found

Interior**B00F - R0001 - Reading Area (161.58 m2)**

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0002 - Seminar/Study (53.04 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0003 - Library Office/Workroom (19.62 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0004 - Librarian (5.99 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0005 - Movement (29.47 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0006 - Staff Toilet (3.29 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0007 - Distribution Board (0.66 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0008 - Cleaning Distributed Store (2 m2)

No Asbestos

B00F - R0009 - Staff Toilet (3.52 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0010 - K.L.A. Store (12.09 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0011 - K.L.A. Store (12.52 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0012 - Seminar/Study (12.96 m2)

Ceiling Structures/Linings Vermiculite
1234/B00F/R0001/Ceiling Structures/Linings/S11
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0013 - Seminar/Study (13.02 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Vermiculite
 1234/B00F/R0001/Ceiling Structures/Linings/S11 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0014 - Movement (89.6 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Technological & Applied Studies/Science - 1972 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00G/Eaves Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids - Packing to Floor Joists	Packing	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1234/B00G/Underfloor Voids - Packing to Floor Joists/S20				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids - Raked Ceiling	No Asbestos Found					

Interior**B00G - R0001 - Food Technology L.S. (116.33 m2)**

No Asbestos

B00G - R0002 - Food/Research Space (16.98 m2)

No Asbestos

B00G - R0003 - Laundry (8.16 m2)

No Asbestos

B00G - R0004 - Apparatus Store (12.68 m2)

No Asbestos

B00G - R0005 - Laboratory L.S. (92.39 m2)

Fume Cupboard	Flat AC Sheeting	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00G/R0005/Fume Cupboard/S10				Chrysotile (white asbestos)	

B00G - R0006 - Preparation (28.36 m2)

Fume Cupboard	Vinyl Tiles	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1234/B00G/R0006/Fume Cupboard/S21				Chrysotile (white asbestos)	
Fume Cupboard	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00G/R0006/Fume Cupboard/S22				Chrysotile (white asbestos)	
Fume Cupboard	Adhesive					No Asbestos Detected
	1234/B00G/R0006/Fume Cupboard/S29					

B00G - R0007 - Apparatus Store (9.46 m2)

No Asbestos

B00G - R0008 - Movement (38.97 m2)

No Asbestos

B00G - R0009 - Distribution Board (0.63 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0010 - Movement (9.65 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1962 - Brick/Block (Brick/Block)**Exterior**

Wall Cladding	Flat AC Sheeting 1234/B00N/Wall Cladding/S1					No Asbestos Detected
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					

Interior**B00H - R0001 - Toilets - Girls (40.88 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00H - R0002 - Senior Seminar (23.69 m2)

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting	20m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00K/R0007/Wall Linings Internal/S7					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R0003 - General Storeroom (12.2 m2)

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting	15m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00K/R0007/Wall Linings Internal/S7					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R0004 - Movement (8.54 m2)

No Asbestos

B00H - R0005 - Staff Toilet (5.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00H - R0006 - Canteen Office/Store (5.4 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00H - R0007 - Canteen (27.2 m2)

Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00H - R0008 - Canteen Office/Store (3.91 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00H - R0009 - Seminar (36.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00H - R0010 - Toilets - Girls (22.38 m2)

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00H - R0011 - Toilets - Boys (11.02 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1234/B00N/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 1993 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00I - R0001 - Movement (310.05 m2)**Ceiling Structures/Linings Flat AC Sheeting
1234/B00I/R0001/Ceiling Structures/Linings/S9 **No Asbestos Detected****B00I - R0002 - General Learning Space (47.27 m2)**

No Asbestos

B00I - R0003 - Interview (15.66 m2)

No Asbestos

B00I - R0004 - Security Store (19.15 m2)

No Asbestos

B00I - R0005 - Deputy Principal (16.5 m2)

No Asbestos

B00I - R0006 - Staff Room Annexe (46.66 m2)

No Asbestos

B00I - R0007 - General Learning Space (47.72 m2)

No Asbestos

B00I - R0008 - General Learning Space (47.49 m2)

No Asbestos

B00I - R0009 - General Learning Space (47.94 m2)

No Asbestos

B00I - R0010 - Toilets - Boys (19.29 m2)

No Asbestos

B00I - R0011 - Shower/Change (17.85 m2)

No Asbestos

B00I - R0012 - Disabled Toilet (5.33 m2)

No Asbestos

B00I - R0013 - Toilets - Girls (22.06 m2)

No Asbestos

B00I - R0014 - Shower/Change (17.15 m2)

No Asbestos

B00I - R0015 - Distribution Board (0.48 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0016 - Cleaning Distributed Store (3.72 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1920 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Packing					
	1234/B00J/Underfloor Voids - Packing to Floor Joists/S23					No Asbestos Detected

Interior

B00J - R0001 - General Storeroom (6.02 m2)

No Asbestos

B00J - R0002 - Movement (9.57 m2)

No Asbestos

B00J - R0003 - General Learning Space (35.95 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Technological & Applied Studies/Art - 1883 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling

Non Accessible Area
- height 4 meters

Underfloor Voids - Packing to Floor Joists

Non Accessible Area
- No access

Interior**B00K - R0001 - Materials Store (3.43 m2)**

No Asbestos

B00K - R0002 - Materials Store (3.58 m2)

No Asbestos

B00K - R0003 - Movement (2.38 m2)

No Asbestos

B00K - R0004 - Main Switch Board (3.62 m2)

Wall Linings Internal	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
1234/B00K/R0007/Wall Linings Internal/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Electrical Backing Board	Resinous Board					No Asbestos Detected
1234/B00K/R0004/Electrical Backing Board/S8						

B00K - R0005 - Staff Toilet (1.62 m2)

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1234/B00K/R0007/Wall Linings Internal/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00K - R0006 - Art Learning Space (75.51 m2)

No Asbestos

B00K - R0007 - Staff Toilet (1.61 m2)

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Poor Condition (4)	Medium (2)	Low Priority (2-3)
1234/B00K/R0007/Wall Linings Internal/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00K - R0008 - Resources Space (6.59 m2)

Wall Linings Internal	Flat AC Sheeting	4m2	East	Poor Condition (4)	Medium (2)	Low Priority (2-3)
1234/B00K/R0007/Wall Linings Internal/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00K - R0009 - Movement (16.56 m2)

No Asbestos

B00K - R0010 - Movement (32 m2)

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
1234/B00K/R0010/Wall Linings Internal/S24						

B00K - R0011 - Wood Technology Bay (51.36 m2)

No Asbestos

B00K - R0012 - Materials Technology L.S. (79.84 m2)

No Asbestos

B00K - R0013 - Welding Area (19.35 m2)

Floor Coverings Res/Textile	Compressed AC Sheet					No Asbestos Detected
1234/B00K/R0013/Floor Coverings Res/Textile/S6						

B00K - R0014 - Staff Room Annexe (13.36 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Music - 1918 - Timber (Timber)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- height - 4 meters

Underfloor Voids - Packing to Floor Joists
No Asbestos Found

Interior**B00L - R0001 - Movement (22.49 m2)**

No Asbestos

B00L - R0002 - Music Learning Space (54.31 m2)

No Asbestos

B00L - R0003 - Music Store (14.08 m2)

No Asbestos

B00L - R0004 - Cleaning Distributed Store (5.01 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Administration - 1955 - Brick/Block (Brick/Block)**Exterior**

Wall Cladding	Flat AC Sheeting 1234/B00M/Wall Cladding/S12					No Asbestos Detected
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00M - R0001 - Uniform Shop (12.66 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 1234/B00N/R0005/Ceiling Structures/Linings/S2	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting 1234/B00M/R0001/Wall Linings Internal/S25					No Asbestos Detected

B00M - R0002 - General Storeroom (35.45 m2)

Ceiling Structures/Linings	Flat AC Sheeting 1234/B00N/R0005/Ceiling Structures/Linings/S2	36m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting 1234/B00K/R0007/Wall Linings Internal/S7	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Agricultural Science - 1955 - Brick/Block (Brick/Block)**Exterior**

Wall Cladding	Flat AC Sheeting 1234/B00N/Wall Cladding/S1					No Asbestos Detected
Gable Ends	Flat AC Sheeting 1234/B00N/Gable Ends/S3	8m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00N - R0001 - Plant Space (7.46 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 1234/B00N/R0005/Ceiling Structures/Linings/S2	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00N - R0002 - Garden Store (8.82 m2)

Ceiling Structures/Linings	Flat AC Sheeting 1234/B00N/R0005/Ceiling Structures/Linings/S2	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00N - R0003 - Garden Store (33.93 m2)

Ceiling Structures/Linings	Flat AC Sheeting 1234/B00N/R0005/Ceiling Structures/Linings/S2	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	------------	--------------------	---------	--

B00N - R0004 - Staff Shower/Change (7.41 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 1234/B00N/R0004/Partition Walls (Cubicles)/S4	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 1234/B00N/R0005/Ceiling Structures/Linings/S2	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00N - R0005 - Movement (41.7 m2)

Ceiling Structures/Linings	Flat AC Sheeting 1234/B00N/R0005/Ceiling Structures/Linings/S2	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	------------	--------------------	---------	--

B00N - R0006 - Movement (1.7 m2)

Ceiling Structures/Linings	Flat AC Sheeting 1234/B00N/R0005/Ceiling Structures/Linings/S2	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00N - R0007 - Sports Store (32.17 m2)

stored item	Flat AC Sheeting 1234/B00N/R0007/stored item/S26					No Asbestos Detected
stored item	Flat AC Sheeting 1234/B00N/R0007/stored item/S27					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Storage - 2013 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B000 - R0001 - Garage/Carport (45.18 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017