


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Boggabilla Central School (1275)
Region : New England
State Electorate : Northern Tablelands
Local Government Area : Moree Plains

Initial Survey : Noel Arnold & Associates : 15 - May - 2008
Reviewed By : Greencap-NAA : 04 - May - 2016



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00B - General Learning/Pupil Facilities - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|--|-------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids - Packing to Floor Joists | No Asbestos Found |

Interior

| | |
|---|---|
| B00B - R0001 - External Movement | No Asbestos |
| B00B - R0002 - Toilets - Boys | No Asbestos |
| B00B - R0003 - General Assistants | No Asbestos |
| B00B - R0004 - Toilets - Girls | No Asbestos |
| B00B - R0005 - General Learning Space | No Asbestos |
| B00B - R0006 - Home Base Store | No Asbestos |
| B00B - R0007 - Withdrawal - M | No Asbestos |
| B00B - R0008 - Home Base | No Asbestos |
| B00B - R0009 - Practical Activities | No Asbestos |
| B00B - R0010 - Home Base | No Asbestos |
| B00B - R0011 - Home Base Store | No Asbestos |
| B00B - R0012 - Practical Activities | No Asbestos |
| B00B - R0013 - Withdrawal - M | No Asbestos |
| B00B - R0014 - Home Base | No Asbestos |
| B00B - R0015 - Practical Activities | No Asbestos |
| B00B - R0016 - Home Base Store | No Asbestos |
| B00B - R0017 - Art Learning Space | No Asbestos |
| B00B - R0018 - Resources Store | No Asbestos |
| B00B - R0019 - Darkroom Space | No Asbestos |
| B00B - R0020 - Distribution Board Cupboard | No Asbestos Note: No inspection of live electrical installation. |
| B00B - R0021 - Special Programs Room | Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found |
| B00B - R0022 - Special Programs Store | No Asbestos |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---|----------------------|--------|--------------------|--------------------|--|------------------|
| Sample No | | | | | Test Result | |
| B00B - R0023 - General Storeroom | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0024 - Toilets - Girls | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0025 - Cleaning Distributed Store | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0026 - Toilets - Boys | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0027 - General Learning Space | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0028 - Interview | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0029 - General Learning Space | | | | | | |
| Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet) | | | | | | |
| B00B - R0030 - Security Store | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0031 - Security Store | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0033 - Staff Study | | | | | | |
| Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet) | | | | | | |
| B00B - R0034 - Preparation | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0035 - Chemical Store | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0036 - Apparatus Store | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0037 - Laboratory L.S. | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0038 - General Learning Space | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0039 - Food Technology L.S. | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0040 - Materials Store | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0041 - Food/Research Space | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0042 - Distribution Board Cupboard | | | | | Note: No inspection of live electrical installation. | |
| No Asbestos | | | | | | |
| B00B - R0045 - Workroom | | | | | | |
| Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet) | | | | | | |
| B00B - R0047 - Reading Area | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0048 - K.L.A. Store | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0049 - Library Office/Workroom | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0050 - Special Programs Room | | | | | | |
| No Asbestos | | | | | | |
| B00B - R0051 - Movement | | | | | | |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

No Asbestos

B00B - R0052 - Home Base

No Asbestos

B00B - R0053 - No Access

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00C - Multi Purpose Facilities/Pupil Facilities - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------------------------|-------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids - Slab on Ground | No Asbestos Found |

Interior

B00C - R0001 - Garden Store

No Asbestos

B00C - R0002 - Sports Store

No Asbestos

B00C - R0003 - Multi-Purpose Space

No Asbestos

B00C - R0004 - General Storeroom

No Asbestos

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Control Room

No Asbestos

B00C - R0007 - Shower/Change

No Asbestos

B00C - R0008 - Shower/Change

No Asbestos

B00C - R0009 - Chair Store

No Asbestos

B00C - R0010 - External Movement

No Asbestos

B00C - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0012 - Office/Store

No Asbestos

B00C - R0013 - Canteen

No Asbestos

B00C - R0014 - External Movement

No Asbestos

B00C - R0015 - Toilets-Disabled

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00D - Other-Community Use - 1920 - Timber (Timber)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- height - 4 meters

Underfloor Voids - Packing to Floor Joists
No Asbestos Found

Interior**B00D - R0001 - Other-Community Use**

No Asbestos

B00D - R0002 - Other-Community Use

No Asbestos

B00D - R0003 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
1275/B00D/R0003/Ceiling Structures/Linings/S1 **No Asbestos Detected**

B00D - R0004 - Kitchen - Pre

No Asbestos

B00D - R0005 - Other-Community Use

Wall Linings Internal Flat AC Sheeting
1275/B00D/R0005/Wall Linings Internal/S2 **No Asbestos Detected**

B00D - R0007 - General Storeroom

No Asbestos

B00D - R0008 - Toilets-Unisex

No Asbestos

B00D - R0009 - Movement

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - Technological & Applied Studies - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|--|-------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids - Packing to Floor Joists | No Asbestos Found |

Interior

B00E - R0001 - External Movement

No Asbestos

B00E - R0002 - T.A.S. Entry/Display

No Asbestos

B00E - R0003 - Materials Store

No Asbestos

B00E - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0005 - Dust Extraction Space

No Asbestos

B00E - R0006 - Wood Technology Bay

No Asbestos

B00E - R0007 - Materials Technology L.S.

No Asbestos

B00E - R0008 - Workshop Area

No Asbestos

B00E - R0009 - Materials Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B001 - Physical Education - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------------------------|-------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids - Slab on Ground | No Asbestos Found |

Interior

B001 - R0001 - Gymnasium

No Asbestos

B001 - R0002 - Sports Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00K - Pre-School Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------------------------|-------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids - Slab on Ground | No Asbestos Found |

Interior

| | |
|--|-------------|
| B00K - R0001 - External Movement | No Asbestos |
| B00K - R0002 - Entry Vestibule | No Asbestos |
| B00K - R0003 - General Storeroom - Pre | No Asbestos |
| B00K - R0004 - General Storeroom - Pre | No Asbestos |
| B00K - R0005 - Home Base - Pre | No Asbestos |
| B00K - R0006 - Practical Activities - Pre | No Asbestos |
| B00K - R0007 - Toilets - Boys/Girls - Pre | No Asbestos |
| B00K - R0008 - Laundry - Pre | No Asbestos |
| B00K - R0009 - Access Shower/Toilet | No Asbestos |
| B00K - R0010 - Cleaning Distributed Store | No Asbestos |
| B00K - R0011 - Kitchen - Pre | No Asbestos |
| B00K - R0012 - Clerical Office - Pre | No Asbestos |
| B00K - R0013 - Clerical Office - Pre | No Asbestos |
| B00K - R0014 - General Storeroom - Pre | No Asbestos |
| B00K - R0015 - External Movement | No Asbestos |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00L - Library - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|--|-------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids - Packing to Floor Joists | No Asbestos Found |

Interior

B00L - R0001 - External Movement

No Asbestos

B00L - R0002 - Reading Area

No Asbestos

B00L - R0003 - Library Office/Workroom

No Asbestos

B00L - R0004 - K.L.A. Store

No Asbestos

B00L - R0005 - Communications Room

No Asbestos

B00L - R0006 - No Access

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00M - General Learning - 2011 - Steel (Steel)

Exterior

| | |
|--|-------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids - Packing to Floor Joists | No Asbestos Found |

Interior

B00M - R0001 - External Movement

No Asbestos

B00M - R0002 - Practical Activities/Movement - 1hb

No Asbestos

B00M - R0003 - Home Base Store

No Asbestos

B00M - R0004 - Home Base

No Asbestos

B00M - R0005 - Withdrawal Space - 2hb

No Asbestos

B00M - R0006 - Home Base

No Asbestos

B00M - R0007 - Home Base Store

No Asbestos

B00M - R0008 - Practical Activities/Movement - 1hb

No Asbestos

B00M - R0009 - Practical Activities/Movement - 1hb

No Asbestos

B00M - R0010 - Home Base Store

No Asbestos

B00M - R0011 - Home Base

No Asbestos

B00M - R0012 - No Access

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

B0AS - Administration/Staff Facilities - 1992 - Steel (Steel)**Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids -
Packing to Floor Joists No Asbestos Found**Interior****B0AS - R0001 - Deputy Principal**

No Asbestos

B0AS - R0002 - External Movement

No Asbestos

B0AS - R0003 - Clinic

No Asbestos

B0AS - R0004 - Staff - Toilet

No Asbestos

B0AS - R0005 - Cleaning Distributed Store

No Asbestos

B0AS - R0006 - Main Switchroom

No Asbestos

B0AS - R0007 - External Movement

No Asbestos

B0AS - R0008 - Security Store

No Asbestos

B0AS - R0009 - Staff - Toilet

No Asbestos

B0AS - R0010 - Interview

No Asbestos

B0AS - R0011 - Movement

No Asbestos

B0AS - R0012 - Public Entry

No Asbestos

B0AS - R0013 - Staff - Toilet

No Asbestos

B0AS - R0014 - Staff - Toilet

No Asbestos

B0AS - R0015 - Communal Space

No Asbestos

B0AS - R0016 - Staff Room Annexe

No Asbestos

B0AS - R0017 - Movement

No Asbestos

B0AS - R0018 - Tafe Utilised

No Asbestos

B0AS - R0019 - Movement

No Asbestos

B0AS - R0020 - Tafe Utilised

No Asbestos

B0AS - R0021 - Clerical Office

No Asbestos

B0AS - R0022 - Tafe Utilised

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|--|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |
| B0AS - R0023 - Duplicating Workroom | | | | | | |
| No Asbestos | | | | | | |
| B0AS - R0024 - Security Store | | | | | | |
| No Asbestos | | | | | | |
| B0AS - R0025 - Principal | | | | | | |
| No Asbestos | | | | | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D15340 - Learning Unit - Standard/Withdrawal : Placement Date - 30/04/2007

Exterior

| | | | |
|-------------|---------------------|------------------|----------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos | 1.08 m2 |
| Landing | Compressed AC Sheet | Assumed Asbestos | 1.2 m2 |
| Eave Lining | Flat AC Sheet | Assumed Asbestos | 11.52 m2 |

Interior

R1 - Entry

| | | | |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | 8 m2 |

R2 - General Learning Space

| | | | |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | 55 m2 |

R3 - Store

| | | | |
|---------|---------------|------------------|-------|
| Ceiling | Flat AC Sheet | Assumed Asbestos | 10 m2 |
|---------|---------------|------------------|-------|

- D15618 - : Placement Date - 8/07/2011

No Asbestos Found.

NS 020 - D15918 - Staff Study/Store : Placement Date - 3/07/2003

Exterior

No Asbestos Found.

Interior

R1 - Staff Room

No Asbestos Found.

R2 - Store

No Asbestos Found.

R3 - Entry

No Asbestos Found.

OS 601 - D17712 - Learning Unit - Standard/Withdrawal : Placement Date - 18/01/2010

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017