


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Brighton-Le-Sands Public School (1358)  
**Region :** Sydney  
**State Electorate :** Rockdale  
**Local Government Area :** Rockdale

**Initial Survey :** Noel Arnold & Associates : 20 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 28 - Aug - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Communal Facilities - 1916 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 1358/B00A/Eaves Linings/S10					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00A - R0003 - External Movement**

No Asbestos

**B00A - R0010 - External Movement**

No Asbestos

**B00A - R0011 - Movement**

No Asbestos

**B00A - R0012 - Staff Room**

No Asbestos

**B00A - R0013 - Staff Room**

No Asbestos

**B00A - R0022 - Home Base**

No Asbestos

**B00A - R0023 - Home Base**

No Asbestos

**B00A - R0026 - Sports Store**

No Asbestos

**B00A - R0038 - Home Base**

No Asbestos

**B00A - R0039 - Home Base**

No Asbestos

**B00A - R0042 - Special Programs Room**

No Asbestos

**B00A - R0043 - Home Base**

No Asbestos

**B00A - R0044 - Movement**

No Asbestos

**B00A - R0045 - Communal Space**

No Asbestos

**B00A - R0046 - Raised Platform**

No Asbestos

**B00A - R0047 - Hall Chair Store**

No Asbestos

**B00A - R0048 - Practical Activities - 1hb**

No Asbestos

**B00A - R0049 - Communal Space**

No Asbestos

**B00A - R0050 - Practical Activities - 1hb**

No Asbestos

**B00A - R0051 - Personal Effects Storage**

No Asbestos

**B00A - R0052 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0053 - Practical Activities - 1hb**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00A - R0054 - Communications Cupboard**

No Asbestos

**B00A - R0055 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0056 - External Movement**

Wall Linings Internal      Flat AC Sheeting  
1358/B00A/R0056/Wall Linings Internal/S9

**No Asbestos Detected**

**B00A - R0057 - Staff Toilet**

No Asbestos

**B00A - R0058 - Access Shower/Toilet**

No Asbestos

**B00A - R0059 - Practical Activities - 1hb**

No Asbestos

**B00A - R0060 - Movement**

No Asbestos

**B00A - R0061 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0062 - Practical Activities - 1hb**

No Asbestos

**B00A - R0063 - Personal Effects Storage**

No Asbestos

**B00A - R0064 - Practical Activities - 1hb**

No Asbestos

**B00A - R0065 - Home Base**

No Asbestos

**B00A - R0066 - Withdrawal Space - 2hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00B - General Learning/Support Unit - 1916 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00B - R0001 - External Movement**

No Asbestos

**B00B - R0002 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
Chalk Board	Compressed AC Sheet	12m2	North facing, South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0003/Chalk Board/S3				<b>Chrysotile (white asbestos)</b>	

**B00B - R0003 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
Chalk Board	Compressed AC Sheet	12m2	North facing, South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0003/Chalk Board/S3				<b>Chrysotile (white asbestos)</b>	

**B00B - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0021/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	

**B00B - R0005 - Special Programs Room**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0021/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	

**B00B - R0006 - Special Programs Room**

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	

**B00B - R0007 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
Chalk Board	Compressed AC Sheet	12m2	North facing, South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0003/Chalk Board/S3				<b>Chrysotile (white asbestos)</b>	

**B00B - R0008 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
Chalk Board	Compressed AC Sheet	12m2	North facing, South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0003/Chalk Board/S3				<b>Chrysotile (white asbestos)</b>	

**B00B - R0009 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
Chalk Board	Compressed AC Sheet	12m2	North facing, South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0003/Chalk Board/S3				<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0010 - Home Base - M</b>						
Ceiling Structures/Linings	Flat AC Sheeting	62m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
Chalk Board	Compressed AC Sheet	12m2	North facing, South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0003/Chalk Board/S3				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0011 - Toilet - M</b>						
Wall Linings Internal	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0011/Wall Linings Internal/S4				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0012 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0011/Wall Linings Internal/S4				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0013 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	33m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0014 - External Movement</b>						
No Asbestos						
<b>B00B - R0015 - General Storeroom</b>						
No Asbestos						
<b>B00B - R0016 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1358/B00B/R0016/Floor Coverings Res/Textile/S5				<b>No Asbestos Detected</b>	
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0017 - Raised Platform</b>						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0018 - Practical Activities - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0019 - Communal Space</b>						
Ceiling Structures/Linings	Flat AC Sheeting	160m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0019/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0020 - External Movement</b>						
No Asbestos						
<b>B00B - R0021 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00B/R0021/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities - 1916 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00C - R0001 - Drinking Facilities**

No Asbestos

**B00C - R0002 - Toilets - Boys**

No Asbestos

**B00C - R0003 - Toilets - Girls**

No Asbestos

**B00C - R0004 - Cleaning Distributed Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1916 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	60m2	Upper portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00D/Eaves Linings/S11					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No access to underfloor void					

**Interior****B00D - R0007 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00D/R0007/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>

**B00D - R0008 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Upper portion	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	1358/B00D/R0007/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>

**B00D - R0009 - Home Base**

No Asbestos

**B00D - R0010 - Practical Activities - 1hb**

No Asbestos

**B00D - R0011 - Home Base Store**

No Asbestos

**B00D - R0012 - Withdrawal Space - 2hb**

No Asbestos

**B00D - R0013 - Movement**

No Asbestos

**B00D - R0014 - Home Base**

No Asbestos

**B00D - R0015 - Home Base Store**

No Asbestos

**B00D - R0016 - Practical Activities - 1hb**

No Asbestos

**B00D - R0017 - Movement**

No Asbestos

**B00D - R0018 - Home Base Store**

No Asbestos

**B00D - R0019 - Special Programs Room**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
<b>B00F - Pupil Facilities/Other - 1916 - Brick/Block (Brick/Block)</b>						
<b>Exterior</b>						
Eaves Linings	Flat AC Sheeting	150m2	Upper portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/Eaves Linings/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Low Priority (2-3)
	1358/B00F/Ceiling Voids/S13			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found					
<b>Interior</b>						
<b>B00F - R0001 - Toilets - Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting	47m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0002 - Cleaning Distributed Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0003 - Cleaning Supplies</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0004 - Special Programs Room</b>						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0005 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0006 - Canteen Office/Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0009 - Canteen Office/Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0010 - General Assistant/Bulk Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0011 - General Assistant/Bulk Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1358/B00F/R0012/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0012 - Toilets - Boys</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	47m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1358/B00F/R0012/Ceiling Structures/Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00F - R0013 - Cleaning Distributed Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1358/B00F/R0012/Ceiling Structures/Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00F - R0014 - Practical Activities - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1358/B00F/R0012/Ceiling Structures/Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00F - R0015 - Canteen</b>						
No Asbestos						
<b>B00F - R0016 - Staff Toilet</b>						
No Asbestos						
<b>B00F - R0017 - Toilet - Lobby</b>						
No Asbestos						
<b>B00F - R0018 - External Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Other-Non-Govt Pre-School - 1916 - Steel (Steel)**

**Exterior**

Eaves Linings	Flat AC Sheeting 1358/B00G/Eaves Linings/S12					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 1358/B00G/Wall Cladding/S16					No Asbestos Detected

**Interior**

**B00G - R0001 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0002 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0003 - Other-Non Government Pre-Sch**

Floor Coverings Res/Textile	Compressed AC Sheet 1358/B00G/R0012/Floor Coverings Res/Textile/S15					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1358/B00G/R0012/Ceiling Structures/Linings/S14					No Asbestos Detected

**B00G - R0004 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0005 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0006 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0007 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0008 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0009 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0010 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0011 - Other-Non Government Pre-Sch**

No Asbestos

**B00G - R0012 - Other-Non Government Pre-Sch**

Ceiling Structures/Linings	Flat AC Sheeting 1358/B00G/R0012/Ceiling Structures/Linings/S14					No Asbestos Detected
Floor Coverings Res/Textile	Compressed AC Sheet 1358/B00G/R0012/Floor Coverings Res/Textile/S15					No Asbestos Detected



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Other-Non-Govt Pre-School - 1916 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00H - R0001 - Other-Non Government Pre-Sch**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00I - Administration - 1999 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00I - R0001 - Staff Room**

No Asbestos

**B00I - R0002 - Staff Room**

No Asbestos

**B00I - R0003 - Cleaning Supplies**

No Asbestos

**B00I - R0004 - Deputy Principal**

No Asbestos

**B00I - R0005 - General Storeroom**

No Asbestos

**B00I - R0006 - Principal**

No Asbestos

**B00I - R0007 - Duplicating Workroom**

No Asbestos

**B00I - R0008 - Entry Vestibule**

No Asbestos

**B00I - R0009 - Clerical Office**

No Asbestos

**B00I - R0010 - Sick Bay**

No Asbestos

**B00I - R0011 - Sick Bay - Shower/Toilet**

No Asbestos

**B00I - R0012 - Interview**

No Asbestos

**B00I - R0013 - Deputy Principal**

No Asbestos

**B00I - R0014 - Sick Bay - Shower/Toilet**

No Asbestos

**B00I - R0015 - Sick Bay - Shower/Toilet**

No Asbestos

**B00I - R0016 - Sick Bay - Shower/Toilet**

No Asbestos

**B00I - R0017 - Movement**

No Asbestos

**B00I - R0018 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00I - R0019 - External Movement**

No Asbestos

**B00I - R0020 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning - 2005 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00J - R0001 - External Movement**

No Asbestos

**B00J - R0002 - Practical Activities - 1hb**

No Asbestos

**B00J - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00J - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00J - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00J - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00J - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00J - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 2007 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00K - R0001 - External Movement**

No Asbestos

**B00K - R0002 - Practical Activities - 1hb**

No Asbestos

**B00K - R0003 - Home Base Store**

No Asbestos

**B00K - R0004 - Home Base**

No Asbestos

**B00K - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00K - R0006 - Home Base**

No Asbestos

**B00K - R0007 - Home Base Store**

No Asbestos

**B00K - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - General Learning - 2007 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00L - R0001 - External Movement**

No Asbestos

**B00L - R0002 - Practical Activities - 1hb**

No Asbestos

**B00L - R0003 - Home Base Store**

No Asbestos

**B00L - R0004 - Home Base**

No Asbestos

**B00L - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00L - R0006 - Home Base**

No Asbestos

**B00L - R0007 - Home Base Store**

No Asbestos

**B00L - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Library - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00M - R0001 - Reading Area**

No Asbestos

**B00M - R0002 - Library Office/Workroom**

No Asbestos

**B00M - R0003 - Communications Room**

No Asbestos

**B00M - R0004 - K.L.A. Store**

No Asbestos

**B00M - R0005 - Cleaning Distributed Store**

No Asbestos

**B00M - R0006 - Toilet - Lobby**

No Asbestos

**B00M - R0007 - Staff Toilet**

No Asbestos

**B00M - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00M - R0009 - External Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00N - R0001 - External Movement**

No Asbestos

**B00N - R0002 - Practical Activities - 1hb**

No Asbestos

**B00N - R0003 - Home Base Store**

No Asbestos

**B00N - R0004 - Home Base**

No Asbestos

**B00N - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00N - R0006 - Home Base**

No Asbestos

**B00N - R0007 - Home Base Store**

No Asbestos

**B00N - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - Storage - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00P - R0001 - General Storeroom**

No Asbestos

**B00P - R0002 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+1 - Added Building**

**Exterior**

No Asbestos

**Interior**

**Build+1 - Room+1 - Added Room**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

### OS 603 - D10069 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 28/01/2000

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

### OS 601 - D10466 - Learning Unit - Standard/Withdrawal : Placement Date - 30/12/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Entry

No Asbestos Found.

##### R2 - General Learning Space

No Asbestos Found.

##### R3 - Store

No Asbestos Found.

### OS 602 - D11391 - Learning Unit - Standard With P.A.A. : Placement Date - 28/11/2013

#### Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

#### Interior

##### R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

##### R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

### OS 601 - D11410 - Learning Unit - Standard/Withdrawal : Placement Date - 13/05/2008

#### Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 601 - D11669 - Learning Unit - Standard/Withdrawal : Placement Date - 5/04/2004</b>						
<b>Exterior</b>						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 601 - D11877 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995</b>						
<b>Exterior</b>						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 602 - D12807 - Learning Unit - Standard With P.A.A. : Placement Date - 21/11/2011</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 601 - D12911 - Learning Unit - Standard/Withdrawal : Placement Date - 18/03/2003</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Exterior</b>						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 602 - D14195 - Learning Unit - Standard With P.A.A. : Placement Date - 24/01/2013</b>						
<b>Exterior</b>						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
<b>R2 - Home Base Store</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
<b>OS 601 - D14671 - Learning Unit - Standard/Withdrawal : Placement Date - 25/06/1998</b>						
<b>Exterior</b>						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 601 - D14905 - Learning Unit - Standard/Withdrawal : Placement Date - 4/04/2006</b>						
<b>Exterior</b>						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017