

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bennett Road Public School (4285)
Region : Western Sydney
State Electorate : Londonderry
Local Government Area : Penrith

Initial Survey : Noel Arnold & Associates : 29 - May - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1964 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting	200m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Eaves Linings/S17					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Gable Verge Lining/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Personal Effects Storage

No Asbestos

B00C - R0003 - General Storeroom

No Asbestos

B00C - R0004 - Toilets - Boys/Girls

No Asbestos

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - General Storeroom

No Asbestos

B00C - R0008 - Personal Effects Storage

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - Personal Effects Storage

No Asbestos

B00C - R0012 - Home Base Store

No Asbestos

B00C - R0013 - Home Base

No Asbestos

B00C - R0014 - Home Base

No Asbestos

B00C - R0015 - Home Base Store

No Asbestos

B00C - R0016 - Personal Effects Storage

No Asbestos

B00C - R0017 - Movement

Wall Linings Internal	Flat AC Sheeting	10m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00C/R0017/Wall Linings Internal/S6					Chrysotile (White asbestos)

B00C - R0018 - Movement

No Asbestos

B00C - R0019 - Staff Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0020 - Staff Toilet						
No Asbestos						
B00C - R0021 - Interview						
No Asbestos						
B00C - R0022 - General Storeroom						
No Asbestos						
B00C - R0023 - Distribution Board				Note: No inspection of live electrical installation.		
Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00C/R0023/Electrical Backing Board/S37				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	2m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00C/R0023/In-fill-panel/S5				Chrysotile (White asbestos) , Amosite (Brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities/Pupil Facilities - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 4285/B00D/Wall Cladding/S25					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B00D - R0001 - Movement

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0001/Wall Linings Internal/S7					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00D - R0002 - Canteen

No Asbestos

B00D - R0003 - Communal Space

No Asbestos

B00D - R0004 - Hall Chair Store

No Asbestos

B00D - R0005 - Raised Platform

No Asbestos

B00D - R0006 - Toilets - Girls

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0018/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

Partition Walls (Cubicles)	Compressed AC Sheet 4285/B00D/R0013/Partition Walls (Cubicles)/S9					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00D - R0007 - Shower/Change

Wall Linings Internal	Fibre cement sheeting 4285/B00D/R0007/Wall Linings Internal/S32					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00D - R0008 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0018/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

Partition Walls (Cubicles)	Compressed AC Sheet 4285/B00D/R0008/Partition Walls (Cubicles)/S38					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00D - R0009 - Movement

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0018/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00D - R0010 - Movement

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0001/Wall Linings Internal/S7					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00D - R0011 - Movement

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0018/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00D - R0012 - Shower/Change

Non Accessible

B00D - R0013 - Toilets - Boys

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0018/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

Partition Walls (Cubicles)	Compressed AC Sheet 4285/B00D/R0013/Partition Walls (Cubicles)/S9					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00D - R0014 - Hall Chair Store

No Asbestos

B00D - R0015 - Movement

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0001/Wall Linings Internal/S7					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0016 - General Storeroom						
Ceiling Structures/Linings	Fibre cement sheeting					
		4285/B00D/R0016/Ceiling Structures/Linings/S29				No Asbestos Detected
B00D - R0017 - Sports Store						
Ceiling Structures/Linings	Fibre cement sheeting					
		4285/B00D/R0016/Ceiling Structures/Linings/S29				No Asbestos Detected
B00D - R0018 - Disabled Toilet						
Wall Linings Internal	Flat AC Sheeting					
		4285/B00D/R0018/Wall Linings Internal/S8				No Asbestos Detected
B00D - R0019 - Distribution Board						
				Note: No inspection of live electrical installation.		
Wall Linings Internal	Flat AC Sheeting					
		4285/B00D/R0018/Wall Linings Internal/S8				No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
		4285/B00D/R0018/Wall Linings Internal/S8				No Asbestos Detected
B00D - R0020 - Canteen Office/Store						
No Asbestos						
B00D - R0021 - Canteen Office/Store						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1986 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting	200m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Eaves Linings/S17					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Gable Verge Lining/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4285/B00E/Underfloor Voids/S23					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Void	No Asbestos Found					

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Movement

No Asbestos

B00E - R0003 - Toilets - Boys/Girls

No Asbestos

B00E - R0004 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	4285/B00E/R0004/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00E - R0005 - Home Base

No Asbestos

B00E - R0006 - Home Base

No Asbestos

B00E - R0007 - Home Base Store

No Asbestos

B00E - R0008 - Personal Effects Storage

Electrical Cupboard Lining	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00E/R0008/Electrical Cupboard/S10					Chrysotile (White asbestos) , Amosite (Brown asbestos)

B00E - R0009 - Movement

No Asbestos

B00E - R0010 - Movement

No Asbestos

B00E - R0011 - Craft Store

No Asbestos

B00E - R0012 - Withdrawal Space - 1hb

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)					
	4285/B00E/R0012/Floor Coverings Res/Textile/S34					No Asbestos Detected

B00E - R0013 - Staff Room Annexe

Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00B/R0003/Floor Coverings Res/Textile/S2					Chrysotile (White asbestos)

B00E - R0014 - Home Base

No Asbestos

B00E - R0015 - Home Base Store

No Asbestos

B00E - R0016 - Personal Effects Storage

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00E - R0017 - Movement

No Asbestos

B00E - R0018 - Movement

No Asbestos

B00E - R0019 - Personal Effects Storage

No Asbestos

B00E - R0020 - Home Base Store

No Asbestos

B00E - R0021 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1961 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Eaves Linings/S17					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Gable Verge Lining/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0001 - Home Base

No Asbestos

B00F - R0002 - Home Base Store

No Asbestos

B00F - R0003 - Movement

No Asbestos

B00F - R0004 - Movement

Ceiling Structures/Linings	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/R0004/Ceiling Structures/Linings/S30					Chrysotile (white asbestos) , Crocidolite (blue asbestos)

B00F - R0005 - Home Base Store

No Asbestos

B00F - R0006 - Home Base

No Asbestos

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1964 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - Movement

No Asbestos

B00G - R0002 - Home Base

No Asbestos

B00G - R0003 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1961 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting 4285/B00H/Wall Cladding/S13				No Asbestos Detected	
Gable Verge Lining	Flat AC Sheeting 4285/B00H/Gable Verge Lining/S39	30m	East and west facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Underfloor Voids	Flat AC Sheeting 4285/B00H/Underfloor Voids/S22	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
Ceiling Void	No Asbestos Found				Chrysotile (white asbestos)	

Interior

B00H - R0001 - General Storeroom

No Asbestos

B00H - R0002 - General Storeroom

No Asbestos

B00H - R0003 - Home Base

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Library/Tiered Learning - 1984 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 4285/B00J/Wall Cladding/S26					No Asbestos Detected

Interior

B00J - R0001 - Movement

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0001/Wall Linings Internal/S7					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00J - R0002 - Movement

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0001/Wall Linings Internal/S7					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00J - R0003 - Reading Area

No Asbestos

B00J - R0004 - Communications Room

No Asbestos

B00J - R0005 - Library Office/Workroom

No Asbestos

B00J - R0006 - Special Programs Room

No Asbestos

B00J - R0007 - General Storeroom

No Asbestos

B00J - R0008 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0018/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00J - R0009 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0018/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

Floor Coverings Res/Textile	Vinyl Tiles 4285/B00J/R0009/Floor Coverings Res/Textile/S35					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00J - R0010 - Movement

Wall Linings Internal	Flat AC Sheeting 4285/B00D/R0001/Wall Linings Internal/S7					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	200m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Eaves Linings/S17					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Gable Verge Lining/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00K - R0001 - Home Base

No Asbestos

B00K - R0002 - Home Base Store

No Asbestos

B00K - R0003 - Cleaning Distributed Store

No Asbestos

B00K - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00M/R0021/Ceiling Structures/Linings/S14					Chrysotile (White asbestos) , Amosite (Brown asbestos)

B00K - R0006 - Cleaning Distributed Store

No Asbestos

B00K - R0007 - Home Base Store

No Asbestos

B00K - R0009 - Home Base

No Asbestos

B00K - R0010 - Home Base

No Asbestos

B00K - R0011 - Home Base Store

No Asbestos

B00K - R0014 - Cleaning Distributed Store

No Asbestos

B00K - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00M/R0021/Ceiling Structures/Linings/S14					Chrysotile (White asbestos) , Amosite (Brown asbestos)

B00K - R0016 - Cleaning Distributed Store

No Asbestos

B00K - R0017 - Home Base Store

No Asbestos

B00K - R0018 - Home Base

No Asbestos

B00K - R0019 - Home Base

No Asbestos

B00K - R0020 - Home Base Store

No Asbestos

B00K - R0023 - General Storeroom

No Asbestos

B00K - R0024 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4285/B00M/R0021/Ceiling Structures/Linings/S14				Chrysotile (White asbestos) , Amosite (Brown asbestos)		

B00K - R0025 - General Storeroom

No Asbestos

B00K - R0026 - Home Base Store

No Asbestos

B00K - R0027 - Home Base

No Asbestos

B00K - R0028 - Personal Effects Storage

No Asbestos

B00K - R0029 - Personal Effects Storage

No Asbestos

B00K - R0030 - Personal Effects Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning/Pupil Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	200m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Eaves Linings/S17					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Gable Verge Lining/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
In-fill-panel	Compressed AC Sheet	8m2	East, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/In-fill-panel/S15					Chrysotile (White asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00L - R0001 - Garden Store

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16					Chrysotile (White asbestos)

B00L - R0002 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16					Chrysotile (White asbestos)

B00L - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	4285/B00D/R0013/Partition Walls (Cubicles)/S9					
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16					Chrysotile (White asbestos)

B00L - R0004 - Home Base

No Asbestos

B00L - R0005 - Home Base Store

No Asbestos

B00L - R0006 - Movement

No Asbestos

B00L - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16					Chrysotile (White asbestos)
In-fill-panel	Flat AC Sheeting	1m	Above door	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16					Chrysotile (White asbestos)

B00L - R0008 - Home Base Store

No Asbestos

B00L - R0009 - Home Base

No Asbestos

B00L - R0010 - Home Base

No Asbestos

B00L - R0011 - Home Base Store

No Asbestos

B00L - R0012 - Movement

No Asbestos

B00L - R0013 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16				Chrysotile (White asbestos)	
In-fill-panel	Flat AC Sheeting	1m	Above door	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16				Chrysotile (White asbestos)	
B00L - R0014 - Movement						
No Asbestos						
B00L - R0015 - Interview						
No Asbestos						
B00L - R0016 - General Storeroom						
No Asbestos						
B00L - R0017 - General Storeroom						
No Asbestos						
B00L - R0018 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting					
	4285/B00D/R0018/Wall Linings Internal/S8				No Asbestos Detected	
B00L - R0019 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting					
	4285/B00D/R0018/Wall Linings Internal/S8				No Asbestos Detected	
B00L - R0020 - Staff Room						
No Asbestos						
B00L - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16				Chrysotile (White asbestos)	
In-fill-panel	Flat AC Sheeting	2m	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00L/R0021/Ceiling Structures/Linings/S16				Chrysotile (White asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	200m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Eaves Linings/S17					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00F/Gable Verge Lining/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00M - R0001 - Home Base

No Asbestos

B00M - R0002 - Home Base Store

No Asbestos

B00M - R0003 - Movement

No Asbestos

B00M - R0004 - No Access

No Asbestos

B00M - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00M/R0021/Ceiling Structures/Linings/S14					Chrysotile (White asbestos) , Amosite (Brown asbestos)

B00M - R0006 - Cleaning Distributed Store

No Asbestos

B00M - R0007 - Home Base Store

No Asbestos

B00M - R0008 - Home Base

No Asbestos

B00M - R0009 - Home Base

No Asbestos

B00M - R0010 - Home Base Store

No Asbestos

B00M - R0011 - Movement

No Asbestos

B00M - R0012 - General Storeroom

No Asbestos

B00M - R0013 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B00M/R0021/Ceiling Structures/Linings/S14					Chrysotile (White asbestos) , Amosite (Brown asbestos)

B00M - R0014 - General Storeroom

No Asbestos

B00M - R0015 - Home Base Store

No Asbestos

B00M - R0016 - Home Base

No Asbestos

B00M - R0017 - Home Base

No Asbestos

B00M - R0018 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00M - R0019 - Movement

No Asbestos

B00M - R0020 - General Storeroom

No Asbestos

B00M - R0021 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

4285/B00M/R0021/Ceiling Structures/Linings/S14

Chrysotile (White asbestos) , Amosite (Brown asbestos)

B00M - R0022 - General Storeroom

No Asbestos

B00M - R0023 - Home Base Store

No Asbestos

B00M - R0024 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Administration - 1964 - Steel (Steel)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - No manhole in building					
Wall Cladding	Compressed AC Sheet 4285/B00N/Wall Cladding/S27	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 4285/B00N/Eaves Linings/S18	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ramp and Landing	Compressed AC Sheet 4285/B00N/Ramp and Landing/S28					No Asbestos Detected
Underfloor Voids	AC Fragments/Debris 4285/B00N/Underfloor Voids/S24	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)

Interior

B00N - R0001 - Community Clinic

Floor Coverings Res/Textile	Vinyl Tiles 4285/B00N/R0004/Floor Coverings Res/Textile/S36					No Asbestos Detected
Wall Linings Internal	Compressed AC Sheet 4285/B00N/R0004/Wall Linings Internal/S33	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Compressed AC Sheet 4285/B00N/R0004/Ceiling Structures/Linings/S31	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00N - R0002 - Community Clinic

Ceiling Structures/Linings	Compressed AC Sheet 4285/B00N/R0004/Ceiling Structures/Linings/S31	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles 4285/B00N/R0004/Floor Coverings Res/Textile/S36					No Asbestos Detected
Wall Linings Internal	Compressed AC Sheet 4285/B00N/R0004/Wall Linings Internal/S33	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00N - R0003 - Community Clinic

Floor Coverings Res/Textile	Vinyl Tiles 4285/B00N/R0004/Floor Coverings Res/Textile/S36					No Asbestos Detected
Ceiling Structures/Linings	Compressed AC Sheet 4285/B00N/R0004/Ceiling Structures/Linings/S31	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Linings Internal	Compressed AC Sheet 4285/B00N/R0004/Wall Linings Internal/S33	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00N - R0004 - Community Clinic

Ceiling Structures/Linings	Compressed AC Sheet 4285/B00N/R0004/Ceiling Structures/Linings/S31	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles 4285/B00N/R0004/Floor Coverings Res/Textile/S36					No Asbestos Detected
Wall Linings Internal	Compressed AC Sheet 4285/B00N/R0004/Wall Linings Internal/S33	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Pupil Facilities - 1961 - Concrete (Concrete)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 4285/B000/Eaves Linings/S19					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4285/B000/Gable Verge Lining/S20					No Asbestos Detected

Interior

B000 - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B000/R0003/Ceiling Structures/Linings/S12				Chrysotile (White asbestos) , Amosite (Brown asbestos)	

B000 - R0002 - Drinking Facilities

No Asbestos

B000 - R0003 - Drinking Facilities

No Asbestos

B000 - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4285/B000/R0003/Ceiling Structures/Linings/S12				Chrysotile (White asbestos) , Amosite (Brown asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet 4285/B00D/R0013/Partition Walls (Cubicles)/S9					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Pupil Facilities - 2009 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00P - R0001 - Toilets - Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00Q - R0001 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Administration - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00R - R0001 - Movement

No Asbestos

B00R - R0002 - Clerical Office

No Asbestos

B00R - R0003 - Interview

No Asbestos

B00R - R0004 - Principal

No Asbestos

B00R - R0005 - Clerical Office

No Asbestos

B00R - R0006 - Clerical Office

No Asbestos

B00R - R0007 - Staff Room

No Asbestos

B00R - R0008 - Staff Room Annexe

No Asbestos

B00R - R0009 - Security Store

No Asbestos

B00R - R0010 - Clerical Office

No Asbestos

B00R - R0011 - Staff Toilet

No Asbestos

B00R - R0012 - Staff Toilet

No Asbestos

B00R - R0013 - Staff Toilet

No Asbestos

B00R - R0014 - Cleaning Distributed Store

No Asbestos

B00R - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00R - R0016 - Disabled Shower/Toilet

No Asbestos

B00R - R0017 - Sick Bay

No Asbestos

B00R - R0018 - Clerical/Printing

No Asbestos

B00R - R0019 - Clerical Office

No Asbestos

B00R - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017