


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bonnyrigg Public School (4545)
Region : South Western Sydney
State Electorate : Cabramatta
Local Government Area : Fairfield

Initial Survey : Noel Arnold & Associates : 05 - May - 2008
Reviewed By : Parsons Brinckerhoff : 03 - Jan - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1981 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	50m2	North, South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4545/B00D/Eaves Linings/S3					Chrysotile (white asbestos)

Interior**B00A - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00A - R0002 - Staff Room

No Asbestos

B00A - R0003 - Deputy Principal

No Asbestos

B00A - R0004 - Staff Room Annexe

No Asbestos

B00A - R0006 - Entry Vestibule

No Asbestos

B00A - R0007 - Duplicating Workroom

No Asbestos

B00A - R0008 - Clerical Office

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Sick Bay

No Asbestos

B00A - R0012 - Principal

No Asbestos

B00A - R0013 - Clerical Office

No Asbestos

B00A - R0014 - Staff Toilet

No Asbestos

B00A - R0015 - Staff Toilet

No Asbestos

B00A - R0016 - Movement

No Asbestos

B00A - R0017 - General Assistant/Bulk Store

No Asbestos

B00A - R0018 - Community Clinic

No Asbestos

B00A - R0019 - Staff Toilet

No Asbestos

B00A - R0020 - Main Switch Board

No Asbestos

B00A - R0021 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0022 - Staff Toilet						
No Asbestos						
B00A - R0023 - Uniform Shop						
No Asbestos						
B00A - R0024 - Canteen						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R0025 - Canteen Office/Store						
No Asbestos						
B00A - R0026 - Cleaning Distributed Store						
No Asbestos						
B00A - R0027 - Raised Platform						
No Asbestos						
B00A - R0028 - Hall Chair Store						
No Asbestos						
B00A - R0029 - Hall Chair Store						
No Asbestos						
B00A - R0030 - Distribution Board						
Note: No inspection of live electrical installation.						
Flooring	Compressed AC Sheet	2m2	North	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
4545/B00L/R0018/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
B00A - R0031 - Communal Space						
No Asbestos						
B00A - R0033 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	95m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R0037 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1981 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	North, South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4545/B00D/Eaves Linings/S3					Chrysotile (white asbestos)

Interior

B00B - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Home Base Store

No Asbestos

B00B - R0004 - Toilets - Girls

No Asbestos

B00B - R0005 - Drinking Facilities

No Asbestos

B00B - R0006 - Toilets - Boys

No Asbestos

B00B - R0007 - Practical Activities - 1hb

No Asbestos

B00B - R0008 - Movement

No Asbestos

B00B - R0009 - Special Programs Room

No Asbestos

B00B - R0010 - Practical Activities - 1hb

No Asbestos

B00B - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0012 - General Storeroom

No Asbestos

B00B - R0013 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00B - R0014 - Home Base

No Asbestos

B00B - R0015 - Home Base Store

No Asbestos

B00B - R0016 - Withdrawal Space - 1hb

No Asbestos

B00B - R0017 - Home Base

No Asbestos

B00B - R0018 - Home Base Store

No Asbestos

B00B - R0019 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00B - R0022 - Home Base						
No Asbestos						
B00B - R0023 - Withdrawal Space - 1hb						
No Asbestos						
B00B - R0024 - Home Base Store						
No Asbestos						
B00B - R0025 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00B - R0026 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00B - R0027 - Withdrawal Space - 1hb						
No Asbestos						
B00B - R0028 - Home Base						
No Asbestos						
B00B - R0029 - Home Base Store						
No Asbestos						
B00B - R0030 - Practical Activities - 1hb						
No Asbestos						
B00B - R0032 - Kiln Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1981 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	North, South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4545/B00D/Eaves Linings/S3					Chrysotile (white asbestos)

Interior

B00C - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Home Base Store

No Asbestos

B00C - R0004 - Toilets - Girls

No Asbestos

B00C - R0005 - Drinking Facilities

No Asbestos

B00C - R0006 - Toilets - Boys

No Asbestos

B00C - R0007 - Practical Activities - 1hb

No Asbestos

B00C - R0008 - Movement

No Asbestos

B00C - R0009 - Withdrawal Space - 1hb

No Asbestos

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0012 - General Storeroom

No Asbestos

B00C - R0013 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00C - R0014 - Home Base

No Asbestos

B00C - R0015 - Home Base Store

No Asbestos

B00C - R0016 - Withdrawal Space - 1hb

No Asbestos

B00C - R0017 - Home Base

No Asbestos

B00C - R0018 - Home Base Store

No Asbestos

B00C - R0019 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00C - R0022 - Home Base						
No Asbestos						
B00C - R0023 - Withdrawal Space - 1hb						
No Asbestos						
B00C - R0024 - Home Base Store						
No Asbestos						
B00C - R0025 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00C - R0026 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1981 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	North, South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4545/B00D/Eaves Linings/S3					Chrysotile (white asbestos)

Interior**B00D - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00D - R0002 - Withdrawal Space - 1hb

No Asbestos

B00D - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00D - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00D - R0005 - Withdrawal Space - 1hb

No Asbestos

B00D - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00D - R0007 - Home Base

No Asbestos

B00D - R0008 - Home Base Store

No Asbestos

B00D - R0010 - Home Base

No Asbestos

B00D - R0011 - Home Base Store

No Asbestos

B00D - R0012 - Home Base

No Asbestos

B00D - R0013 - Home Base Store

No Asbestos

B00D - R0015 - Home Base

No Asbestos

B00D - R0016 - Home Base Store

No Asbestos

B00D - R0017 - Toilets - Girls

No Asbestos

B00D - R0018 - Drinking Facilities

No Asbestos

B00D - R0019 - Toilets - Boys

No Asbestos

B00D - R0020 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00D - R0022 - Movement

Ceiling Structures/Linings Flat AC Sheeting 4m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

4545/B00B/R0001/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

B00D - R0023 - Special Programs Room

No Asbestos

B00D - R0024 - Movement

Ceiling Structures/Linings Flat AC Sheeting 4m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

4545/B00B/R0001/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

B00D - R0026 - Practical Activities - 1hb

No Asbestos

B00D - R0027 - Kiln Room

No Asbestos

B00D - R0028 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0029 - General Storeroom

No Asbestos

B00D - R0030 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 1981 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	5m2	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4545/B00D/Eaves Linings/S3					Chrysotile (white asbestos)

Interior

B00E - R0009 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0010 - General Assistant/Bulk Store

No Asbestos

B00E - R0011 - Movement

No Asbestos

B00E - R0014 - Security Store

No Asbestos

B00E - R0015 - Staff Toilet

No Asbestos

B00E - R0031 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 1981 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	50m2	North, South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4545/B00D/Eaves Linings/S3					Chrysotile (white asbestos)

Interior

B00F - R0001 - Sports Store

No Asbestos

B00F - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00F - R0003 - Home Base

No Asbestos

B00F - R0004 - Home Base Store

No Asbestos

B00F - R0005 - Toilets - Girls

No Asbestos

B00F - R0006 - Drinking Facilities

No Asbestos

B00F - R0007 - Toilets - Boys

No Asbestos

B00F - R0008 - Practical Activities - 1hb

No Asbestos

B00F - R0009 - Movement

No Asbestos

B00F - R0010 - Withdrawal Space - 1hb

No Asbestos

B00F - R0011 - Practical Activities - 1hb

No Asbestos

B00F - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0013 - General Storeroom

No Asbestos

B00F - R0014 - Drinking Facilities

No Asbestos

B00F - R0015 - Movement

No Asbestos

B00F - R0016 - Withdrawal Space - 1hb

No Asbestos

B00F - R0017 - Cleaning Distributed Store

No Asbestos

B00F - R0018 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00F - R0019 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0020 - Home Base Store						
No Asbestos						
B00F - R0021 - Withdrawal Space - 1hb						
No Asbestos						
B00F - R0022 - Home Base						
No Asbestos						
B00F - R0023 - Home Base Store						
No Asbestos						
B00F - R0024 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00F - R0027 - Home Base						
No Asbestos						
B00F - R0028 - Withdrawal Space - 1hb						
No Asbestos						
B00F - R0029 - Home Base Store						
No Asbestos						
B00F - R0030 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00F - R0031 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library - 1981 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00L - R0001 - Movement

No Asbestos

B00L - R0002 - Toilets - Boys

No Asbestos

B00L - R0003 - Toilets - Girls

No Asbestos

B00L - R0004 - Security Store

No Asbestos

B00L - R0005 - Cleaning Supplies

No Asbestos

B00L - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

B00L - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4545/B00B/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

B00L - R0008 - Garden Store

No Asbestos

B00L - R0009 - General Assistant/Bulk Store

No Asbestos

B00L - R0010 - P.E. Store

No Asbestos

B00L - R0011 - K.L.A. Store

No Asbestos

B00L - R0012 - K.L.A. Store

No Asbestos

B00L - R0013 - Reading Area

No Asbestos

B00L - R0014 - Reading Area

No Asbestos

B00L - R0015 - Library Office/Workroom

No Asbestos

B00L - R0016 - Communications Room

No Asbestos

B00L - R0017 - Library Office/Workroom

No Asbestos

B00L - R0018 - Distribution Board

Note: No inspection of live electrical installation.

Flooring	Compressed AC Sheet	1m2	Lower portion	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
4545/B00L/R0018/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	

B00L - R0019 - Special Programs Room

No Asbestos

B00L - R0020 - Cleaning Distributed Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00L - R0021 - Plant

No Asbestos

B00L - R0022 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

4545/B00B/R0001/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

B00L - R0023 - Movement

No Asbestos

B00L - R0024 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Pre-School Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00P - R0001 - Movement

No Asbestos

B00P - R0002 - Entry Vestibule

No Asbestos

B00P - R0003 - Security Store

No Asbestos

B00P - R0004 - General Storeroom - Pre

No Asbestos

B00P - R0005 - Home Base - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00P - R0006 - Practical Activities - Pre

No Asbestos

B00P - R0007 - Toilets - Boys/Girls - Pre

No Asbestos

B00P - R0008 - Laundry - Pre

No Asbestos

B00P - R0009 - Access Shower/Toilet - Type 2

No Asbestos

B00P - R0010 - Cleaning Distributed Store

No Asbestos

B00P - R0011 - Kitchen - Pre

No Asbestos

B00P - R0012 - Clerical Office - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00P - R0013 - Clerical Office - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00P - R0014 - General Storeroom - Pre

No Asbestos

B00P - R0015 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017