


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Blue Haven Public School (4623)  
**Region :** Hunter/Central Coast  
**State Electorate :** Wyong  
**Local Government Area :** Wyong

**Initial Survey :** Noel Arnold & Associates : 14 - Mar - 2008  
**Register Issue Date :** 23 - Mar - 2017



# 2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00A - Administration - 1998 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

**B00A - R0002 - Entry Vestibule**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0003 - Clerical Office**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0004 - Sick Bay**

No Asbestos

**B00A - R0005 - Disabled Toilet**

No Asbestos

**B00A - R0006 - Interview**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0007 - Deputy Principal**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0008 - Deputy Principal**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0011 - Cleaning Distributed Store**

No Asbestos

**B00A - R0012 - Main Switch Board**

No Asbestos

**B00A - R0013 - Staff Toilet**

No Asbestos

**B00A - R0014 - Staff Toilet**

No Asbestos

**B00A - R0015 - Staff Toilet**

No Asbestos

**B00A - R0016 - Security Store**

No Asbestos

**B00A - R0017 - Principal**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0018 - Duplicating Workroom**

No Asbestos

**B00A - R0019 - Movement**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0021 - Clerical Office**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0022 - Staff Room**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0023 - Staff Room Annexe**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00A - R0024 - External Movement**

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00B - General Learning - 1998 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

**B00B - R0001 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0002 - Home Base**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0003 - Practical Activities - 1hb**

No Asbestos

**B00B - R0004 - Withdrawal Space - 1hb**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0005 - Home Base**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0006 - Practical Activities - 1hb**

No Asbestos

**B00B - R0007 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0008 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0009 - Home Base**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0010 - Practical Activities - 1hb**

No Asbestos

**B00B - R0011 - Withdrawal Space - 1hb**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0012 - Practical Activities - 1hb**

No Asbestos

**B00B - R0013 - Home Base**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0014 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00B - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0016 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0017 - External Movement**

No Asbestos

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00C - General Learning - 1998 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

**B00C - R0001 - Withdrawal Space - 1hb**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00C - R0002 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00C - R0003 - Security Store**

No Asbestos

**B00C - R0004 - Cleaning Distributed Store**

No Asbestos

**B00C - R0005 - Staff Toilet**

No Asbestos

**B00C - R0006 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00D - Multi Purpose Facilities/Pupil Facilities - 1998 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

|                                                    |                                                      |
|----------------------------------------------------|------------------------------------------------------|
| <b>B00D - R0001 - External Movement</b>            | No Asbestos                                          |
| <b>B00D - R0005 - Communications Cupboard</b>      | No Asbestos                                          |
| <b>B00D - R0009 - Garden Store</b>                 | No Asbestos                                          |
| <b>B00D - R0010 - Toilets - Girls</b>              | No Asbestos                                          |
| <b>B00D - R0011 - Shower/Change</b>                | No Asbestos                                          |
| <b>B00D - R0015 - Toilets - Boys</b>               | No Asbestos                                          |
| <b>B00D - R0016 - Sports Store</b>                 | No Asbestos                                          |
| <b>B00D - R0017 - P.E. Store</b>                   | No Asbestos                                          |
| <b>B00D - R0018 - Hall Chair Store</b>             | No Asbestos                                          |
| <b>B00D - R0019 - Distribution Board</b>           | Note: No inspection of live electrical installation. |
| <b>B00D - R0020 - Disabled Toilet</b>              | No Asbestos                                          |
| <b>B00D - R0021 - Distribution Board</b>           | Note: No inspection of live electrical installation. |
| <b>B00D - R0025 - Canteen</b>                      | No Asbestos                                          |
| <b>B00D - R0026 - Canteen Office/Store</b>         | No Asbestos                                          |
| <b>B00D - R0027 - General Assistant/Bulk Store</b> | No Asbestos                                          |
| <b>B00D - R0028 - Communal Space</b>               | No Asbestos                                          |
| <b>B00D - R0029 - Movement</b>                     | No Asbestos                                          |
| <b>B00D - R0030 - Raised Platform</b>              | No Asbestos                                          |
| <b>B00D - R0031 - Movement</b>                     | No Asbestos                                          |
| <b>B00D - R0032 - Hall Chair Store</b>             | No Asbestos                                          |
| <b>B00D - R0033 - Cleaning Distributed Store</b>   | No Asbestos                                          |
| <b>B00D - R0034 - Movement</b>                     | No Asbestos                                          |
| <b>B00D - R0035 - External Movement</b>            | No Asbestos                                          |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority   |
|---------|----------------------|--------|--------------------|--------------------|-------------|--------------------|
|         | <b>Sample No</b>     |        |                    |                    |             | <b>Test Result</b> |

No Asbestos

**B00D - R0036 - External Movement**

No Asbestos

**B00D - R0037 - Movement**

No Asbestos

**B00D - R0038 - Hall Chair Store**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00E - General Learning/Library - 1998 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

**B00E - R0001 - Practical Activities - 1hb**

No Asbestos

**B00E - R0002 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0005 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0007 - Practical Activities - 1hb**

No Asbestos

**B00E - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0014 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0015 - Staff Toilet**

No Asbestos

**B00E - R0016 - Staff Toilet**

No Asbestos

**B00E - R0017 - K.L.A. Store**

No Asbestos

**B00E - R0018 - Communications Room**

No Asbestos

**B00E - R0019 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0020 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0021 - Cleaning Distributed Store**

No Asbestos

**B00E - R0022 - External Movement**

No Asbestos



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00F - General Learning - 1998 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

**B00F - R0001 - Toilets - Boys**

No Asbestos

**B00F - R0002 - Kiln Room**

No Asbestos

**B00F - R0003 - Toilets - Girls**

No Asbestos

**B00F - R0004 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0005 - Practical Activities - 1hb**

No Asbestos

**B00F - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0007 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0008 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0009 - Practical Activities - 1hb**

No Asbestos

**B00F - R0010 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0012 - Practical Activities - 1hb**

No Asbestos

**B00F - R0013 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0014 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0015 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0016 - Practical Activities - 1hb**

No Asbestos

**B00F - R0017 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0018 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0019 - External Movement**

No Asbestos

**B00F - R0020 - Distribution Board**

Note: No inspection of live electrical installation.

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00G - General Learning - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

**B00G - R0001 - Home Base**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0002 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0003 - Practical Activities - 1hb**

No Asbestos

**B00G - R0004 - Withdrawal Space - 2hb**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0005 - Home Base**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0006 - Practical Activities - 1hb**

No Asbestos

**B00G - R0007 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0008 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0009 - Practical Activities - 1hb**

No Asbestos

**B00G - R0010 - Home Base**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0011 - Withdrawal Space - 2hb**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0012 - Home Base**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0013 - Practical Activities - 1hb**

No Asbestos

**B00G - R0014 - Home Base Store**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0015 - Special Programs Room**

|                                           |                   |
|-------------------------------------------|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|-------------------------------------------|-------------------|

**B00G - R0017 - Special Programs Store**

No Asbestos

**B00G - R0018 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0019 - Laundry - Type 2**

No Asbestos

**B00G - R0020 - Access Shower/Toilet - Type 2**

No Asbestos

| Product                                                          | Material Description | Extent | Location Reference | Material Condition | Risk Status                                          | Control Priority |
|------------------------------------------------------------------|----------------------|--------|--------------------|--------------------|------------------------------------------------------|------------------|
| Sample No                                                        |                      |        |                    |                    | Test Result                                          |                  |
| <b>B00G - R0022 - Toilets - Girls</b>                            |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0023 - Toilets - Boys</b>                             |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0024 - Cleaning Distributed Store</b>                 |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0025 - Distribution Board</b>                         |                      |        |                    |                    | Note: No inspection of live electrical installation. |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0026 - Movement</b>                                   |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0027 - Lift</b>                                       |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0028 - Garden Store</b>                               |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0029 - External Stairs</b>                            |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0030 - External Movement</b>                          |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0031 - Garden Store</b>                               |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R0032 - External Stairs</b>                            |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1001 - Home Base</b>                                  |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1002 - Home Base Store</b>                            |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1003 - Practical Activities - 1hb</b>                 |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1004 - Withdrawal Space - 2hb</b>                     |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1005 - Home Base</b>                                  |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1006 - Practical Activities - 1hb</b>                 |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1007 - Home Base Store</b>                            |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1008 - Home Base Store</b>                            |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1009 - Practical Activities - 1hb</b>                 |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1010 - Home Base</b>                                  |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1011 - Withdrawal Space - 2hb</b>                     |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1012 - Home Base</b>                                  |                      |        |                    |                    |                                                      |                  |

| Product                                          | Material Description | Extent | Location Reference | Material Condition | Risk Status                                          | Control Priority |
|--------------------------------------------------|----------------------|--------|--------------------|--------------------|------------------------------------------------------|------------------|
| Sample No                                        |                      |        |                    |                    | Test Result                                          |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)        | No Asbestos Found    |        |                    |                    |                                                      |                  |
| <b>B00G - R1013 - Practical Activities - 1hb</b> |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1014 - Home Base Store</b>            |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)        | No Asbestos Found    |        |                    |                    |                                                      |                  |
| <b>B00G - R1015 - Home Base Store</b>            |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)        | No Asbestos Found    |        |                    |                    |                                                      |                  |
| <b>B00G - R1016 - Practical Activities - 1hb</b> |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1017 - Home Base</b>                  |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)        | No Asbestos Found    |        |                    |                    |                                                      |                  |
| <b>B00G - R1018 - Withdrawal Space - 2hb</b>     |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)        | No Asbestos Found    |        |                    |                    |                                                      |                  |
| <b>B00G - R1019 - Home Base</b>                  |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)        | No Asbestos Found    |        |                    |                    |                                                      |                  |
| <b>B00G - R1020 - Practical Activities - 1hb</b> |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1021 - Home Base Store</b>            |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)        | No Asbestos Found    |        |                    |                    |                                                      |                  |
| <b>B00G - R1022 - Distribution Board</b>         |                      |        |                    |                    | Note: No inspection of live electrical installation. |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1023 - Lift</b>                       |                      |        |                    |                    |                                                      |                  |
| Vinyl Tiles (Under Floor Covering/Carpet)        | No Asbestos Found    |        |                    |                    |                                                      |                  |
| <b>B00G - R1024 - External Stairs</b>            |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1025 - External Movement</b>          |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1026 - Movement</b>                   |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1027 - Distribution Board</b>         |                      |        |                    |                    | Note: No inspection of live electrical installation. |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |
| <b>B00G - R1028 - External Stairs</b>            |                      |        |                    |                    |                                                      |                  |
| No Asbestos                                      |                      |        |                    |                    |                                                      |                  |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
|         | Sample No            |        |                    |                    |             | Test Result      |

**B00H - General Learning/Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

**B00H - R0001 - Toilets - Girls**

No Asbestos

**B00H - R0002 - Toilets - Boys**

No Asbestos

**B00H - R0003 - Access Shower/Toilet/Change**

No Asbestos

**B00H - R0004 - Practical Activities - 1hb**

No Asbestos

**B00H - R0005 - Home Base Store**

No Asbestos

**B00H - R0006 - Home Base**

No Asbestos

**B00H - R0007 - Withdrawal Space - 2hb**

No Asbestos

**B00H - R0008 - Practical Activities - 1hb**

No Asbestos

**B00H - R0009 - Home Base Store**

No Asbestos

**B00H - R0010 - Home Base**

No Asbestos

**B00H - R0011 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0012 - Special Programs Room**

No Asbestos

**B00H - R0013 - Special Programs Store**

No Asbestos

**B00H - R0014 - External Movement**

No Asbestos

**B00H - R0015 - External Stairs**

No Asbestos

**B00H - R0016 - External Stairs**

No Asbestos

**B00H - R0017 - General Storeroom**

No Asbestos

**B00H - R0018 - External Movement**

No Asbestos

**B00H - R1001 - Practical Activities - 1hb**

No Asbestos

**B00H - R1002 - Home Base Store**

No Asbestos

**B00H - R1003 - Home Base**

No Asbestos

**B00H - R1004 - Withdrawal Space - 2hb**

No Asbestos

**B00H - R1005 - Practical Activities - 1hb**

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority   |
|---------|----------------------|--------|--------------------|--------------------|-------------|--------------------|
|         | <b>Sample No</b>     |        |                    |                    |             | <b>Test Result</b> |

No Asbestos

**B00H - R1006 - Home Base Store**

No Asbestos

**B00H - R1007 - Home Base**

No Asbestos

**B00H - R1008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R1009 - External Movement**

No Asbestos

**B00H - R1010 - External Stairs**

No Asbestos

**B00H - R1011 - External Stairs**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00I - Storage - 2010 - Metal Shed (Metal Shed)**

**Exterior**

|                  |                     |
|------------------|---------------------|
| Ceiling Voids    | No Asbestos Found   |
| Underfloor Voids | Requires Inspection |

**Interior**

**B00I - R0001 - Sports Store**

No Asbestos

2017



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017