

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Administration - 1963 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 5529/B00E/Eaves Linings/S2					No Asbestos Detected
Gable Ends	Flat AC Sheeting 5529/B00E/Gable Ends/S3					No Asbestos Detected
Underfloor Voids	No Asbestos Found					
Ceiling Void	No Asbestos Found					

Interior**B00E - R0003 - Seminar/Study**

No Asbestos

B00E - R0004 - Sick Bay

No Asbestos

B00E - R0008 - General Learning Space

No Asbestos

B00E - R0009 - General Storeroom

No Asbestos

B00E - R0010 - Movement

No Asbestos

B00E - R0011 - Security Store

No Asbestos

B00E - R0013 - Staff Toilet

No Asbestos

B00E - R0014 - Cleaning Supplies

No Asbestos

B00E - R0015 - Entry Vestibule

No Asbestos

B00E - R0017 - Reading Area

No Asbestos

B00E - R0022 - Raised Platform

No Asbestos

B00E - R0023 - Movement

No Asbestos

B00E - R0024 - Movement

No Asbestos

B00E - R0037 - Entry Vestibule

No Asbestos

B00E - R0038 - Clerical Office

No Asbestos

B00E - R0039 - Duplicating Workroom

No Asbestos

B00E - R0040 - Interview

No Asbestos

B00E - R0041 - Principal

No Asbestos

B00E - R0042 - Deputy Principal

No Asbestos

B00E - R0043 - Movement

No Asbestos

B00E - R0044 - Security Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R0045 - Staff Toilet

No Asbestos

B00E - R0046 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0047 - Staff Shower/Change

No Asbestos

B00E - R0048 - General Storeroom

No Asbestos

B00E - R0049 - Movement

No Asbestos

B00E - R0050 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - General Storeroom

No Asbestos

B00F - R0002 - Cleaning Supplies

No Asbestos

B00F - R0003 - Toilets - Boys/Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 5529/B00G/Eaves Linings/S1					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00G - R0001 - Cleaning Supplies

No Asbestos

B00G - R0002 - General Assistant/Bulk Store

No Asbestos

B00G - R0003 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Support Unit - 1958 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior**B00H - R0001 - Home Base**

No Asbestos

B00H - R0002 - Withdrawal Space - 1hb

No Asbestos

B00H - R0003 - Home Base Store

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Withdrawal Space - 1hb

No Asbestos

B00H - R0006 - Home Base Store

No Asbestos

B00H - R0007 - Practical Activities - 1hb

No Asbestos

B00H - R0008 - Toilets - Girls

No Asbestos

B00H - R0009 - Toilets - Boys

No Asbestos

B00H - R0010 - Laundry

No Asbestos

B00H - R0011 - Home Base

No Asbestos

B00H - R0012 - Withdrawal Space - 1hb

No Asbestos

B00H - R0013 - Communications Cupboard

No Asbestos

B00H - R0014 - Home Base Store

No Asbestos

B00H - R0015 - Home Base

No Asbestos

B00H - R0016 - Withdrawal Space - 1hb

No Asbestos

B00H - R0017 - Home Base Store

No Asbestos

B00H - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0019 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities - 1999 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B001 - R0001 - Cleaning Supplies**

No Asbestos

B001 - R0002 - Therapy Store

No Asbestos

B001 - R0003 - Plant

No Asbestos

B001 - R0004 - Staff Room

No Asbestos

B001 - R0005 - Staff Shower/Change

No Asbestos

B001 - R0006 - Movement

No Asbestos

B001 - R0007 - Hydrotherapy - Pool

No Asbestos

B001 - R0008 - Shower/Change

No Asbestos

B001 - R0009 - Toilets - Girls

No Asbestos

B001 - R0010 - Toilets - Boys

No Asbestos

B001 - R0011 - Shower/Change

No Asbestos

B001 - R0012 - Movement

No Asbestos

B001 - R0013 - Movement

No Asbestos

B001 - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B001 - R0015 - Staff Toilet

No Asbestos

B001 - R0016 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00J - General Learning - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00J - R0001 - Home Base**

No Asbestos

B00J - R0002 - Withdrawal Space - 1hb

No Asbestos

B00J - R0003 - Cleaning Supplies

No Asbestos

B00J - R0004 - Practical Activities - 1hb

No Asbestos

B00J - R0005 - Toilets - Girls

No Asbestos

B00J - R0006 - Toilets - Boys

No Asbestos

B00J - R0007 - Laundry

No Asbestos

B00J - R0008 - Home Base Store

No Asbestos

B00J - R0009 - Home Base Store

No Asbestos

B00J - R0010 - Home Base

No Asbestos

B00J - R0011 - Withdrawal Space - 1hb

No Asbestos

B00J - R0012 - Communications Cupboard

No Asbestos

B00J - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0014 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00K - R0001 - Home Base**

No Asbestos

B00K - R0002 - Withdrawal Space - 1hb

No Asbestos

B00K - R0003 - Home Base Store

No Asbestos

B00K - R0004 - Home Base

No Asbestos

B00K - R0005 - Home Base Store

No Asbestos

B00K - R0006 - Withdrawal Space - 1hb

No Asbestos

B00K - R0007 - Practical Activities - 1hb

No Asbestos

B00K - R0008 - Toilets - Girls

No Asbestos

B00K - R0009 - Toilets - Boys

No Asbestos

B00K - R0010 - Home Base

No Asbestos

B00K - R0011 - Withdrawal Space - 1hb

No Asbestos

B00K - R0012 - Home Base Store

No Asbestos

B00K - R0013 - Home Base

No Asbestos

B00K - R0014 - Withdrawal Space - 1hb

No Asbestos

B00K - R0015 - Home Base Store

No Asbestos

B00K - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0017 - Laundry

No Asbestos

B00K - R0018 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Communal Facilities - 1999 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00L - R0001 - Other-Community Use

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Communal Space

No Asbestos

B00M - R0002 - No Access

No Asbestos

B00M - R0003 - Access Shower/Toilet/Change

No Asbestos

B00M - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 120 - D10545 - Learning Unit - Single Primary H/Cap PAA : Placement Date - 30/04/2010

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Home Base Store-I.O.

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Entry

No Asbestos Found.

NS 120 - D12822 - Learning Unit - Single Primary H/Cap PAA : Placement Date - 29/04/2010

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Home Base Store-I.O.

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Entry

No Asbestos Found.

NS 120 - D12878 - Learning Unit - Single Primary H/Cap PAA : Placement Date - 22/12/2008

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Home Base Store-I.O.

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Entry

No Asbestos Found.

NS 120 - D13766 - Learning Unit - Single Primary H/Cap PAA : Placement Date - 26/01/2007

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Exterior						
No Asbestos Found.						
Interior						
R1 - Home Base-I.O.						
No Asbestos Found.						
R2 - Toilets-Disabled						
No Asbestos Found.						
R3 - Home Base Store-I.O.						
No Asbestos Found.						
R4 - Practical Activity Area						
No Asbestos Found.						
R5 - Entry						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017