


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Bullimbal School (5569)
Region : New England
State Electorate : Tamworth
Local Government Area : Tamworth

Initial Survey : Noel Arnold & Associates : 25 - Mar - 2008
Reviewed By : Greencap-NAA : 07 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/Library - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00A - M0001 - Plant**

No Asbestos

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Entry Vestibule

No Asbestos

B00A - R0003 - Interview

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Principal

No Asbestos

B00A - R0006 - Deputy Principal

No Asbestos

B00A - R0007 - Cleaning Distributed Store

No Asbestos

B00A - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0009 - Staff Kitchen

No Asbestos

B00A - R0010 - Staff Room

No Asbestos

B00A - R0011 - Staff Room Annexe

No Asbestos

B00A - R0012 - Security Store

No Asbestos

B00A - R0013 - Access Shower/Toilet

No Asbestos

B00A - R0014 - Staff Toilet

No Asbestos

B00A - R0015 - Staff Toilet

No Asbestos

B00A - R0016 - Sick Bay

No Asbestos

B00A - R0017 - Clerical/Printing

No Asbestos

B00A - R0018 - Clerical/Printing

No Asbestos

B00A - R0019 - External Movement

No Asbestos

B00A - R0020 - Reading Area

No Asbestos

B00A - R0021 - Library Office/Workroom

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0022 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R0023 - Communications Room						
No Asbestos						
B00A - R0024 - General Storeroom						
No Asbestos						
B00A - R0025 - K.L.A. Store						
No Asbestos						
B00A - R0026 - Cleaning Distributed Store						
No Asbestos						
B00A - R0027 - Access Shower/Toilet/Change						
No Asbestos						
B00A - R0028 - Plant						
No Asbestos						
B00A - R0029 - Home Base Store						
No Asbestos						
B00A - R0030 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0031 - Other						
No Asbestos						
B00A - R0032 - Home Base						
No Asbestos						
B00A - R0033 - Toilet - Lobby						
No Asbestos						
B00A - R0034 - Access Shower/Toilet/Change						
No Asbestos						
B00A - R0035 - Laundry - Type 3						
No Asbestos						
B00A - R0036 - Access Shower/Toilet/Change						
No Asbestos						
B00A - R0037 - Access Shower/Toilet/Change						
No Asbestos						
B00A - R0038 - Home Base						
No Asbestos						
B00A - R0039 - Other						
No Asbestos						
B00A - R0040 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0041 - Home Base Store						
No Asbestos						
B00A - R0042 - Cleaning Distributed Store						
No Asbestos						
B00A - R0043 - Practical Activities - 1hb						
No Asbestos						
B00A - R0044 - Practical Activities - 1hb						
No Asbestos						
B00A - R0045 - Special Programs Room						
No Asbestos						
B00A - R0046 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Special Purpose (Craft Art Science Tas Etc) - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00B - R0001 - Covered Outdoor Learning Area

No Asbestos

B00B - R0002 - External Movement

No Asbestos

B00B - R0003 - Covered Outdoor Learning Area

No Asbestos

B00B - R0004 - Staff Kitchen

No Asbestos

B00B - R0005 - Special Programs Room

No Asbestos

B00B - R0006 - Special Programs Store

No Asbestos

B00B - R0007 - Special Programs Room - Type 2

No Asbestos

B00B - R0008 - P.E. Store

No Asbestos

B00B - R0009 - Sports Store

No Asbestos

B00B - R0010 - Toilets - Girls

No Asbestos

B00B - R0011 - Toilets - Boys

No Asbestos

B00B - R0012 - Access Shower/Toilet/Change

No Asbestos

B00B - R0013 - Cleaning Supplies

No Asbestos

B00B - R0014 - General Storeroom

No Asbestos

B00B - R0015 - Garden Store

No Asbestos

B00B - R0016 - Plant

No Asbestos

B00B - R0017 - Main Switch Board

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00C - R0001 - External Movement**

No Asbestos

B00C - R0002 - Practical Activities

No Asbestos

B00C - R0003 - Home Base

No Asbestos

B00C - R0004 - Home Base Store

No Asbestos

B00C - R0005 - Withdrawal Space - 1hb

No Asbestos

B00C - R0006 - Other

No Asbestos

B00C - R0007 - Plant

No Asbestos

B00C - R0008 - Other

No Asbestos

B00C - R0009 - Access Shower/Toilet/Change

No Asbestos

B00C - R0010 - Laundry - Type 3

No Asbestos

B00C - R0011 - Access Shower/Toilet/Change

No Asbestos

B00C - R0012 - Other

No Asbestos

B00C - R0013 - Home Base

No Asbestos

B00C - R0014 - Practical Activities - 1hb

No Asbestos

B00C - R0015 - Withdrawal Space - 1hb

No Asbestos

B00C - R0016 - Home Base Store

No Asbestos

B00C - R0017 - Cleaning Distributed Store

No Asbestos

B00C - R0018 - Access Shower/Toilet/Change

No Asbestos

B00C - R0019 - Home Base Store

No Asbestos

B00C - R0020 - Withdrawal Space - 1hb

No Asbestos

B00C - R0021 - Other

No Asbestos

B00C - R0022 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0023 - Practical Activities - 1hb						
No Asbestos						
B00C - R0024 - Access Shower/Toilet/Change						
No Asbestos						
B00C - R0025 - Laundry - Type 3						
No Asbestos						
B00C - R0026 - Home Base						
No Asbestos						
B00C - R0027 - Other						
No Asbestos						
B00C - R0028 - Withdrawal Space - 1hb						
No Asbestos						
B00C - R0029 - Home Base Store						
No Asbestos						
B00C - R0030 - Cleaning Distributed Store						
No Asbestos						
B00C - R0031 - Practical Activities - 1hb						
No Asbestos						
B00C - R0032 - Access Shower/Toilet/Change						
No Asbestos						
B00C - R0033 - Home Base Store						
No Asbestos						
B00C - R0034 - Withdrawal Space - 1hb						
No Asbestos						
B00C - R0035 - Practical Activities						
No Asbestos						
B00C - R0036 - Home Base						
No Asbestos						
B00C - R0037 - Other						
No Asbestos						
B00C - R0038 - Access Shower/Toilet/Change						
No Asbestos						
B00C - R0039 - Laundry - Type 3						
No Asbestos						
B00C - R0040 - Other						
No Asbestos						
B00C - R0041 - Withdrawal Space - 1hb						
No Asbestos						
B00C - R0042 - Home Base Store						
No Asbestos						
B00C - R0043 - Garden Store						
No Asbestos						
B00C - R0044 - Home Base						
No Asbestos						
B00C - R0045 - Practical Activities - 1hb						
No Asbestos						
B00C - R0046 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R0047 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R0048 - Distribution Board					Note: No inspection of live electrical installation.	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Other - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00D - R0001 - External Movement**

No Asbestos

B00D - R0002 - Other

No Asbestos

B00D - R0003 - Movement

No Asbestos

B00D - R0004 - Hydrotherapy - Pool

No Asbestos

B00D - R0005 - Other

No Asbestos

B00D - R0006 - Access Shower/Toilet/Change

No Asbestos

B00D - R0007 - Access Shower/Toilet

No Asbestos

B00D - R0008 - Other

No Asbestos

B00D - R0009 - Plant

No Asbestos

B00D - R0010 - Other

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017