

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bexley Public School (7406)
Region : Sydney
State Electorate : Rockdale
Local Government Area : Rockdale

Initial Survey : Noel Arnold & Associates : 17 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 21 - Jul - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1924 - Brick/Block (Brick/Block)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00A - R0001 - Cleaning Distributed Store

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
		7406/B00A/R0003/Floor Coverings Res/Textile/S1				No Asbestos Detected

B00A - R0004 - Disabled Toilet

Wall Linings Internal	Flat AC Sheeting					
		7406/B00A/R0005/Wall Linings Internal/S2				No Asbestos Detected

B00A - R0005 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting					
		7406/B00A/R0005/Wall Linings Internal/S2				No Asbestos Detected

B00A - R0006 - Staff Room

No Asbestos

B00A - R0007 - Interview

No Asbestos

B00A - R0008 - Duplicating Workroom

No Asbestos

B00A - R0009 - Principal

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Clerical Office

No Asbestos

B00A - R0012 - Sick Bay

No Asbestos

B00A - R0013 - Entry Vestibule

No Asbestos

B00A - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
		7406/B00A/R0019/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Main Switch Board

No Asbestos

B00A - R0017 - Movement

No Asbestos

B00A - R0018 - Security Store

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
		7406/B00A/R0019/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)

B00A - R0019 - Communal Space

Ceiling Structures/Linings	Flat AC Sheeting	126m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
		7406/B00A/R0019/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0020 - Raised Platform						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R0022 - Stairs						
No Asbestos						
B00A - R0023 - Stairs						
No Asbestos						
B00A - R1001 - Cleaning Supplies						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1002 - Deputy Principal						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1003 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1004 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1006 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1007 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles					
7406/B00A/R0003/Floor Coverings Res/Textile/S1					No Asbestos Detected	
B00A - R1008 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles					
7406/B00A/R0003/Floor Coverings Res/Textile/S1					No Asbestos Detected	
B00A - R1009 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	77m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1010 - Home Base Store						
Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1011 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	51m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1012 - Special Programs Room						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1013 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1014 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7406/B00A/R0019/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1015 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R1016 - Withdrawal Space - 2hb						
No Asbestos						
B00A - R1017 - Home Base Store						
No Asbestos						
B00A - R1018 - Withdrawal Space - 1hb						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1917 - Brick/Block (Brick/Block)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - Cleaning Distributed Store

No Asbestos

B00B - R0004 - Special Programs Room

No Asbestos

B00B - R0006 - Movement

No Asbestos

B00B - R0007 - Deputy Principal

No Asbestos

B00B - R0008 - Home Base

No Asbestos

B00B - R0009 - Practical Activities - 1hb

No Asbestos

B00B - R0010 - Home Base Store

No Asbestos

B00B - R0011 - Home Base

No Asbestos

B00B - R0012 - Practical Activities - 1hb

No Asbestos

B00B - R0013 - Home Base Store

No Asbestos

B00B - R0014 - Home Base

No Asbestos

B00B - R0015 - Practical Activities - 1hb

No Asbestos

B00B - R0016 - Home Base Store

No Asbestos

B00B - R0017 - Home Base

No Asbestos

B00B - R0018 - Practical Activities - 1hb

No Asbestos

B00B - R0019 - Home Base Store

No Asbestos

B00B - R0020 - Home Base

No Asbestos

B00B - R0021 - Practical Activities - 1hb

No Asbestos

B00B - R0022 - Home Base Store

No Asbestos

B00B - R0023 - Home Base

No Asbestos

B00B - R0024 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00B - R0025 - Movement					
	No Asbestos					
	B00B - R0026 - Movement					
	No Asbestos					
	B00B - R0027 - Special Programs Room					
	No Asbestos					
	B00B - R0028 - General Storeroom					
	No Asbestos					
	B00B - R0030 - Movement					
	No Asbestos					
	B00B - R0031 - Cleaning Distributed Store					
	No Asbestos					
	B00B - R0032 - Stairs					
	No Asbestos					
	B00B - R0033 - Stairs					
	No Asbestos					
	B00B - R0035 - External Movement					
	No Asbestos					
	B00B - R0036 - External Movement					
	No Asbestos					
	B00B - R1001 - Practical Activities - 1hb					
	No Asbestos					
	B00B - R1002 - Movement					
	No Asbestos					
	B00B - R1003 - Home Base					
	No Asbestos					
	B00B - R1004 - Home Base					
	No Asbestos					
	B00B - R1005 - Home Base					
	No Asbestos					
	B00B - R1006 - Home Base					
	No Asbestos					
	B00B - R1007 - Home Base					
	No Asbestos					
	B00B - R1008 - Home Base					
	No Asbestos					
	B00B - R1009 - Practical Activities - 1hb					
	No Asbestos					
	B00B - R1010 - Cleaning Distributed Store					
	No Asbestos					
	B00B - R1011 - Stairs					
	No Asbestos					
	B00B - R1012 - Stairs					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Toilets - Boys

No Asbestos

B00C - R0006 - Cleaning Distributed Store

No Asbestos

B00C - R0007 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Toilets - Girls

No Asbestos

B00C - R0010 - Lift

No Asbestos

B00C - R0011 - Movement

No Asbestos

B00C - R0012 - Movement

No Asbestos

B00C - R0013 - Plant

No Asbestos

B00C - R1001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1002 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1003 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1004 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1005 - Cleaning Distributed Store

No Asbestos

B00C - R1006 - General Storeroom

No Asbestos

B00C - R1007 - Lift

No Asbestos

B00C - R1008 - Distribution Board

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)

No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities/Building Services - 1970 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting					
	7406/B00D/Eaves Linings/S5					No Asbestos Detected

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Canteen

No Asbestos

B00D - R0003 - Canteen Office/Store

No Asbestos

B00D - R0004 - Movement

No Asbestos

B00D - R0005 - General Assistant/Bulk Store

No Asbestos

B00D - R0006 - Garden Store

No Asbestos

B00D - R0007 - Sports Store

No Asbestos

B00D - R0008 - Staff Toilet

No Asbestos

B00D - R0009 - Kiln Room

No Asbestos

B00D - R0010 - Cleaning Supplies

No Asbestos

B00D - R0011 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	30m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	7406/B00D/R0011/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

B00D - R0012 - Cleaning Supplies

No Asbestos

B00D - R0013 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	7406/B00D/R0011/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Other-Non Government Pre-School - 1938 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior**B00E - R0004 - Movement**

No Asbestos

B00E - R0006 - Other-Vacant

No Asbestos

B00E - R0007 - Movement

No Asbestos

B00E - R0008 - Toilets - Boys/Girls

No Asbestos

B00E - R0009 - General Storeroom

No Asbestos

B00E - R0010 - Staff Kitchen

No Asbestos

B00E - R0013 - Movement

No Asbestos

B00E - R0014 - Staff Toilet - Pre

No Asbestos

B00E - R0015 - General Storeroom - Pre

No Asbestos

B00E - R0016 - Home Base - Pre

No Asbestos

B00E - R0017 - Home Base - Pre

No Asbestos

B00E - R0018 - Toilets - Boys/Girls - Pre

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00G - R0001 - Communal Space

No Asbestos

B00G - R0002 - Raised Platform

No Asbestos

B00G - R0003 - Movement

No Asbestos

B00G - R0004 - Movement

No Asbestos

B00G - R0005 - Movement

No Asbestos

B00G - R0006 - Hall Chair Store

No Asbestos

B00G - R0007 - Communal/Performance Store

No Asbestos

B00G - R0008 - P.E. Store

No Asbestos

B00G - R0009 - Toilet - Lobby

No Asbestos

B00G - R0010 - Toilets - Girls

No Asbestos

B00G - R0011 - Sound Cupboard

No Asbestos

B00G - R0012 - Toilet - Lobby

No Asbestos

B00G - R0013 - Toilets - Boys

No Asbestos

B00G - R0014 - Cleaning Distributed Store

No Asbestos

B00G - R0015 - Plant

No Asbestos

B00G - R0016 - Plant

No Asbestos

B00G - R0017 - Disabled Shower/Toilet

No Asbestos

B00G - R0018 - Main Switch Board

No Asbestos

B00G - R0019 - Covered Outdoor Learning Area

No Asbestos

B00G - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

7406_ASB_261112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017