


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bankstown Girls High School (8254)
Region : South Western Sydney
State Electorate : Bankstown
Local Government Area : Bankstown

Initial Survey : Noel Arnold & Associates : 22 - Apr - 2008
Reviewed By : Greencap-NAA : 29 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Science Learning - 1960 - Concrete Framed (Concrete Framed)**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	No Asbestos Found

Interior**B00A - R0001 - Resources Store**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0003 - Careers Advisers Office

No Asbestos

B00A - R0004 - Careers Advisers Office

No Asbestos

B00A - R0005 - Science Laboratory

No Asbestos

B00A - R0006 - Uniform Shop

No Asbestos

B00A - R0007 - Uniform Shop

No Asbestos

B00A - R0008 - General Learning Space

No Asbestos

B00A - R0009 - Dark Room

No Asbestos

B00A - R0010 - Resources Store

No Asbestos

B00A - R0011 - Music Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0012 - Cleaning Store - Distributed

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0013 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0014 - Chemical Store

No Asbestos

B00A - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0016 - Cleaning Store - Distributed

No Asbestos

B00A - R0017 - Plant

No Asbestos

B00A - R0018 - Resources Store

No Asbestos

B00A - R0019 - Science Laboratory

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0020 - Performance Workshop						
No Asbestos						
B00A - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R0022 - Performance Store						
No Asbestos						
B00A - R0023 - Movement						
No Asbestos						
B00A - R0024 - Science Laboratory						
No Asbestos						
B00A - R0025 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	114m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting					
8254/B00A/R0025/Wall Linings Internal/S1				No Asbestos Detected		
B00A - R0026 - Science Laboratory						
No Asbestos						
B00A - R0027 - Staff Study						
No Asbestos						
B00A - R0028 - Preparation - Science						
No Asbestos						
B00A - R0029 - Staff - Toilet						
No Asbestos						
B00A - R0030 - Cleaning Store - Distributed						
No Asbestos						
B00A - R0031 - General Learning Space						
No Asbestos						
B00A - R0033 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R0034 - Printing/Photocopying						
No Asbestos						
B00A - R0035 - Science Laboratory						
No Asbestos						
B00A - R0036 - Staff - Toilet						
No Asbestos						
B00A - R0037 - Resources Store						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R0038 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R0039 - Office/Store						
No Asbestos						
B00A - R0040 - Staff Study						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0041 - Stairs						
No Asbestos						
B00A - R0042 - Stairs						
No Asbestos						
B00A - R0044 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Electrical Cupboard Opposite Uniform Shop	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R0046 - Stairs						
No Asbestos						
B00A - R0047 - Apparatus Storage						
No Asbestos						
B00A - R0048 - Printing/Photocopying						
No Asbestos						
B00A - R0049 - External Stairs						
No Asbestos						
B00A - R0050 - Stairs						
No Asbestos						
B00A - R1001 - Staff - Toilet						
No Asbestos						
B00A - R1002 - Movement						
No Asbestos						
B00A - R1005 - Computer Learning Space						
No Asbestos						
B00A - R1006 - General Learning Space						
No Asbestos						
B00A - R1007 - General Learning Space						
No Asbestos						
B00A - R1008 - Staff Study						
No Asbestos						
B00A - R1009 - Resources Store						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R1010 - General Learning Space						
No Asbestos						
B00A - R1011 - General Learning Space						
No Asbestos						
B00A - R1012 - General Learning Space						
No Asbestos						
B00A - R1013 - General Learning Space						
No Asbestos						
B00A - R1014 - General Learning Space						
No Asbestos						
B00A - R1015 - Staff - Toilet						
No Asbestos						
B00A - R1016 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R1017 - General Learning Space						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
B00A - R1018 - General Learning Space						
No Asbestos						
B00A - R1019 - General Learning Space						
No Asbestos						
B00A - R1020 - General Learning Space						
No Asbestos						
B00A - R1021 - General Learning Space						
No Asbestos						
B00A - R1022 - Cleaning Store - Distributed						
No Asbestos						
B00A - R1023 - Resources Store						
Floor Coverings Res/Textile	Vinyl Tiles					
8254/B00A/R1023/Floor Coverings Res/Textile/S4						No Asbestos Detected
B00A - R1024 - Staff Study						
No Asbestos						
B00A - R1025 - General Learning Space						
No Asbestos						
B00A - R1026 - Office/Store						
No Asbestos						
B00A - R1027 - Distribution Board Cupboard						
						Note: No inspection of live electrical installation.
No Asbestos						
B00A - R1028 - Computer Store						
No Asbestos						
B00A - R1029 - Computer Learning Space						
No Asbestos						
B00A - R1030 - Cleaning Store - Distributed						
No Asbestos						
B00A - R1031 - Stairs						
No Asbestos						
B00A - R1032 - Stairs						
No Asbestos						
B00A - R1033 - Stairs						
No Asbestos						
B00A - R1034 - Stairs						
No Asbestos						
B00A - R1035 - General Learning Space						
No Asbestos						
B00A - R9001 - General Storeroom						
No Asbestos						
B00A - R9002 - Staff - Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3						Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R9005 - Cleaning Store - Distributed						
No Asbestos						
B00A - R9006 - Pantry						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00A/R0038/Ceiling Structures/Linings/S3						Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R9007 - Stairs						
No Asbestos						
B00A - R9008 - Movement						
No Asbestos						
B00A - R9009 - Student Canteen						
No Asbestos						
B00A - R9010 - Multi-Purpose Space						
No Asbestos						
B00A - R9011 - Cleaning Store - Distributed						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Technological & Applied Studies/General Learning - 1960 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting	45m2	North, South, East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction - Height						
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

Interior**B00B - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00B/R0010/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - General Learning Space

No Asbestos

B00B - R0005 - Main Switchroom

Floor Coverings Res/Textile	Compressed AC Sheet				
8254/B00B/R0005/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00B - R0006 - Food Technology L.S.

No Asbestos

B00B - R0010 - Staff - Toilet

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00B/R0010/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00B/R0010/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0012 - General Storeroom

No Asbestos

B00B - R0013 - Dust Extraction Space

No Asbestos

B00B - R0014 - Wood Technology Bay

No Asbestos

B00B - R0015 - Materials Store

No Asbestos

B00B - R0019 - Resources Store

No Asbestos

B00B - R0022 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8254/B00B/R0010/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0023 - Preparation

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0024 - Pantry						
No Asbestos						
B00B - R0025 - Food Technology L.S.						
No Asbestos						
B00B - R0026 - Stairs						
No Asbestos						
B00B - R0027 - Design/Technology L.S.						
No Asbestos						
B00B - R0028 - Design/Technology L.S.						
No Asbestos						
B00B - R0029 - Movement						
No Asbestos						
B00B - R0031 - Design/Technology L.S.						
No Asbestos						
B00B - R0032 - Staff Study						
No Asbestos						
B00B - R0033 - Tea Room						
No Asbestos						
B00B - R1001 - Special Learning Space						
No Asbestos						
B00B - R1002 - Resources Store						
No Asbestos						
B00B - R1003 - Cleaning Store - Distributed						
No Asbestos						
B00B - R1004 - Resources Store						
No Asbestos						
B00B - R1007 - General Learning Space						
No Asbestos						
B00B - R1008 - Distribution Board Cupboard						
No Asbestos					Note: No inspection of live electrical installation.	
B00B - R1009 - Cleaning Store - Distributed						
No Asbestos						
B00B - R1010 - Staff Study						
No Asbestos						
B00B - R1011 - Movement						
No Asbestos						
B00B - R1012 - Stairs						
No Asbestos						
B00B - R1013 - General Learning Space						
No Asbestos						
B00B - R1014 - Handwashing Facilities						
No Asbestos						
B00B - R1015 - General Learning Space						
No Asbestos						
B00B - R1016 - Handwashing Facilities						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Music/Technological & Applied Studies - 1960 - Concrete Framed (Concrete Framed)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - General Learning Space

No Asbestos

B00C - R0004 - Resources Store

No Asbestos

B00C - R0005 - Music Learning Space

No Asbestos

B00C - R0006 - Cleaning Store - Distributed

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Practice/Seminar

No Asbestos

B00C - R0009 - General Storeroom

No Asbestos

B00C - R0010 - Music Store

No Asbestos

B00C - R0011 - Movement

No Asbestos

B00C - R0012 - Music Learning Space

No Asbestos

B00C - R0013 - Stairs

No Asbestos

B00C - R0014 - Resources Store

No Asbestos

B00C - R0015 - Handwashing Facilities

No Asbestos

B00C - R1002 - General Learning Space

No Asbestos

B00C - R1003 - Resources Store

No Asbestos

B00C - R1004 - Resources Store

No Asbestos

B00C - R1005 - Interview/Office - Type 1

No Asbestos

B00C - R1006 - Cleaning Store - Distributed

No Asbestos

B00C - R1008 - Design/Technology L.S.

No Asbestos

B00C - R1009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R1010 - Resources Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R1011 - Resources Store

No Asbestos

B00C - R1012 - Design/Technology L.S.

No Asbestos

B00C - R1013 - Stairs

No Asbestos

B00C - R1014 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Multi Purpose Facilities/Physical Education - 1960 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting	150m2	North, South, East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00D/Eaves Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Awnings	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00E/R0005/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00D - M0001 - Archive Store**

No Asbestos

B00D - M0002 - Movement

No Asbestos

B00D - M0003 - Movement

No Asbestos

B00D - M0004 - Performance Store

No Asbestos

B00D - R0001 - Staff Study

No Asbestos

B00D - R0003 - Cleaning Store - Distributed

No Asbestos

B00D - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00A/R0038/Ceiling Structures/Linings/S3			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0005 - Movement

No Asbestos

B00D - R0006 - Resources Store

No Asbestos

B00D - R0007 - Stage

No Asbestos

B00D - R0008 - General Storeroom

No Asbestos

B00D - R0009 - Movement

No Asbestos

B00D - R0010 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0011 - Chair Store

No Asbestos

B00D - R0012 - Multi-Purpose Space

No Asbestos

B00D - R0013 - Plant

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00A/R0038/Ceiling Structures/Linings/S3			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0014 - Sport Equipment Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
					No Asbestos	
	B00D - R0015 - External Movement				No Asbestos	
	B00D - R0016 - External Movement				No Asbestos	
	B00D - R0018 - Sport Equipment Store				No Asbestos	
	B00D - R0019 - Staff - Toilet				No Asbestos	
	B00D - R0020 - Staff - Toilet				No Asbestos	
	B00D - R0021 - External Movement				No Asbestos	
	B00D - R9001 - General Assistants				No Asbestos	
	B00D - R9002 - General Assistants				No Asbestos	
	B00D - R9003 - General Assistants				No Asbestos	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00E - Pupil Facilities - 1960 - Concrete (Concrete)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00D/Eaves Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior**B00E - R0002 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00E/R0005/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0003 - Staff - Toilet

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00E/R0005/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00E/R0005/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	134m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00E/R0005/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0006 - Toilets-Girls

Ceiling Structures/Linings	Flat AC Sheeting	118m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00E/R0005/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0007 - Cleaning Store - Distributed

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8254/B00E/R0005/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Administration/Library/Art - 1994 - Brick/Steel Frame (Brick/Steel Frame)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00F - R0001 - Administration - Clerical

No Asbestos

B00F - R0003 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0007 - Cleaning Store - Distributed

No Asbestos

B00F - R0008 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - Multi Media Workshop

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - Secure Storeroom

No Asbestos

B00F - R0011 - Resources Store

No Asbestos

B00F - R0012 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0013 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0014 - Staff - Toilet

No Asbestos

B00F - R0015 - Staff - Toilet

No Asbestos

B00F - R0016 - Clinic - Girls

No Asbestos

B00F - R0017 - Toilets-Girls

No Asbestos

B00F - R0018 - Leading Teacher

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0022 - Art Learning Space

No Asbestos

B00F - R0023 - Workshop

No Asbestos

B00F - R0024 - Kiln Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Small Kiln "Rada-therm"	Encapsulated Insulation material within unit 8254/B00F/R0024/Small Kiln "Rada-therm"/S7	1Unit	Between two large kilns	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00F - R0025 - Art Learning Space

No Asbestos

B00F - R0026 - Art Learning Space

No Asbestos

B00F - R0027 - Access Staff Shower/Toilet

No Asbestos

B00F - R0028 - Lift

No Asbestos

B00F - R0029 - Plant

No Asbestos

B00F - R0030 - Plant

No Asbestos

B00F - R0031 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0032 - Tiered Learning Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0033 - External Movement

No Asbestos

B00F - R0034 - External Movement

No Asbestos

B00F - R0035 - External Stairs

No Asbestos

B00F - R0036 - Movement

No Asbestos

B00F - R0037 - Staff Study

No Asbestos

B00F - R1001 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1002 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1003 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1004 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1005 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1006 - Audio Visual Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1007 - Library Administration

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1008 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R1010 - Covered Area						
No Asbestos						
B00F - R1011 - Cleaning Store - Distributed						
No Asbestos						
B00F - R1012 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00F - R1013 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00F - R1014 - Leading Teacher						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00F - R1015 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00F - R1017 - External Stairs						
No Asbestos						
B00F - R1018 - Commonroom						
No Asbestos						
B00F - R1019 - Staff Kitchen						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Z - Building Services - 2000 - Brick/Block (Brick/Block)

Exterior

No Asbestos

Interior

B00Z - R0001 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D13696 - Learning Unit - Standard/Withdrawal : Placement Date - 8/01/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017