

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Guildford West Public School (4000)
Region : South Western Sydney
State Electorate : Fairfield
Local Government Area : Holroyd

Initial Survey : Noel Arnold & Associates : 28 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Aug - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Other-Community Use - 1964 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00G/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	

Interior

B00A - R0001 - Home Base

No Asbestos

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - Community Clinic

No Asbestos

B00A - R0004 - Movement

Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0007/Electrical Backing Board/S33				Chrysotile (white asbestos)	

B00A - R0005 - General Storeroom

No Asbestos

B00A - R0006 - Personal Effects Storage

No Asbestos

B00A - R0007 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1974 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00G/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4000/B00G/Underfloor Voids - Packing to Floor Joists/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Home Base Store

No Asbestos

B00B - R0003 - Staff Toilet

No Asbestos

B00B - R0004 - Home Base

No Asbestos

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Personal Effects Storage

No Asbestos

B00B - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00G/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4000/B00G/Underfloor Voids - Packing to Floor Joists/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00C - R0001 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00C/R0001/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Home Base

No Asbestos

B00C - R0004 - Movement

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00C/R0004/Electrical Backing Board/S35				Chrysotile (white asbestos)	

B00C - R0005 - Deputy Principal

No Asbestos

B00C - R0006 - Staff Toilet

No Asbestos

B00C - R0007 - General Storeroom

No Asbestos

B00C - R0008 - Personal Effects Storage

No Asbestos

B00C - R0009 - General Storeroom

No Asbestos

B00C - R0010 - Home Base

No Asbestos

B00C - R0011 - Home Base

No Asbestos

B00C - R0012 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00C/R0001/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - General Learning - 1956 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00G/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4000/B00G/Underfloor Voids - Packing to Floor Joists/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00D - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0002/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0002/In-fill-panel/S6				Chrysotile (white asbestos)	

B00D - R0002 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0002/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0002/In-fill-panel/S6				Chrysotile (white asbestos)	

B00D - R0003 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0003/Wall Linings Internal/S4				Chrysotile (white asbestos)	

B00D - R0004 - Cleaning Distributed Store

No Asbestos

B00D - R0005 - K.L.A. Store

No Asbestos

B00D - R0006 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0003/Wall Linings Internal/S4				Chrysotile (white asbestos)	

B00D - R0007 - Personal Effects Storage

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0007/Electrical Backing Board/S33				Chrysotile (white asbestos)	
Electrical Cupboard	Flat AC Sheeting	1m2	Infill Panels throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	4000/B00D/R0007/Electrical Cupboard/S34				Chrysotile (white asbestos)	

B00D - R0008 - Craft Store

No Asbestos

B00D - R0009 - Movement

No Asbestos

B00D - R0010 - Home Base

No Asbestos

B00D - R0011 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - R0012 - Personal Effects Storage

No Asbestos

B00D - R0013 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library/General Learning - 1964 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting 4000/B00G/Eaves Linings/S24	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting 4000/B00H/Gable Verge Lining/S26	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Gable Ends	Flat AC Sheeting 4000/B00G/Gable Ends/S25	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Movement

No Asbestos

B00F - R0003 - Staff Room Annexe

No Asbestos

B00F - R0004 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 4000/B00F/R0007/Wall Linings Internal/S10	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0005 - General Storeroom

No Asbestos

B00F - R0006 - Personal Effects Storage

No Asbestos

B00F - R0007 - K.L.A. Store

Wall Linings Internal	Flat AC Sheeting 4000/B00F/R0007/Wall Linings Internal/S10	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0008 - Reading Area

No Asbestos

B00F - R0009 - Reading Area

No Asbestos

B00F - R0010 - Library Office/Workroom

In-fill-panel	Flat AC Sheeting 4000/B00F/R0010/In-fill-panel/S9					No Asbestos Detected
---------------	--	--	--	--	--	-----------------------------

B00F - R0011 - Personal Effects Storage

No Asbestos

B00F - R0012 - Movement

No Asbestos

B00F - R0013 - External Movement

No Asbestos

B00F - R0014 - Special Programs Room

No Asbestos

B00F - R0015 - Home Base Store

No Asbestos

B00F - R0016 - Personal Effects Storage

No Asbestos

B00F - R0017 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00F - R0018 - External Movement

No Asbestos

B00F - R0020 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

4000/B00F/R0020/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	
---	--	--	--	--	------------------------------------	--

In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	----	----------------------	--------------------	---------	--------------------

4000/B00F/R0020/In-fill-panel/S8					Chrysotile (white asbestos)	
----------------------------------	--	--	--	--	------------------------------------	--

B00F - R0021 - Staff Room

No Asbestos

B00F - R0022 - Movement

No Asbestos

B00F - R0023 - Staff Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00G - Administration/General Learning - 1964 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting 4000/B00G/Eaves Linings/S24	80m2	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
Gable Verge Lining	Flat AC Sheeting 4000/B00H/Gable Verge Lining/S26	40m2	East, West	Good Condition (1) Chrysotile (white asbestos)	Low (1)	Low Priority (2-3)
Gable Ends	Flat AC Sheeting 4000/B00G/Gable Ends/S25	20m2	East, West	Good Condition (1) Chrysotile (white asbestos)	Low (1)	Low Priority (2-3)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting 4000/B00G/Underfloor Voids - Packing to Floor Joists/S27	1m2	Throughout	Some Damage - Unsealed (3) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Medium Priority (4-5)

Interior

B00G - R0001 - Principal

No Asbestos

B00G - R0002 - Interview

No Asbestos

B00G - R0003 - Entry Vestibule

No Asbestos

B00G - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 4000/B00D/R0002/Ceiling Structures/Linings/S5	5m2	Throughout	Good Condition (1) Chrysotile (white asbestos)	Low (1)	Low Priority (2-3)
In-fill-panel	Flat AC Sheeting 4000/B00D/R0002/In-fill-panel/S6	1m	South, Upper portion	Good Condition (1) Chrysotile (white asbestos)	Low (1)	Low Priority (2-3)

B00G - R0005 - Sick Bay

No Asbestos

B00G - R0006 - General Storeroom

No Asbestos

B00G - R0008 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 4000/B00G/R0010/Wall Linings Internal/S11	30m2	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
Ceiling Structures/Linings	Flat AC Sheeting 4000/B00G/R0010/Ceiling Structures/Linings/S12	4m2	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)

B00G - R0009 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 4000/B00G/R0010/Wall Linings Internal/S11	30m2	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
Ceiling Structures/Linings	Flat AC Sheeting 4000/B00G/R0010/Ceiling Structures/Linings/S12	5m2	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)

B00G - R0010 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 4000/B00G/R0010/Wall Linings Internal/S11	30m2	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
-----------------------	---	------	------------	---	---------	--------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4000/B00G/R0010/Ceiling Structures/Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)		

- B00G - R0011 - General Storeroom**
No Asbestos
- B00G - R0012 - Home Base**
No Asbestos
- B00G - R0013 - External Movement**
No Asbestos
- B00G - R0014 - Uniform Shop**
No Asbestos
- B00G - R0015 - Personal Effects Storage**
No Asbestos
- B00G - R0016 - Personal Effects Storage**
No Asbestos
- B00G - R0017 - Movement**
No Asbestos
- B00G - R0018 - Home Base Store**
No Asbestos
- B00G - R0019 - Home Base**
No Asbestos
- B00G - R0020 - Clerical Office**
No Asbestos
- B00G - R0021 - Clerical Office/Workroom**
No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	25m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00G/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/R0001/Ceiling Structures/Linings/S31				Chrysotile (white asbestos)	

B00H - R0002 - Interview/Office - Type 3

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/R0001/Ceiling Structures/Linings/S31				Chrysotile (white asbestos)	

B00H - R0003 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/R0001/Ceiling Structures/Linings/S31				Chrysotile (white asbestos)	

B00H - R0004 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/R0001/Ceiling Structures/Linings/S31				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities - 1968 - Brick/Veneer (Brick/Veneer)

Exterior

Wall Cladding	Flat AC Sheeting 4000/B001/Wall Cladding/S13					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B001 - R0001 - External Movement

No Asbestos

B001 - R0002 - Toilets - Girls

Wall Linings Internal	Flat AC Sheeting 4000/B001/R0002/Wall Linings Internal/S14					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B001/R0002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0003 - Toilets - Boys/Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services/Pupil Facilities - 1968 - Concrete (Concrete)

Exterior

Wall Cladding	Flat AC Sheeting	2m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00J/Wall Cladding/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00J - R0001 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B001/R0002/Ceiling Structures/Linings/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0002 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B001/R0002/Ceiling Structures/Linings/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0003 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B001/R0002/Ceiling Structures/Linings/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0004 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B001/R0002/Ceiling Structures/Linings/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0005 - Drinking Facilities

No Asbestos

B00J - R0006 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B001/R0002/Ceiling Structures/Linings/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1968 - Concrete (Concrete)

Exterior

Wall Cladding	Flat AC Sheeting 4000/B00K/Wall Cladding/S21	2m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00K - R0002 - Toilets - Girls

Wall Linings Internal	Flat AC Sheeting 4000/B00K/Wall Cladding/S21	4m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 4000/B00I/R0002/Ceiling Structures/Linings/S15	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 1956 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00G/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4000/B00L/Underfloor Voids - Packing to Floor Joists/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00L - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00M/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	1m	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00L/R0001/In-fill-panel/S17				Chrysotile (white asbestos)	

B00L - R0002 - Movement

No Asbestos

B00L - R0003 - Home Base

No Asbestos

B00L - R0004 - Deputy Principal

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 1964 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00G/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	12m2	West, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00M/In-fill-panel/S18				Chrysotile (white asbestos)	
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4000/B00G/Underfloor Voids - Packing to Floor Joists/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					

Interior

B00M - R0001 - External Movement

In-fill-panel	Flat AC Sheeting	14m	West, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00M/In-fill-panel/S18				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00M/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos)	

B00M - R0002 - Personal Effects Storage

No Asbestos

B00M - R0003 - Home Base Store

No Asbestos

B00M - R0004 - Home Base

No Asbestos

B00M - R0005 - Home Base

No Asbestos

B00M - R0006 - Home Base Store

No Asbestos

B00M - R0007 - Personal Effects Storage

No Asbestos

B00M - R0008 - Home Base Store

No Asbestos

B00M - R0009 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00N - Pupil Facilities - 1968 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting 4000/B00G/Eaves Linings/S24	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting 4000/B00H/Gable Verge Lining/S26	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Gable Ends	Flat AC Sheeting 4000/B00G/Gable Ends/S25	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting 4000/B00G/Underfloor Voids - Packing to Floor Joists/S27	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Packing between Brick & Block work	Flat AC Sheeting 4000/B00N/Packing between Brick & Block work/S30	30m	Throughout lower wall	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00N - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 4000/B00N/R0003/Ceiling Structures/Linings/S32	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00N - R0002 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 4000/B00N/R0003/Ceiling Structures/Linings/S32	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00N - R0003 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting 4000/B00N/R0003/Ceiling Structures/Linings/S32	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B000 - General Learning - 1964 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting 4000/B00G/Eaves Linings/S24	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting 4000/B00H/Gable Verge Lining/S26	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Gable Ends	Flat AC Sheeting 4000/B00G/Gable Ends/S25	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Underfloor Voids	AC Fragments/Debris 4000/B00O/Underfloor Voids/S28	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
				Chrysotile (white asbestos)		
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting 4000/B00G/Underfloor Voids - Packing to Floor Joists/S27	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B000 - R0001 - External Movement

No Asbestos

B000 - R0002 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 4000/B00O/R0002/Wall Linings Internal/S23	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B000 - R0003 - Movement

Wall Linings Internal	Flat AC Sheeting 4000/B00O/R0002/Wall Linings Internal/S23	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B000 - R0004 - Withdrawal Space - 1hb

No Asbestos

B000 - R0005 - Raised Platform

No Asbestos

B000 - R0006 - Communal Space

No Asbestos

B000 - R0007 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 4000/B00O/R0007/Ceiling Structures/Linings/S22	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B000 - R0008 - P.E. Store

No Asbestos

B000 - R0009 - External Movement

No Asbestos

B000 - R0010 - Home Base

No Asbestos

B000 - R0011 - Home Base Store

No Asbestos

B000 - R0012 - Personal Effects Storage

No Asbestos

B000 - R0013 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Communal Facilities - 1968 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00G/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00H/Gable Verge Lining/S26				Chrysotile (white asbestos)	
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4000/B00G/Underfloor Voids - Packing to Floor Joists/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					

Interior

B00P - R0001 - Home Base Store

No Asbestos

B00P - R0002 - Personal Effects Storage

No Asbestos

B00P - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0002/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	2m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0002/In-fill-panel/S6				Chrysotile (white asbestos)	

B00P - R0004 - Home Base

No Asbestos

B00P - R0005 - Home Base

No Asbestos

B00P - R0006 - Home Base Store

No Asbestos

B00P - R0007 - Movement

No Asbestos

B00P - R0008 - Personal Effects Storage

No Asbestos

B00P - R0009 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0002/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	2m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4000/B00D/R0002/In-fill-panel/S6				Chrysotile (white asbestos)	

B00P - R0010 - Home Base

No Asbestos

B00P - R0011 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00Q - R0001 - Communal Space

No Asbestos

B00Q - R0002 - Raised Platform

No Asbestos

B00Q - R0003 - Hall Chair Store

No Asbestos

B00Q - R0004 - Communal/Performance Store

No Asbestos

B00Q - R0005 - P.E. Store

No Asbestos

B00Q - R0006 - Toilet - Lobby

No Asbestos

B00Q - R0007 - Toilets - Girls

No Asbestos

B00Q - R0008 - Sound Cupboard

No Asbestos

B00Q - R0009 - Toilet - Lobby

No Asbestos

B00Q - R0010 - Toilets - Boys

No Asbestos

B00Q - R0011 - Cleaning Distributed Store

No Asbestos

B00Q - R0012 - Plant

No Asbestos

B00Q - R0013 - Main Switch Board

No Asbestos

B00Q - R0014 - Access Shower/Toilet

No Asbestos

B00Q - R0015 - Movement

No Asbestos

B00Q - R0016 - Movement

No Asbestos

B00Q - R0017 - Movement

No Asbestos

B00Q - R0018 - External Movement

No Asbestos

B00Q - R0019 - Covered Outdoor Learning Area

No Asbestos

B00Q - R0020 - Canteen

No Asbestos

B00Q - R0021 - Canteen Office/Store

No Asbestos

B00Q - R0022 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00R - R0001 - Toilets - Boys

No Asbestos

B00R - R0002 - Toilets - Girls

No Asbestos

B00R - R0003 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D13949 - Learning Unit - Standard With P.A.A. : Placement Date - 30/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14689 - Learning Unit - Standard With P.A.A. : Placement Date - 7/01/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 750 - D17703 - Learning Unit - ESL : Placement Date - 29/05/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017