

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Various - 1990 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00A - R0005 - Careers Advisers Office (13.83 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0006 - Cleaning Store - Distributed (3.75 m2)

No Asbestos

B00A - R0007 - Maintenance Bulk Store (6.12 m2)

No Asbestos

B00A - R0008 - General Assistants (13.09 m2)

No Asbestos

B00A - R0009 - Cleaning Supplies Store (13.05 m2)

No Asbestos

B00A - R0010 - Cleaning Supplies Store (17.13 m2)

No Asbestos

B00A - R0012 - Movement (17.87 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - Staff Study (28.51 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Darkroom Space (27.78 m2)

No Asbestos

B00A - R0015 - Distribution Board Cupboard (1.12 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting
8442/B00A/R0015/Ceiling Structures/Linings/S7

No Asbestos Detected

B00A - R0017 - Resources Store (15.06 m2)

No Asbestos

B00A - R0018 - General Storeroom (6.03 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0019 - Seminar (24.59 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0020 - Kiln Space (31.31 m2)

No Asbestos

B00A - R0021 - Resources Space (26.59 m2)

No Asbestos

B00A - R0022 - Art Learning Space (62.17 m2)

No Asbestos

B00A - R0023 - Maintenance Bulk Store (32.5 m2)

No Asbestos

B00A - R0029 - Stairs (14.76 m2)

No Asbestos

B00A - R0030 - Movement (5.31 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0031 - Toilet - Lobby (3.26 m2)						
No Asbestos						
B00A - R0032 - Staff - Toilet (2.47 m2)						
No Asbestos						
B00A - R0033 - External Movement (44.01 m2)						
No Asbestos						
B00A - R0034 - External Movement (66.13 m2)						
No Asbestos						
B00A - R1001 - Staff Study (22.43 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1002 - Security Store (15.44 m2)						
No Asbestos						
B00A - R1003 - Laboratory L.S. (92.45 m2)						
No Asbestos						
B00A - R1004 - Preparation (35.15 m2)						
No Asbestos						
B00A - R1005 - Chemical Store (12.59 m2)						
No Asbestos						
B00A - R1006 - Laboratory L.S. (94.14 m2)						
No Asbestos						
B00A - R1007 - Apparatus Store (25.13 m2)						
No Asbestos						
B00A - R1008 - Cleaning Store - Distributed (4.44 m2)						
No Asbestos						
B00A - R1009 - Distribution Board Cupboard (1.61 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1010 - Interview/Office - Type 1 (13.65 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1011 - External Movement (124.11 m2)						
No Asbestos						
B00A - R1012 - Stairs (21.91 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1968 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Interior**B00B - M0001 - Staff - Toilet (4.01 m2)**

No Asbestos

B00B - M0002 - Stairs (5.03 m2)

No Asbestos

B00B - M0003 - Movement (5.48 m2)

No Asbestos

B00B - M0004 - Stairs (3.74 m2)

No Asbestos

B00B - R0001 - Movement (103.19 m2)

Ceiling Structures/Linings	Vermiculite							
	8442/B00C/R0002/Ceiling Structures/Linings/S1							Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>							
Floor Coverings Res/Textile	Vinyl Tiles	103m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)		
	8442/B00B/R0001/Floor Coverings Res/Textile/S4							Chrysotile (white asbestos)

B00B - R0004 - External Movement (5.09 m2)

No Asbestos

B00B - R0005 - Seminar (29.16 m2)

Ceiling Structures/Linings	Vermiculite							
	8442/B00C/R0002/Ceiling Structures/Linings/S1							Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>							

B00B - R0006 - General Storeroom (7.28 m2)

Ceiling Structures/Linings	Vermiculite							
	8442/B00C/R0002/Ceiling Structures/Linings/S1							Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>							
Floor Coverings Res/Textile	Vinyl Tiles							
	8442/B00B/R0003/Floor Coverings Res/Textile/S3							No Asbestos Detected

B00B - R0009 - External Movement (5.52 m2)

No Asbestos

B00B - R0010 - General Learning Space (51.9 m2)

No Asbestos

B00B - R0011 - Science Laboratory (39.25 m2)

No Asbestos

B00B - R0012 - General Storeroom (0.51 m2)

No Asbestos

B00B - R0013 - Stairs (16.04 m2)

No Asbestos

B00B - R0014 - Stairs (0.38 m2)

No Asbestos

B00B - R0015 - Stairs (11.3 m2)

No Asbestos

B00B - R0016 - Computer Learning Space (78.49 m2)

Recently Modified Space Requires Inspection

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R1001 - Movement (79.73 m2)						
Ceiling Structures/Linings	Vermiculite		8442/B00C/R0002/Ceiling Structures/Linings/S1			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1002 - General Learning Space (52.11 m2)						
Ceiling Structures/Linings	Vermiculite		8442/B00C/R0002/Ceiling Structures/Linings/S1			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1003 - External Movement (5.33 m2)						
No Asbestos						
B00B - R1004 - General Learning Space (52.47 m2)						
Ceiling Structures/Linings	Vermiculite		8442/B00C/R0002/Ceiling Structures/Linings/S1			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1005 - External Movement (5.33 m2)						
No Asbestos						
B00B - R1006 - Computer Learning Space (52.92 m2)						
Ceiling Structures/Linings	Vermiculite		8442/B00C/R0002/Ceiling Structures/Linings/S1			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1007 - General Learning Space (51.75 m2)						
Ceiling Structures/Linings	Vermiculite		8442/B00C/R0002/Ceiling Structures/Linings/S1			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1008 - External Movement (5.33 m2)						
No Asbestos						
B00B - R1009 - External Movement (5.29 m2)						
No Asbestos						
B00B - R1010 - Stairs (15.79 m2)						
No Asbestos						
B00B - R1011 - Stairs (1.54 m2)						
No Asbestos						
B00B - R1012 - General Storeroom (0.49 m2)						
No Asbestos						
B00B - R9001 - General Storeroom (105.23 m2)						
No Asbestos						
B00B - R9002 - General Storeroom (1.34 m2)						
No Asbestos						
B00B - R9003 - Dust Extraction Space (10.27 m2)						
No Asbestos						
B00B - R9005 - Materials Store (26.02 m2)						
Ceiling Structures/Linings	Vermiculite		8442/B00C/R0002/Ceiling Structures/Linings/S1			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R9006 - Staff Study (25.14 m2)						
Ceiling Structures/Linings	Vermiculite		8442/B00C/R0002/Ceiling Structures/Linings/S1			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R9008 - Movement (10.77 m2)						
Ceiling Structures/Linings	Vermiculite		8442/B00C/R0002/Ceiling Structures/Linings/S1			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R9011 - Stairs (10.95 m2)						
No Asbestos						
B00B - R9012 - General Storeroom (0.51 m2)						
No Asbestos						
B00B - R9013 - Plant (0.28 m2)						
No Asbestos						
B00B - R9014 - General Storeroom (0.49 m2)						
No Asbestos						
B00B - R9015 - Wood Technology Bay (113.33 m2)						
No Asbestos						
B00B - R9016 - Movement (20.35 m2)						
No Asbestos						
B00B - R9017 - Movement (26.43 m2)						
No Asbestos						
B00B - R9018 - External Movement (12.21 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Technological - 1968 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8442/B00C/Eaves Linings/S2	200m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids	AC Fragments/Debris 8442/B00C/Underfloor Voids/S9	100m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00C - R0001 - External Movement (2.03 m2)**

No Asbestos

B00C - R0002 - Movement (44.07 m2)

Ceiling Structures/Linings	Vermiculite 8442/B00C/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0003 - Security Store (20.47 m2)

Ceiling Structures/Linings	Vermiculite 8442/B00C/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0004 - Resource/Project Store (4.59 m2)

Ceiling Structures/Linings	Vermiculite 8442/B00C/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0005 - Design L.S. (66.4 m2)

Ceiling Structures/Linings	Vermiculite 8442/B00C/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0006 - Laundry (7.94 m2)

Ceiling Structures/Linings	Vermiculite 8442/B00C/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0007 - Resource/Project Store (14.04 m2)

Ceiling Structures/Linings	Vermiculite 8442/B00C/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0008 - External Movement (1.21 m2)

No Asbestos

B00C - R0009 - Stairs (4.08 m2)

No Asbestos

B00C - R0010 - General Storeroom (5.07 m2)

No Asbestos

B00C - R1001 - General Learning Space (52.63 m2)

No Asbestos

B00C - R1002 - General Learning Space (52.92 m2)

No Asbestos

B00C - R1003 - Staff Study (26.28 m2)

No Asbestos

B00C - R1004 - Tiered Learning Area (52.54 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R1005 - Tiered Learning Store (1.85 m2)						
No Asbestos						
B00C - R1006 - Distribution Board Cupboard (0.87 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R1007 - Movement (93.2 m2)						
No Asbestos						
B00C - R1008 - Cleaning Store - Distributed (2.65 m2)						
No Asbestos						
B00C - R1009 - Entry (31.34 m2)						
No Asbestos						
B00C - R1010 - Seminar (13.04 m2)						
No Asbestos						
B00C - R1011 - Seminar (13.04 m2)						
No Asbestos						
B00C - R1012 - Main Area (178.71 m2)						
No Asbestos						
B00C - R1013 - Audio Visual Workroom (17.76 m2)						
No Asbestos						
B00C - R1014 - Workroom (21.16 m2)						
No Asbestos						
B00C - R1015 - Librarian (11.76 m2)						
No Asbestos						
B00C - R1016 - Interview/Office - Type 1 (11.82 m2)						
No Asbestos						
B00C - R1017 - Computer Resource (11.87 m2)						
No Asbestos						
B00C - R1018 - Computer Store (9.31 m2)						
No Asbestos						
B00C - R1019 - Computer Learning Space (69.15 m2)						
No Asbestos						
B00C - R1020 - General Learning Space (45.35 m2)						
No Asbestos						
B00C - R1021 - Toilets-Disabled (6.99 m2)						
No Asbestos						
B00C - R1022 - Distribution Board Cupboard (1.89 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R1024 - Staff Study (22.33 m2)						
No Asbestos						
B00C - R1025 - Entry (3.14 m2)						
No Asbestos						
B00C - R1026 - Staff - Toilet (4.83 m2)						
No Asbestos						
B00C - R1027 - Cleaning Store - Distributed (2.49 m2)						
No Asbestos						
B00C - R1032 - Plant (8.68 m2)						
No Asbestos						
B00C - R1034 - Stairs (14.57 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R1035 - Senior Study (48.59 m2)						
No Asbestos						
B00C - R1036 - Movement (12.03 m2)						
No Asbestos						
B00C - R1037 - External Movement (7.7 m2)						
No Asbestos						
B00C - R1038 - Distribution Board Cupboard (0.34 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00C - R1039 - Other (2.07 m2)						
No Asbestos						
B00C - R1040 - Other (2.28 m2)						
No Asbestos						
B00C - R1041 - Food Technology L.S. (104 m2)						
No Asbestos						
B00C - R1042 - Pantry (11.41 m2)						
No Asbestos						
B00C - R1043 - Laundry (0.75 m2)						
No Asbestos						
B00C - R1044 - Preparation - Materials (16.02 m2)						
No Asbestos						
B00C - R1045 - Other (13.74 m2)						
No Asbestos						
B00C - R1046 - Movement (25.77 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration - 1990 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00C/Eaves Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					

Interior

B00D - R0001 - Music Store (17.71 m2)

No Asbestos

B00D - R0002 - Distribution Board Cupboard (0.3 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0003 - Music Learning Space (88.24 m2)

No Asbestos

B00D - R0004 - Practice/Seminar (26.5 m2)

No Asbestos

B00D - R0005 - Resources (15.02 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00E - Pupil Facilities - 1968 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	80m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00C/Eaves Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00E - R0001 - Toilets-Boys (27.57 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00E/R0004/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0002 - Movement (68.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	69m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00E/R0004/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0003 - Cleaning Store - Distributed (5.64 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00E/R0004/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0004 - Toilets-Girls (31.84 m2)

Ceiling Structures/Linings	Flat AC Sheeting	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00E/R0004/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0005 - General Storeroom (12.18 m2)

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00E/R0004/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0006 - Staff - Toilet (4.41 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00E/R0004/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0007 - Pantry (3.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00E/R0004/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0008 - Student Canteen (28.43 m2)

Floor Coverings Res/Textile	Vinyl Tiles	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8442/B00B/R0001/Floor Coverings Res/Textile/S4			Chrysotile (white asbestos)		

B00E - R0009 - External Movement (8.51 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Music - 1968 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior**B00F - R0001 - Clinic - Boys (15.89 m2)**

No Asbestos

B00F - R0002 - External Movement (4.02 m2)

No Asbestos

B00F - R0003 - Deputy Principal Office (16.42 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0004 - Interview/Office - Type 1 (12.74 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Movement (59.35 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Distribution Board Cupboard (1.23 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0007 - Seminar (13.28 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Principal Office (19.63 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - Cleaning Store - Distributed (2.36 m2)

No Asbestos

B00F - R0010 - Security Store (16.36 m2)

No Asbestos

B00F - R0011 - Duplicating Workroom (18.98 m2)

No Asbestos

B00F - R0012 - Administration - Clerical (23.13 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0013 - Clinic - Girls (14.23 m2)

No Asbestos

B00F - R0014 - Clinic-Toilets (3.42 m2)

No Asbestos

B00F - R0015 - Clinic-Toilets (3.42 m2)

No Asbestos

B00F - R0016 - External Movement (21.92 m2)

No Asbestos

B00F - R1001 - External Movement (18.94 m2)

No Asbestos

B00F - R1002 - Duplicating Workroom (13.47 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1003 - Commonroom (84.96 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1004 - Staff - Toilet (5.23 m2)

No Asbestos

B00F - R1005 - Staff Shower (7.29 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Shed - 1968 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior**B00G - R0001 - General Storeroom (5.8 m2)**

No Asbestos

B00G - R0002 - Staff - Toilet (2.34 m2)

No Asbestos

B00G - R0003 - Class Tools Storage (12.55 m2)

No Asbestos

B00G - R0004 - Machine Storage (20.97 m2)

No Asbestos

B00G - R0005 - External Movement (21.99 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Multi Purpose Facilities - 1992 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00H - R0001 - Chair Store (49.13 m2)**

No Asbestos

B00H - R0002 - Toilets-Disabled (4.02 m2)

No Asbestos

B00H - R0003 - Distribution Board Cupboard (3 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0004 - Toilets-Boys (20.79 m2)

No Asbestos

B00H - R0005 - Shower/Change (29.75 m2)

No Asbestos

B00H - R0006 - Chair Store (39.96 m2)

No Asbestos

B00H - R0008 - Shower/Change (29.82 m2)

No Asbestos

B00H - R0009 - Toilets-Girls (20.68 m2)

No Asbestos

B00H - R0010 - Cleaning Store - Distributed (3.13 m2)

No Asbestos

B00H - R0011 - Staff Kitchen (13.82 m2)

No Asbestos

B00H - R0012 - Staff Shower (5.62 m2)

No Asbestos

B00H - R0013 - Staff Study (11.61 m2)

No Asbestos

B00H - R0014 - Sport Equipment Store (20.71 m2)

No Asbestos

B00H - R0015 - Multi-Purpose Space (455.43 m2)

No Asbestos

B00H - R0017 - Stage (63.58 m2)

No Asbestos

B00H - R0018 - External Movement (229.44 m2)

No Asbestos

B00H - R0019 - Movement (5.95 m2)

No Asbestos

B00H - R0020 - Movement (17.98 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0A1 - Technological & Applied Studies - 1990 - Brick/Block (Brick/Block)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B0A1 - R0001 - Welding Area (13.75 m2)**

No Asbestos

B0A1 - R0002 - Welding Store (3.52 m2)

No Asbestos

B0A1 - R0003 - General Storeroom (1.8 m2)

No Asbestos

B0A1 - R0004 - External Movement (27.59 m2)

No Asbestos

B0A1 - R0024 - Distribution Board Cupboard (1.04 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0A1 - R0025 - Materials Store (11.9 m2)

No Asbestos

B0A1 - R0026 - Metal Technology Bay (26.43 m2)

No Asbestos

B0A1 - R0027 - Metal Technology Bay (93.49 m2)

No Asbestos

B0A1 - R0028 - Metal Technology Bay (62.53 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D14652 - Learning Unit - Standard/Withdrawal : Placement Date - 23/12/2009

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017