


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kalinda School (5699)  
**Region :** Riverina  
**State Electorate :** Murray  
**Local Government Area :** Griffith

**Initial Survey :** Noel Arnold & Associates : 13 - May - 2008  
**Register Issue Date :** 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Shed - 1981 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00A - R0001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Building Services - 2008 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00B - R0001 - Garage/Carport**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00C - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)

#### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

#### Interior

##### B00C - R0001 - Kitchen - Pre

No Asbestos

##### B00C - R0002 - General Storeroom

No Asbestos

##### B00C - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

##### B00C - R0004 - Special Programs Room

No Asbestos

##### B00C - R0005 - Communal Space

No Asbestos

##### B00C - R0006 - Toilets - Girls

No Asbestos

##### B00C - R0007 - Toilets - Boys

No Asbestos

##### B00C - R0008 - Sports Store

No Asbestos

##### B00C - R0009 - General Assistant/Bulk Store

No Asbestos

##### B00C - R0010 - P.E. Store

No Asbestos

##### B00C - R0011 - Cleaning Distributed Store

No Asbestos

##### B00C - R0012 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00D - R0001 - Home Base Store - P**

No Asbestos

**B00D - R0002 - Home Base - P**

No Asbestos

**B00D - R0003 - Practical Activities - P - 2hb**

No Asbestos

**B00D - R0004 - Access Shower/Toilet/Change**

No Asbestos

**B00D - R0005 - Plant**

No Asbestos

**B00D - R0006 - Laundry - P**

No Asbestos

**B00D - R0007 - Access Shower/Toilet/Change**

No Asbestos

**B00D - R0008 - Home Base - P**

No Asbestos

**B00D - R0009 - Home Base Store - P**

No Asbestos

**B00D - R0010 - Cleaning Distributed Store**

No Asbestos

**B00D - R0011 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0012 - Cleaning Supplies**

No Asbestos

**B00D - R0013 - Garden Store**

No Asbestos

**B00D - R0014 - External Movement**

No Asbestos

**B00D - R0015 - No Access**

No Asbestos

**B00D - R0016 - No Access**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00E - R0001 - Access Shower/Toilet/Change**

No Asbestos

**B00E - R0002 - Plant**

No Asbestos

**B00E - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0004 - General Storeroom**

No Asbestos

**B00E - R0005 - Hydrotherapy - Pool**

No Asbestos

**B00E - R0006 - Movement**

No Asbestos

**B00E - R0007 - Movement**

No Asbestos

**B00E - R0008 - Staff Room Annexe**

No Asbestos

**B00E - R0009 - Access Shower/Toilet/Change**

No Asbestos

**B00E - R0010 - Access Shower/Toilet/Change**

No Asbestos

**B00E - R0011 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Administration - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00F - R0001 - Staff Room Annexe**

No Asbestos

**B00F - R0002 - Staff Room**

No Asbestos

**B00F - R0003 - Interview**

No Asbestos

**B00F - R0004 - Security Store**

No Asbestos

**B00F - R0005 - Principal**

No Asbestos

**B00F - R0006 - Interview**

No Asbestos

**B00F - R0007 - Entry Vestibule**

No Asbestos

**B00F - R0008 - Clerical Office**

No Asbestos

**B00F - R0009 - Sick Bay**

No Asbestos

**B00F - R0010 - Disabled Shower/Toilet**

No Asbestos

**B00F - R0011 - Cleaning Distributed Store**

No Asbestos

**B00F - R0012 - Staff Toilet**

No Asbestos

**B00F - R0013 - Staff Toilet**

No Asbestos

**B00F - R0014 - Movement**

No Asbestos

**B00F - R0015 - External Movement**

No Asbestos

**B00F - R0016 - External Movement**

No Asbestos

**B00F - R0017 - External Movement**

No Asbestos

**B00F - R0018 - Distribution Board**

No Asbestos

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00G - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00G - R0001 - Home Base - M**

No Asbestos

**B00G - R0002 - Home Base Store - M**

No Asbestos

**B00G - R0003 - Practical Activities - M - 2hb**

No Asbestos

**B00G - R0004 - Access Shower/Toilet/Change**

No Asbestos

**B00G - R0005 - Plant**

No Asbestos

**B00G - R0006 - Laundry - P**

No Asbestos

**B00G - R0007 - Access Shower/Toilet/Change**

No Asbestos

**B00G - R0008 - Home Base - M**

No Asbestos

**B00G - R0009 - Home Base Store - M**

No Asbestos

**B00G - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0011 - Home Base - M**

No Asbestos

**B00G - R0012 - Home Base Store - M**

No Asbestos

**B00G - R0013 - Practical Activities - M - 2hb**

No Asbestos

**B00G - R0014 - Access Shower/Toilet/Change**

No Asbestos

**B00G - R0015 - Laundry - P**

No Asbestos

**B00G - R0016 - Plant**

No Asbestos

**B00G - R0017 - Access Shower/Toilet/Change**

No Asbestos

**B00G - R0018 - Home Base - M**

No Asbestos

**B00G - R0019 - Home Base Store - M**

No Asbestos

**B00G - R0020 - Main Switch Board**

No Asbestos

**B00G - R0021 - Cleaning Distributed Store**

No Asbestos

**B00G - R0022 - Access Shower/Toilet/Change**

No Asbestos

**B00G - R0023 - K.L.A. Store**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00G - R0024 - Reading Area**

No Asbestos

**B00G - R0025 - Communications Room**

No Asbestos

**B00G - R0026 - Library Office/Workroom**

No Asbestos

**B00G - R0027 - General Storeroom**

No Asbestos

**B00G - R0028 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017