


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kariong Mountains High School (8292)
Region : Hunter/Central Coast
State Electorate : Gosford
Local Government Area : Gosford

Initial Survey : :
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Technological & Applied Studies - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior

B00A - R0001 - Visual Arts Workshop

No Asbestos

B00A - R0002 - General Learning Space

No Asbestos

B00A - R0003 - Project Store - Type 1

No Asbestos

B00A - R0004 - Visual Arts Store

No Asbestos

B00A - R0005 - Project Store - Type 1

No Asbestos

B00A - R0006 - General Learning Space

No Asbestos

B00A - R0007 - General Learning Space

No Asbestos

B00A - R0008 - Bulk Store

No Asbestos

B00A - R0009 - Materials Store

No Asbestos

B00A - R0010 - Dust Extraction Space

No Asbestos

B00A - R0011 - Materials Workshop - Type 2

No Asbestos

B00A - R0012 - Materials Store

No Asbestos

B00A - R0013 - Visual Arts Workshop

No Asbestos

B00A - R0014 - Dark Room

No Asbestos

B00A - R0015 - Cleaning Store - Distributed

No Asbestos

B00A - R0016 - Outdoor Workshop

No Asbestos

B00A - R0017 - L.P.G. Store

No Asbestos

B00A - R0018 - Welding/Hot Metals Area

No Asbestos

B00A - R0019 - Pottery Store

No Asbestos

B00A - R0020 - Kiln Space

No Asbestos

B00A - R0021 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0022 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0023 - External Movement						
No Asbestos						
B00A - R0024 - Welding Area						
No Asbestos						
B00A - R0025 - Welding Area						
No Asbestos						
B00A - R0026 - Welding Area						
No Asbestos						
B00A - R0027 - Darkroom Space						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Administration/General Learning - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior**B00B - R0001 - Deputy Principal Office**

No Asbestos

B00B - R0002 - Deputy Principal Office

No Asbestos

B00B - R0003 - Administration - Executive

No Asbestos

B00B - R0005 - Administration - Clerical

No Asbestos

B00B - R0006 - Principal Office

No Asbestos

B00B - R0007 - Store

No Asbestos

B00B - R0008 - Staff - Toilet

No Asbestos

B00B - R0009 - Staff - Toilet

No Asbestos

B00B - R0010 - Visitors Office

No Asbestos

B00B - R0011 - Interview/Meeting

No Asbestos

B00B - R0012 - Interview/Meeting

No Asbestos

B00B - R0013 - Administration - Clerical

No Asbestos

B00B - R0014 - Cleaning Store - Distributed

No Asbestos

B00B - R0015 - Tea Room

No Asbestos

B00B - R0016 - Interview/Meeting

No Asbestos

B00B - R0017 - Clinic - Girls

No Asbestos

B00B - R0018 - Toilets-Disabled

No Asbestos

B00B - R0019 - Clinic - Boys

No Asbestos

B00B - R0020 - Interview/Office - Type 1

No Asbestos

B00B - R0021 - Movement

No Asbestos

B00B - R0022 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0024 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0025 - External Movement						
No Asbestos						
B00B - R0026 - External Stairs						
No Asbestos						
B00B - R1001 - General Learning Space						
No Asbestos						
B00B - R1002 - General Learning Space						
No Asbestos						
B00B - R1003 - Seminar						
No Asbestos						
B00B - R1004 - Cleaning Store - Distributed						
No Asbestos						
B00B - R1006 - Laundry						
No Asbestos						
B00B - R1007 - Pantry						
No Asbestos						
B00B - R1008 - Preparation						
No Asbestos						
B00B - R1009 - Materials Store						
No Asbestos						
B00B - R1010 - Materials Workshop - Type 2						
No Asbestos						
B00B - R1011 - Distribution Board Cupboard						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1012 - Movement						
No Asbestos						
B00B - R1013 - External Movement						
No Asbestos						
B00B - R1014 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior**B00C - R0001 - General Learning Space**

No Asbestos

B00C - R0002 - General Learning Space

No Asbestos

B00C - R0003 - General Learning Space

No Asbestos

B00C - R0004 - Toilets-Boys

No Asbestos

B00C - R0005 - Toilets-Girls

No Asbestos

B00C - R0006 - General Learning Space

No Asbestos

B00C - R0007 - General Learning Space

No Asbestos

B00C - R0008 - Cleaning Store - Distributed

No Asbestos

B00C - R0010 - G.L.S. Store

No Asbestos

B00C - R0011 - Practical Activities

No Asbestos

B00C - R0012 - Shared Learning Space

No Asbestos

B00C - R0013 - General Learning Space

No Asbestos

B00C - R0014 - General Learning Space

No Asbestos

B00C - R0015 - Shared Learning Space

No Asbestos

B00C - R0016 - Seminar

No Asbestos

B00C - R0017 - G.L.S. Store

No Asbestos

B00C - R0018 - Practical Activities

No Asbestos

B00C - R0019 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0020 - Movement

No Asbestos

B00C - R0022 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0023 - Plant

No Asbestos

B00C - R0024 - Access Student Shower/Toilet/Change

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0026 - Laundry						
No Asbestos						
B00C - R0027 - External Movement						
No Asbestos						
B00C - R0028 - External Stairs						
No Asbestos						
B00C - R0029 - External Stairs						
No Asbestos						
B00C - R1001 - General Learning Space						
No Asbestos						
B00C - R1002 - General Learning Space						
No Asbestos						
B00C - R1003 - General Learning Space						
No Asbestos						
B00C - R1004 - General Learning Space						
No Asbestos						
B00C - R1005 - General Learning Space						
No Asbestos						
B00C - R1006 - General Learning Space						
No Asbestos						
B00C - R1007 - Cleaning Store - Distributed						
No Asbestos						
B00C - R1008 - G.L.S. Store						
No Asbestos						
B00C - R1009 - Seminar						
No Asbestos						
B00C - R1010 - Practical Activities						
No Asbestos						
B00C - R1011 - Shared Learning Space						
No Asbestos						
B00C - R1012 - General Learning Space						
No Asbestos						
B00C - R1013 - General Learning Space						
No Asbestos						
B00C - R1014 - Shared Learning Space						
No Asbestos						
B00C - R1015 - Seminar						
No Asbestos						
B00C - R1016 - G.L.S. Store						
No Asbestos						
B00C - R1017 - Practical Activities						
No Asbestos						
B00C - R1018 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R1019 - Movement						
No Asbestos						
B00C - R1020 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R1021 - External Movement						
No Asbestos						
B00C - R1022 - External Stairs						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R1023 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00D - Library/Staff Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior**B00D - R0001 - Main Area**

No Asbestos

B00D - R0002 - Seminar

No Asbestos

B00D - R0003 - Seminar

No Asbestos

B00D - R0004 - Careers Advisers Office

No Asbestos

B00D - R0005 - Lift

No Asbestos

B00D - R0006 - Main Entry

No Asbestos

B00D - R0007 - Toilets-Disabled

No Asbestos

B00D - R0008 - Staff - Toilet

No Asbestos

B00D - R0009 - Library Administration

No Asbestos

B00D - R0010 - System Administrators Office

No Asbestos

B00D - R0011 - Communications Cupboard

No Asbestos

B00D - R0012 - Computer Store

No Asbestos

B00D - R0013 - Computer Learning Space

No Asbestos

B00D - R0014 - Senior Study

No Asbestos

B00D - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0016 - External Movement

No Asbestos

B00D - R0017 - External Movement

No Asbestos

B00D - R0018 - External Stairs

No Asbestos

B00D - R1001 - Archive Store

No Asbestos

B00D - R1002 - Staff - Toilet

No Asbestos

B00D - R1003 - Staff - Toilet

No Asbestos

B00D - R1004 - Cleaning Store - Distributed

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1005 - Staff - Toilet						
No Asbestos						
B00D - R1006 - Access Staff Shower/Toilet						
No Asbestos						
B00D - R1007 - Preparation/Printing						
No Asbestos						
B00D - R1008 - Interview/Meeting						
No Asbestos						
B00D - R1009 - Interview/Meeting						
No Asbestos						
B00D - R1010 - Movement						
No Asbestos						
B00D - R1011 - Staff Study						
No Asbestos						
B00D - R1012 - Staff Kitchen						
No Asbestos						
B00D - R1013 - Staff Study						
No Asbestos						
B00D - R1014 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00D - R1015 - Commonroom						
No Asbestos						
B00D - R1016 - External Movement						
No Asbestos						
B00D - R1017 - External Stairs						
No Asbestos						
B00D - R1018 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - Science/Performing Arts - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior**B00E - R0001 - General Learning Space**

No Asbestos

B00E - R0002 - General Learning Space

No Asbestos

B00E - R0003 - Chemical Store

No Asbestos

B00E - R0004 - Chemical Store

No Asbestos

B00E - R0005 - Pantry

No Asbestos

B00E - R0006 - Apparatus Storage

No Asbestos

B00E - R0007 - General Learning Space

No Asbestos

B00E - R0008 - General Learning Space

No Asbestos

B00E - R0009 - External Stairs

No Asbestos

B00E - R0010 - Student Shower

No Asbestos

B00E - R0011 - Student Shower

No Asbestos

B00E - R0012 - External Movement

No Asbestos

B00E - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0014 - Cleaning Store - Distributed

No Asbestos

B00E - R0015 - Science Laboratory

No Asbestos

B00E - R0016 - Preparation

No Asbestos

B00E - R0017 - Plant Growing Space

No Asbestos

B00E - R0018 - Plant Growing Space

No Asbestos

B00E - R0019 - External Movement

No Asbestos

B00E - R0020 - External Stairs

No Asbestos

B00E - R0030 - Toilets-Disabled

No Asbestos

B00E - R0031 - Science Laboratory

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R1001 - General Learning Space						
No Asbestos						
B00E - R1002 - General Learning Space						
No Asbestos						
B00E - R1003 - Change						
No Asbestos						
B00E - R1004 - Change						
No Asbestos						
B00E - R1005 - General Learning Space						
No Asbestos						
B00E - R1006 - General Learning Space						
No Asbestos						
B00E - R1007 - Seminar - Type 1						
No Asbestos						
B00E - R1008 - Cleaning Store - Distributed						
No Asbestos						
B00E - R1009 - External Movement						
No Asbestos						
B00E - R1010 - Fitness Store						
No Asbestos						
B00E - R1011 - External Stairs						
No Asbestos						
B00E - R1012 - Fitness Laboratory						
No Asbestos						
B00E - R1013 - Performance Store						
No Asbestos						
B00E - R1014 - Practice/Seminar						
No Asbestos						
B00E - R1015 - Performance Workshop						
No Asbestos						
B00E - R1016 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1017 - Seminar - Type 1						
No Asbestos						
B00E - R1018 - Multi Media Studio						
No Asbestos						
B00E - R1019 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - Physical Education/Building Services - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior**B00F - R0001 - Gymnasium**

No Asbestos

B00F - R0002 - Plant

No Asbestos

B00F - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0004 - Sport Equipment Store

No Asbestos

B00F - R0005 - Cleaning Store - Distributed

No Asbestos

B00F - R0006 - Chair Store

No Asbestos

B00F - R0007 - Control Room

No Asbestos

B00F - R0008 - Sport Equipment Store

No Asbestos

B00F - R0009 - First Aid

No Asbestos

B00F - R0010 - Movement Studio

No Asbestos

B00F - R0011 - Toilets-Disabled

No Asbestos

B00F - R0012 - Staff Shower

No Asbestos

B00F - R0013 - Toilet - Lobby

No Asbestos

B00F - R0014 - Movement Studio Store

No Asbestos

B00F - R0015 - Outdoor Equipment Store

No Asbestos

B00F - R0016 - Garden Store Room

No Asbestos

B00F - R0017 - Staff - Toilet

No Asbestos

B00F - R0018 - Other - Site Manager

No Asbestos

B00F - R0019 - Stage

No Asbestos

B00F - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0E1 - Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior

B0E1 - R0001 - Office/Store

No Asbestos

B0E1 - R0002 - Student Canteen

No Asbestos

B0E1 - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0E1 - R0004 - General Storeroom

No Asbestos

B0E1 - R0005 - Covered Outdoor Space

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0E2 - Pupil Facilities - 2010 - Brick/Block (Brick/Block)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior

B0E2 - R0001 - Toilets-Girls

No Asbestos

B0E2 - R0002 - Toilets-Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0E3 - Agricultural Science - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior

B0E3 - R0001 - Botany/Zoology

No Asbestos

B0E3 - R0002 - Seminar

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D11644 - Learning Unit - Standard/Withdrawal : Placement Date - 19/01/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D12518 - Learning Unit - Standard/Withdrawal : Placement Date - 19/01/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017