


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Lake Munmorah Public School (2362)  
**Region :** Hunter/Central Coast  
**State Electorate :** Swansea  
**Local Government Area :** Wyong

**Initial Survey :** Noel Arnold & Associates : 29 - Mar - 2008  
**Reviewed By :** AECOM : 28 - Jun - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00A - Communal Facilities/Pupil Facilities - 1994 - Brick/Veneer (Brick/Veneer)

#### Exterior

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground, no access points.

Ceiling Voids      No Asbestos Found

#### Interior

##### B00A - R0001 - Movement

No Asbestos

##### B00A - R0002 - Cleaning Supplies

No Asbestos

##### B00A - R0003 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

##### B00A - R0004 - Movement

No Asbestos

##### B00A - R0005 - Canteen Office/Store

No Asbestos

##### B00A - R0006 - Canteen

No Asbestos

##### B00A - R0007 - External Movement

No Asbestos

##### B00A - R0008 - Sports Store

No Asbestos

##### B00A - R0009 - Communal Space

No Asbestos

##### B00A - R0010 - Plant

No Asbestos

##### B00A - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

##### B00A - R0012 - Toilets - Girls

No Asbestos

##### B00A - R0013 - Communal Space

No Asbestos

##### B00A - R0014 - Shower/Change

No Asbestos

##### B00A - R0015 - Toilets - Boys

No Asbestos

##### B00A - R0016 - Hall Chair Store

No Asbestos

##### B00A - R0017 - P.E. Store

No Asbestos

##### B00A - R0018 - Plant

No Asbestos

##### B00A - R0019 - Cleaning Distributed Store

No Asbestos

##### B00A - R0020 - Disabled Toilet

No Asbestos

##### B00A - R0021 - Cleaning Supplies

No Asbestos

##### B00A - R0022 - General Assistant/Bulk Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground, no access points.

Ceiling Voids      No Asbestos Found

**Interior**

**B00B - R0001 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0002 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0003 - Duplicating Workroom**

No Asbestos

**B00B - R0004 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0005 - General Storeroom**

No Asbestos

**B00B - R0006 - Cleaning Distributed Store**

No Asbestos

**B00B - R0007 - Staff Toilet**

No Asbestos

**B00B - R0008 - Staff Toilet**

No Asbestos

**B00B - R0009 - Staff Toilet**

No Asbestos

**B00B - R0010 - Main Switch Board**

No Asbestos

**B00B - R0011 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0012 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0013 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0014 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0015 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0016 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0017 - Sick Bay - Shower/Toilet**

No Asbestos

**B00B - R0018 - Sick Bay - Shower/Toilet**

No Asbestos

**B00B - R0019 - Sick Bay**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - R0020 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Pupil Facilities - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground, no access points.
Ceiling Voids	No Asbestos Found

**Interior**

**B00C - R0001 - External Movement**

No Asbestos

**B00C - R0002 - Toilets - Girls**

No Asbestos

**B00C - R0003 - Kiln Room**

No Asbestos

**B00C - R0004 - Toilets - Boys**

No Asbestos

**B00C - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0006 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0008 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0009 - Practical Activities - 1hb**

No Asbestos

**B00C - R0010 - Practical Activities - 1hb**

No Asbestos

**B00C - R0011 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0012 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0013 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground, no access points.
Ceiling Voids	No Asbestos Found

**Interior**

**B00D - R0001 - Distribution Board** Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0002 - External Movement**

No Asbestos

**B00D - R0003 - Practical Activities - 1hb**

No Asbestos

**B00D - R0004 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0005 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0008 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0009 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0010 - Practical Activities - 1hb**

No Asbestos

**B00D - R0011 - Practical Activities - 1hb**

No Asbestos

**B00D - R0012 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0013 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0015 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0016 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0017 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)    No Asbestos Found

**B00D - R0018 - Practical Activities - 1hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

<b>B00D - R0019 - Distribution Board</b>	Note: No inspection of live electrical installation.					
--	--	--	--	--	--	--

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Tiered Learning - 1994 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground, no access points.

Ceiling Voids      No Asbestos Found

**Interior****B00E - R0001 - External Movement**

No Asbestos

**B00E - R0002 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0003 - Cleaning Distributed Store**

No Asbestos

**B00E - R0004 - Special Programs Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0005 - Plant**

No Asbestos

**B00E - R0006 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0008 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0009 - Practical Activities - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0011 - Practical Activities - 1hb**

No Asbestos

**B00E - R0012 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0013 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0014 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0015 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0016 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0017 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0018 - Practical Activities - 1hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R0019 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00E - R0020 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00E - R0021 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00E - R0022 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00E - R0023 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning/Pupil Facilities - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground, no access points.
Ceiling Voids	No Asbestos Found

**Interior**

**B00F - R0001 - External Movement**

No Asbestos

**B00F - R0002 - Toilets - Boys**

No Asbestos

**B00F - R0003 - Disabled Toilet**

No Asbestos

**B00F - R0004 - Toilets - Girls**

No Asbestos

**B00F - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0006 - Practical Activities - 1hb**

No Asbestos

**B00F - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0008 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0010 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0011 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0012 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0013 - Practical Activities - 1hb**

No Asbestos

**B00F - R0014 - Practical Activities - 1hb**

No Asbestos

**B00F - R0015 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0016 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0017 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0018 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0019 - Withdrawal Space - 1hb**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0020 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0021 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00F - R0022 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Library - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground, no access points.
Ceiling Voids	No Asbestos Found

**Interior**

**B00G - R0002 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0003 - Communications Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0004 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0005 - Resource/Toy Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0006 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning/Support Unit - 1922 - Timber (Timber)**

**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction, 3.10m.					
Eaves Linings	Flat AC Sheeting 2362/B00H/Awnings/S1	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Awnings	Flat AC Sheeting 2362/B00H/Awnings/S1	16m2	Over North and South Entrance	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Underfloor Voids	Compressed AC Sheet 2362/B00H/Underfloor Voids/S2					<b>No Asbestos Detected</b>

**Interior**

**B00H - R0001 - Staff Kitchen**

No Asbestos

**B00H - R0002 - Home Base**

No Asbestos

**B00H - R0003 - Home Base**

No Asbestos

**B00H - R0004 - Toilet - E**

No Asbestos

**B00H - R0005 - Personal Effects - E**

No Asbestos

**B00H - R0006 - Home Base Store - E**

No Asbestos

**B00H - R0007 - Home Base Store - E**

No Asbestos

**B00H - R0008 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 2005 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground, no access points.

Ceiling Voids      No Asbestos Found

**Interior**

**B00J - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Building Services - 2005 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground, shed, no access points.

Ceiling Voids      No Asbestos Found

**Interior**

**B00K - R0001 - General Assistant/Bulk Store**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

### B00L - General Learning/Building Services - 2010 - Brick/Veneer (Brick/Veneer)

#### Exterior

Underfloor Voids - Slab on Ground      Non Accessible Area  
- Area inaccessible, slab to ground, no access points.

Ceiling Voids      No Asbestos Found

#### Interior

##### B00L - R0001 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

##### B00L - R0002 - General Assistant/Bulk Store

No Asbestos

##### B00L - R0003 - Sports Store

No Asbestos

##### B00L - R0004 - Practical Activities - 1hb

No Asbestos

##### B00L - R0005 - Personal Effects Storage

No Asbestos

##### B00L - R0006 - Home Base

No Asbestos

##### B00L - R0007 - Home Base Store

No Asbestos

##### B00L - R0008 - Withdrawal Space - 1hb

No Asbestos

##### B00L - R0009 - Practical Activities - 1hb

No Asbestos

##### B00L - R0010 - Personal Effects Storage

No Asbestos

##### B00L - R0011 - Home Base

No Asbestos

##### B00L - R0012 - Home Base Store

No Asbestos

##### B00L - R0013 - Withdrawal Space - 2hb

No Asbestos

##### B00L - R0014 - Practical Activities - 1hb

No Asbestos

##### B00L - R0015 - Personal Effects Storage

No Asbestos

##### B00L - R0016 - Home Base

No Asbestos

##### B00L - R0017 - Home Base Store

No Asbestos

##### B00L - R0018 - Garden Store

No Asbestos

##### B00L - R0019 - General Storeroom

No Asbestos

##### B00L - R0020 - General Storeroom

No Asbestos

##### B00L - R0021 - External Movement

No Asbestos

##### B00L - R0022 - External Stairs

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00L - R0023 - External Stairs</b>						
No Asbestos						
<b>B00L - R1001 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00L - R1002 - Personal Effects Storage</b>						
No Asbestos						
<b>B00L - R1003 - Home Base</b>						
No Asbestos						
<b>B00L - R1004 - Home Base Store</b>						
No Asbestos						
<b>B00L - R1005 - Withdrawal Space - 2hb</b>						
No Asbestos						
<b>B00L - R1006 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00L - R1007 - Personal Effects Storage</b>						
No Asbestos						
<b>B00L - R1008 - Home Base</b>						
No Asbestos						
<b>B00L - R1009 - Home Base Store</b>						
No Asbestos						
<b>B00L - R1010 - Distribution Board</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00L - R1011 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00L - R1012 - Personal Effects Storage</b>						
No Asbestos						
<b>B00L - R1013 - Home Base Store</b>						
No Asbestos						
<b>B00L - R1014 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00L - R1015 - Home Base</b>						
No Asbestos						
<b>B00L - R1016 - External Movement</b>						
No Asbestos						
<b>B00L - R1017 - External Stairs</b>						
No Asbestos						
<b>B00L - R1018 - External Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017