

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Llandilo Public School (2413)  
**Region :** Western Sydney  
**State Electorate :** Londonderry  
**Local Government Area :** Penrith

**Initial Survey :** Noel Arnold & Associates : 22 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 14 - May - 2015



# 2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00A - General Learning/Building Services - 1989 - Brick/Block (Brick/Block)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00A - R0001 - Withdrawal Space - 1hb**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0002 - Home Base Store**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0003 - Cleaning Distributed Store**

No Asbestos

**B00A - R0004 - Practical Activities - 1hb**

No Asbestos

**B00A - R0005 - Home Base**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0006 - Home Base**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0007 - Practical Activities - 1hb**

No Asbestos

**B00A - R0008 - Home Base Store**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0009 - Home Base Store**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0010 - Withdrawal Space - 1hb**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0011 - Home Base**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0012 - Practical Activities - 1hb**

No Asbestos

**B00A - R0013 - Practical Activities - 1hb**

No Asbestos

**B00A - R0014 - Home Base**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0015 - Withdrawal Space - 1hb**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0016 - Home Base Store**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00A - R0017 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0018 - Personal Effects Storage**

No Asbestos

**B00A - R0019 - Personal Effects Storage**

No Asbestos

| Product  | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|--|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No                                      |                      |        |                    |                    | Test Result |                  |
| <b>B00A - R0020 - Personal Effects Storage</b> |                      |        |                    |                    |             |                  |
| No Asbestos                                    |                      |        |                    |                    |             |                  |
| <b>B00A - R0021 - Movement</b>                 |                      |        |                    |                    |             |                  |
| No Asbestos                                    |                      |        |                    |                    |             |                  |
| <b>B00A - R0022 - Movement</b>                 |                      |        |                    |                    |             |                  |
| No Asbestos                                    |                      |        |                    |                    |             |                  |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00B - General Learning/Library - 1989 - Brick/Block (Brick/Block)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00B - R0001 - Practical Activities - 1hb**

No Asbestos

**B00B - R0002 - Home Base**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0003 - Withdrawal Space - 1hb**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0004 - Home Base Store**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0005 - Home Base Store**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0006 - Practical Activities - 1hb**

No Asbestos

**B00B - R0007 - Home Base**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0008 - Kiln Room**

No Asbestos

**B00B - R0009 - Main Switch Board**

|                            |  |                             |
|----------------------------|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2413/B00B/R0009/Ceiling Structures/Linings/S27 | <b>No Asbestos Detected</b> |
|----------------------------|--|-----------------------------|

**B00B - R0010 - Reading Area**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0011 - Library Office/Workroom**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0012 - Library Office/Workroom**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0013 - Special Programs Room**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0014 - Special Programs Store**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00B - R0015 - Plant**

No Asbestos

**B00B - R0016 - Movement**

No Asbestos

**B00B - R0017 - Personal Effects Storage**

No Asbestos

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00C - Pupil Facilities - 1982 - Brick/Block (Brick/Block)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00C - R0001 - Canteen**

No Asbestos

**B00C - R0002 - Canteen Office/Store**

No Asbestos

**B00C - R0003 - Canteen Office/Store**

No Asbestos

**B00C - R0004 - Staff Toilet**

No Asbestos

**B00C - R0005 - Canteen Office/Store**

No Asbestos

**B00C - R0006 - Movement**

No Asbestos

**B00C - R0007 - Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00D - Administration - 1983 - Brick/Block (Brick/Block)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00D - R0001 - Staff Room Annexe**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0002 - Staff Room**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0003 - Staff Toilet**

No Asbestos

**B00D - R0004 - Movement**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0005 - Security Store**

No Asbestos

**B00D - R0006 - Principal**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0007 - Clerical Office**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0008 - Entry Vestibule**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0009 - Interview**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0010 - Duplicating Workroom**

No Asbestos

**B00D - R0011 - Deputy Principal**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0012 - Sick Bay**

No Asbestos

**B00D - R0013 - Staff Shower/Change**

No Asbestos

**B00D - R0014 - Deputy Principal**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00D - R0015 - Cleaning Distributed Store**

No Asbestos

**B00D - R0016 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0017 - Staff Toilet**

No Asbestos

**B00D - R0018 - Movement**

No Asbestos

**B00D - R0019 - Movement**

No Asbestos

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00E - Communal Facilities/Administration - 1989 - Brick/Block (Brick/Block)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00E - R0001 - Movement**

|                            |  |                      |
|----------------------------|--|----------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2413/B00E/R0026/Ceiling Structures/Linings/S17 | No Asbestos Detected |
|----------------------------|--|----------------------|

**B00E - R0002 - Shower/Change**

No Asbestos

**B00E - R0003 - Communal/Performance Store**

|                            |  |                      |
|----------------------------|--|----------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2413/B00E/R0026/Ceiling Structures/Linings/S17 | No Asbestos Detected |
|----------------------------|--|----------------------|

**B00E - R0004 - Communal Space**

No Asbestos

**B00E - R0005 - Disabled Toilet**

No Asbestos

**B00E - R0006 - Staff Toilet**

|                            |  |                      |
|----------------------------|--|----------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2413/B00E/R0026/Ceiling Structures/Linings/S17 | No Asbestos Detected |
|----------------------------|--|----------------------|

**B00E - R0007 - Community Clinic**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00E - R0008 - Community Clinic**

|   |                   |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

**B00E - R0009 - Plant**

No Asbestos

**B00E - R0010 - Hall Chair Store**

No Asbestos

**B00E - R0011 - P.E. Store**

No Asbestos

**B00E - R0012 - General Assistant/Bulk Store**

No Asbestos

**B00E - R0013 - Cleaning Supplies**

No Asbestos

**B00E - R0014 - Staff Room Annexe**

No Asbestos

**B00E - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

|                            |  |                      |
|----------------------------|--|----------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2413/B00E/R0026/Ceiling Structures/Linings/S17 | No Asbestos Detected |
|----------------------------|--|----------------------|

**B00E - R0016 - Movement**

No Asbestos

**B00E - R0017 - Movement**

No Asbestos

**B00E - R0018 - Cleaning Distributed Store**

|                            |  |                      |
|----------------------------|--|----------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2413/B00E/R0026/Ceiling Structures/Linings/S17 | No Asbestos Detected |
|----------------------------|--|----------------------|

**B00E - R0019 - Shower/Change**

No Asbestos

**B00E - R0020 - Movement**

| Product                               | Material Description                           | Extent | Location Reference | Material Condition | Risk Status | Control Priority     |
|---------------------------------------|--|--------|--------------------|--------------------|-------------|----------------------|
| Sample No                             |  |        |                    |                    | Test Result |                      |
| Ceiling Structures/Linings            | Flat AC Sheeting                               |        |                    |                    |             |                      |
|                                       | 2413/B00E/R0026/Ceiling Structures/Linings/S17 |        |                    |                    |             | No Asbestos Detected |
| <b>B00E - R0021 - Garden Store</b>    |  |        |                    |                    |             |                      |
| Ceiling Structures/Linings            | Flat AC Sheeting                               |        |                    |                    |             |                      |
|                                       | 2413/B00E/R0026/Ceiling Structures/Linings/S17 |        |                    |                    |             | No Asbestos Detected |
| <b>B00E - R0022 - Toilets - Boys</b>  |  |        |                    |                    |             |                      |
| Ceiling Structures/Linings            | Flat AC Sheeting                               |        |                    |                    |             |                      |
|                                       | 2413/B00E/R0026/Ceiling Structures/Linings/S17 |        |                    |                    |             | No Asbestos Detected |
| <b>B00E - R0023 - Movement</b>        |  |        |                    |                    |             |                      |
| Ceiling Structures/Linings            | Flat AC Sheeting                               |        |                    |                    |             |                      |
|                                       | 2413/B00E/R0026/Ceiling Structures/Linings/S17 |        |                    |                    |             | No Asbestos Detected |
| <b>B00E - R0024 - Sports Store</b>    |  |        |                    |                    |             |                      |
| Ceiling Structures/Linings            | Flat AC Sheeting                               |        |                    |                    |             |                      |
|                                       | 2413/B00E/R0026/Ceiling Structures/Linings/S17 |        |                    |                    |             | No Asbestos Detected |
| <b>B00E - R0025 - Toilets - Girls</b> |  |        |                    |                    |             |                      |
| Ceiling Structures/Linings            | Flat AC Sheeting                               |        |                    |                    |             |                      |
|                                       | 2413/B00E/R0026/Ceiling Structures/Linings/S17 |        |                    |                    |             | No Asbestos Detected |
| <b>B00E - R0026 - Movement</b>        |  |        |                    |                    |             |                      |
| Ceiling Structures/Linings            | Flat AC Sheeting                               |        |                    |                    |             |                      |
|                                       | 2413/B00E/R0026/Ceiling Structures/Linings/S17 |        |                    |                    |             | No Asbestos Detected |
| <b>B00E - R0027 - Raised Platform</b> |  |        |                    |                    |             |                      |
| No Asbestos                           |  |        |                    |                    |             |                      |
| <b>B00E - R0028 - Movement</b>        |  |        |                    |                    |             |                      |
| No Asbestos                           |  |        |                    |                    |             |                      |
| <b>B00E - R0029 - Movement</b>        |  |        |                    |                    |             |                      |
| No Asbestos                           |  |        |                    |                    |             |                      |
| <b>B00E - R0030 - Movement</b>        |  |        |                    |                    |             |                      |
| No Asbestos                           |  |        |                    |                    |             |                      |
| <b>B00E - R0031 - Ramp</b>            |  |        |                    |                    |             |                      |
| No Asbestos                           |  |        |                    |                    |             |                      |

2017



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00F - Museum - 1913 - Timber (Timber)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00F - R0001 - Museum**

No Asbestos

**B00F - R0002 - Museum**

|   |   |      |            |                    |                                    |                    |
|---|---|------|------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile                     | Vinyl Tiles (Under Floor Covering/Carpet) | 23m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2413/B00F/R0002/Floor Coverings Res/Textile/S23 |   |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00F - R0003 - Museum**

|   |   |     |            |                    |                                    |                    |
|---|---|-----|------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile                     | Vinyl Tiles (Under Floor Covering/Carpet) | 8m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2413/B00F/R0002/Floor Coverings Res/Textile/S23 |   |     |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00G - General Learning/Staff Facilities - 1959 - Timber (Timber)**

**Exterior**

|                  |   |  |  |  |  |                             |
|------------------|---|--|--|--|--|-----------------------------|
| Wall Cladding    | Flat AC Sheeting<br>2413/B00G/Wall Cladding/S16 |  |  |  |  | <b>No Asbestos Detected</b> |
| Ceiling Voids    | No Asbestos Found                               |  |  |  |  |                             |
| Underfloor Voids | No Asbestos Found                               |  |  |  |  |                             |

**Interior**

**B00G - R0001 - Personal Effects Storage**

|                            |  |      |             |                    |         |   |
|----------------------------|--|------|-------------|--------------------|---------|---|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2413/B00G/R0001/Ceiling Structures/Linings/S18 | 16m2 | Throughout  | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                            |  |      |             |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |
| Wall Linings Internal      | Flat AC Sheeting<br>2413/B00G/R0001/Ceiling Structures/Linings/S18 | 8m2  | East & West | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                            |  |      |             |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |

**B00G - R0002 - Home Base**

|                             |  |  |  |  |  |                             |
|-----------------------------|--|--|--|--|--|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles<br>2413/B00G/R0003/Floor Coverings Res/Textile/S25 |  |  |  |  | <b>No Asbestos Detected</b> |
|-----------------------------|--|--|--|--|--|-----------------------------|

**B00G - R0003 - Home Base Store**

|                             |  |  |  |  |  |                             |
|-----------------------------|--|--|--|--|--|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles<br>2413/B00G/R0003/Floor Coverings Res/Textile/S25 |  |  |  |  | <b>No Asbestos Detected</b> |
|-----------------------------|--|--|--|--|--|-----------------------------|

**B00G - R0004 - Staff Room Annexe**

|                             |  |  |  |  |  |                             |
|-----------------------------|--|--|--|--|--|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles (Under Floor Covering/Carpet)<br>2413/B00G/R0005/Floor Coverings Res/Textile/S24 |  |  |  |  | <b>No Asbestos Detected</b> |
|-----------------------------|--|--|--|--|--|-----------------------------|

**B00G - R0005 - General Storeroom**

|                             |  |      |             |                    |         |   |
|-----------------------------|--|------|-------------|--------------------|---------|---|
| Ceiling Structures/Linings  | Flat AC Sheeting<br>2413/B00G/R0001/Ceiling Structures/Linings/S18                           | 7m2  | Throughout  | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                             |  |      |             |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |
| Floor Coverings Res/Textile | Vinyl Tiles (Under Floor Covering/Carpet)<br>2413/B00G/R0005/Floor Coverings Res/Textile/S24 |      |             |                    |         | <b>No Asbestos Detected</b>                                   |
| Wall Linings Internal       | Flat AC Sheeting<br>2413/B00G/R0001/Ceiling Structures/Linings/S18                           | 24m2 | East & West | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                             |  |      |             |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00H - General Learning/Pupil Facilities - 1964 - Brick/Block (Brick/Block)**

**Exterior**

|                    |                                  |      |                    |                    |   |                    |
|--------------------|----------------------------------|------|--------------------|--------------------|---|--------------------|
| Eaves Linings      | Flat AC Sheeting                 | 60m2 | Throughout         | Good Condition (1) | Low (1)   | Low Priority (2-3) |
|                    | 2413/B00H/Eaves Linings/S14      |      |                    |                    | <b>Chrysotile (white asbestos)</b>                            |                    |
| Gable Verge Lining | Flat AC Sheeting                 | 10m2 | Variable positions | Minimal Damage (2) | Low (1)   | Low Priority (2-3) |
|                    | 2413/B00H/Gable Verge Lining/S15 |      |                    |                    | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |                    |
| Ceiling Voids      | No Asbestos Found                |      |                    |                    |   |                    |
| Underfloor Voids   | No Asbestos Found                |      |                    |                    |   |                    |

**Interior**

**B00H - R0001 - Practical Activities - 1hb**

No Asbestos

**B00H - R0002 - Home Base**

No Asbestos

**B00H - R0003 - Movement**

No Asbestos

**B00H - R0004 - Personal Effects Storage**

No Asbestos

**B00H - R0005 - Toilets - Boys**

|                            |  |     |            |                    |                                    |                             |
|----------------------------|--|-----|------------|--------------------|------------------------------------|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                               |     |            |                    |                                    | <b>No Asbestos Detected</b> |
|                            | 2413/B00H/R0007/Ceiling Structures/Linings/S19 |     |            |                    |                                    |                             |
| Partition Walls (Cubicles) | Compressed AC Sheet                            | 8m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3)          |
|                            | 2413/B00H/R0006/Partition Walls (Cubicles)/S22 |     |            |                    | <b>Chrysotile (white asbestos)</b> |                             |

**B00H - R0006 - Toilets - Girls**

|                            |  |      |            |                    |                                    |                             |
|----------------------------|--|------|------------|--------------------|------------------------------------|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                               |      |            |                    |                                    | <b>No Asbestos Detected</b> |
|                            | 2413/B00H/R0007/Ceiling Structures/Linings/S19 |      |            |                    |                                    |                             |
| Partition Walls (Cubicles) | Compressed AC Sheet                            | 12m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3)          |
|                            | 2413/B00H/R0006/Partition Walls (Cubicles)/S22 |      |            |                    | <b>Chrysotile (white asbestos)</b> |                             |

**B00H - R0007 - Movement**

|                            |  |  |  |  |  |                             |
|----------------------------|--|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                               |  |  |  |  | <b>No Asbestos Detected</b> |
|                            | 2413/B00H/R0007/Ceiling Structures/Linings/S19 |  |  |  |  |                             |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00J - General Learning/Pupil Facilities - 1972 - Brick/Block (Brick/Block)**

**Exterior**

|                    |                                  |      |             |                    |   |                    |
|--------------------|----------------------------------|------|-------------|--------------------|---|--------------------|
| Eaves Linings      | Flat AC Sheeting                 | 80m2 | Throughout  | Good Condition (1) | Low (1)   | Low Priority (2-3) |
|                    | 2413/B00J/Eaves Linings/S12      |      |             |                    | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |                    |
| In-fill-panel      | Flat AC Sheeting                 | 9m2  | South       | Good Condition (1) | Low (1)   | Low Priority (2-3) |
|                    | 2413/B00J/In-fill-panel/S2       |      |             |                    | <b>Chrysotile (white asbestos)</b>                            |                    |
| Gable Verge Lining | Flat AC Sheeting                 | 10m2 | East & West | Minimal Damage (2) | Low (1)   | Low Priority (2-3) |
|                    | 2413/B00J/Gable Verge Lining/S13 |      |             |                    | <b>Chrysotile (white asbestos)</b>                            |                    |
| Ceiling Voids      | No Asbestos Found                |      |             |                    |   |                    |
| Underfloor Voids   | No Asbestos Found                |      |             |                    |   |                    |

**Interior**

**B00J - R0001 - Cleaning Distributed Store**

No Asbestos

**B00J - R0002 - Cleaning Distributed Store**

No Asbestos

**B00J - R0003 - Staff Toilet**

No Asbestos

**B00J - R0004 - Toilets - Boys**

No Asbestos

**B00J - R0005 - Movement**

|                            |  |      |       |                    |                                    |                    |
|----------------------------|--|------|-------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                               | 40m2 | North | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
|                            | 2413/B00J/R0017/Ceiling Structures/Linings/S20 |      |       |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00J - R0006 - Movement**

No Asbestos

**B00J - R0007 - General Storeroom**

No Asbestos

**B00J - R0008 - Movement**

No Asbestos

**B00J - R0009 - Toilets - Girls**

No Asbestos

**B00J - R0010 - Staff Toilet**

No Asbestos

**B00J - R0011 - Main Switch Board**

No Asbestos

**B00J - R0012 - Practical Activities - 1hb**

|                             |   |      |            |                    |                                    |                    |
|-----------------------------|---|------|------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile | Vinyl Tiles                                     | 17m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
|                             | 2413/B00J/R0016/Floor Coverings Res/Textile/S26 |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00J - R0013 - Toilets - Boys/Girls**

No Asbestos

**B00J - R0014 - Home Base**

|                             |   |      |            |                    |                                    |                    |
|-----------------------------|---|------|------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile | Vinyl Tiles                                     | 84m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
|                             | 2413/B00J/R0016/Floor Coverings Res/Textile/S26 |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00J - R0015 - Home Base**

|                             |   |      |            |                    |                                    |                    |
|-----------------------------|---|------|------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile | Vinyl Tiles                                     | 53m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
|                             | 2413/B00J/R0016/Floor Coverings Res/Textile/S26 |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00J - R0016 - Practical Activities - 1hb**

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status                        | Control Priority   |
|---|----------------------|--------|--------------------|--------------------|------------------------------------|--------------------|
| Sample No                                       |                      |        |                    |                    | Test Result                        |                    |
| Floor Coverings Res/Textile                     | Vinyl Tiles          | 21m2   | Throughout         | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2413/B00J/R0016/Floor Coverings Res/Textile/S26 |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00J - R0017 - Movement</b>                  |                      |        |                    |                    |                                    |                    |
| Ceiling Structures/Linings                      | Flat AC Sheeting     | 41m2   | Throughout         | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2413/B00J/R0017/Ceiling Structures/Linings/S20  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| In-fill-panel                                   | Flat AC Sheeting     | 9m     | North              | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2413/B00J/R0017/In-fill-panel/S21               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00J - R0018 - Movement</b>                  |                      |        |                    |                    |                                    |                    |
| No Asbestos                                     |                      |        |                    |                    |                                    |                    |
| <b>B00J - R0019 - Stairs</b>                    |                      |        |                    |                    |                                    |                    |
| Ceiling Structures/Linings                      | Flat AC Sheeting     | 3m2    | Throughout         | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2413/B00J/R0017/Ceiling Structures/Linings/S20  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00K - General Learning/Support Unit (M P S) - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00K - R0001 - External Movement**

No Asbestos

**B00K - R0002 - Practical Activities - 1hb**

No Asbestos

**B00K - R0003 - Home Base Store**

No Asbestos

**B00K - R0004 - Home Base**

No Asbestos

**B00K - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00K - R0006 - Home Base**

No Asbestos

**B00K - R0007 - Home Base Store**

No Asbestos

**B00K - R0008 - Practical Activities - 1hb**

No Asbestos

**B00K - R0009 - Special Programs Room**

No Asbestos

**B00K - R0010 - Special Programs Store**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D10202 - Learning Unit - Standard With P.A.A. : Placement Date - 8/10/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D13118 - Learning Unit - Standard With P.A.A. : Placement Date - 29/01/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017