


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Peakhurst Public School (2849)
Region : Sydney
State Electorate : Oatley
Local Government Area : Hurstville

Initial Survey : Noel Arnold & Associates : 15 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Aug - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1926 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	250m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00A/Eaves Linings/S9					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	30m2	Central Wall	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00A/R0002/Wall Linings Internal/S5					Chrysotile (white asbestos)

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - Security Store

No Asbestos

B00A - R0005 - Staff Toilet

No Asbestos

B00A - R0006 - Communal Space

No Asbestos

B00A - R0007 - Raised Platform

No Asbestos

B00A - R0008 - Staff Room Annexe

No Asbestos

B00A - R0009 - Cleaning Distributed Store

No Asbestos

B00A - R0010 - Principal

No Asbestos

B00A - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00A/R0011/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Clerical Office/Workroom

No Asbestos

B00A - R0014 - Home Base

No Asbestos

B00A - R0015 - Home Base

No Asbestos

B00A - R0016 - Home Base

No Asbestos

B00A - R0017 - General Storeroom

No Asbestos

B00A - R0018 - External Movement

No Asbestos

B00A - R0019 - Stairs

No Asbestos

B00A - R0020 - Stairs

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1001 - Staff Room Annexe						
No Asbestos						
B00A - R1003 - Interview						
No Asbestos						
B00A - R1004 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00A/R1002/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
B00A - R1005 - Special Programs Room						
No Asbestos						
B00A - R1006 - Home Base						
No Asbestos						
B00A - R1007 - Home Base						
No Asbestos						
B00A - R1008 - Home Base						
No Asbestos						
B00A - R1009 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00A/R1002/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
B00A - R1010 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00A/R0011/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00A - R1011 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00A/R0011/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00A - R1012 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2849/B00A/R1013/Floor Coverings Res/Textile/S19					Chrysotile (white asbestos)	
B00A - R1013 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	81m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2849/B00A/R1013/Floor Coverings Res/Textile/S19					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1928 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0002 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0004 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Plant

No Asbestos

B00B - R0009 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00B - R0010 - Cleaning Distributed Store

No Asbestos

B00B - R0011 - External Movement

No Asbestos

B00B - R0012 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Communal Facilities - 1950 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	100m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/Eaves Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	2849/B00C/Underfloor Voids - Packing to Floor Joists/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior**B00C - R0001 - Outdoor Learning Area**

No Asbestos

B00C - R0002 - Home Base

In-fill Panel Below Window Compressed AC Sheet

2849/B00C/R0002/In-fill Panel Below Window/S2

No Asbestos Detected**B00C - R0003 - Home Base**

No Asbestos

B00C - R0004 - External Movement

Ceiling Structures/Linings Flat AC Sheeting 2m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)

2849/B00C/R0017/Ceiling Structures/Linings/S17

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**B00C - R0005 - External Movement**

No Asbestos

B00C - R0006 - Movement

No Asbestos

B00C - R0007 - External Movement

No Asbestos

B00C - R0008 - Movement

No Asbestos

B00C - R0009 - Home Base

No Asbestos

B00C - R0010 - Home Base - M

No Asbestos

B00C - R0011 - External Movement

Ceiling Structures/Linings Flat AC Sheeting 2m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)

2849/B00C/R0017/Ceiling Structures/Linings/S17

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**B00C - R0012 - General Storeroom**

No Asbestos

B00C - R0013 - Home Base

No Asbestos

B00C - R0014 - Home Base

No Asbestos

B00C - R0015 - Home Base

No Asbestos

B00C - R0016 - Withdrawal Space - 2hb

No Asbestos

B00C - R0017 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)

2849/B00C/R0017/Ceiling Structures/Linings/S17

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00C - R0018 - Home Base

No Asbestos

B00C - R0019 - External Movement

No Asbestos

B00C - R0020 - Home Base

No Asbestos

B00C - R0021 - Security Store

No Asbestos

B00C - R0022 - Staff Toilet

No Asbestos

B00C - R0023 - Withdrawal Space - 1hb

No Asbestos

B00C - R0024 - Cleaning Distributed Store

No Asbestos

B00C - R0025 - Security Store

No Asbestos

B00C - R0026 - Main Switch Board

No Asbestos

B00C - R0027 - Communal Space

No Asbestos

B00C - R0028 - Raised Platform

No Asbestos

B00C - R0029 - General Storeroom

No Asbestos

B00C - R0030 - Interview

No Asbestos

B00C - R0031 - Personal Effects Storage

No Asbestos

B00C - R0032 - Staff Toilet

Partition Walls (Cubicles) Compressed AC Sheet
2849/B00C/R0032/Partition Walls (Cubicles)/S1 **No Asbestos Detected**

B00C - R0033 - General Storeroom

No Asbestos

B00C - R0034 - External Movement

No Asbestos

B00C - R0035 - Stairs

No Asbestos

B00C - R9001 - General Assistant/Bulk Store

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - Pupil Facilities - 1950 - Brick/Block (Brick/Block)						
Exterior						
Eaves Linings	Flat AC Sheeting	100m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/Eaves Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Interior						
B00D - R0002 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0003 - Handwashing Facilities						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0004 - Handwashing Facilities						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0006 - Cleaning Supplies						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0007 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	116m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0008 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0009 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0010 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0011 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0012 - Canteen						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0013 - Canteen Office/Store						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00D/R0014/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00D - R0014 - Toilets - Boys						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00D/R0014/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
2849/B00H/R0005/Partition Walls (Cubicles)/S18						
B00D - R0015 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00D/R0014/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00D - R0016 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00D/R0014/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
2849/B00H/R0005/Partition Walls (Cubicles)/S18						
B00D - R0017 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2849/B00D/R0014/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities - 1928 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	2849/B00E/Underfloor Voids - Packing to Floor Joists/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00E - R0001 - External Movement

Floor Coverings Res/Textile	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00E/R0001/Floor Coverings Res/Textile/S4			Chrysotile (white asbestos)		

B00E - R0002 - Sports Store

No Asbestos

B00E - R0003 - Craft Store

No Asbestos

B00E - R0004 - Home Base

Wall Linings Internal	Flat AC Sheeting	200m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00E/R0004/Wall Linings Internal/S3			Chrysotile (white asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Other-Non-Govt Pre-School - 1928 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 2849/B00F/Eaves Linings/S11					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0001 - Other-Non Government Pre-Sch

No Asbestos

B00F - R0002 - Other-Non Government Pre-Sch

No Asbestos

B00F - R0003 - Other-Non Government Pre-Sch

No Asbestos

B00F - R0004 - Other-Non Government Pre-Sch

Wall Linings Internal	Flat AC Sheeting	150m2	South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00F/R0004/Wall Linings Internal/S7					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0005 - Other-Non Government Pre-Sch

Wall Linings Internal	Flat AC Sheeting 2849/B00F/R0007/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00F - R0006 - Other-Non Government Pre-Sch

Wall Linings Internal	Flat AC Sheeting 2849/B00F/R0007/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00F - R0007 - Other-Non Government Pre-Sch

Wall Linings Internal	Flat AC Sheeting 2849/B00F/R0007/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00F - R0008 - Other-Non Government Pre-Sch

No Asbestos

B00F - R0009 - Other-Non Government Pre-Sch

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Staff Facilities - 1928 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00G/Eaves Linings/S12					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	30m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00G/Gable Verge Lining/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Staff Toilet

No Asbestos

B00G - R0003 - Movement

No Asbestos

B00G - R0004 - Cleaning Distributed Store

No Asbestos

B00G - R0005 - Staff Room

No Asbestos

B00G - R0006 - Staff Room

No Asbestos

B00G - R0007 - External Movement

No Asbestos

B00G - R0008 - Movement

No Asbestos

B00G - R0009 - Personal Effects Storage

No Asbestos

B00G - R0010 - Personal Effects Storage

No Asbestos

B00G - R0011 - General Storeroom

No Asbestos

B00G - R0012 - Home Base Store

No Asbestos

B00G - R0013 - Home Base

No Asbestos

B00G - R0014 - Practical Activities - 1hb

No Asbestos

B00G - R0015 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1949 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00H - R0005 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 2849/B00H/R0005/Partition Walls (Cubicles)/S18	No Asbestos Detected
----------------------------	---	-----------------------------

B00H - R0006 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 2849/B00H/R0005/Partition Walls (Cubicles)/S18	No Asbestos Detected
----------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Other-Non-Govt Pre-School - 1980 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00I - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities - 1928 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00J - R0001 - Drinking Facilities

No Asbestos

B00J - R0002 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 1950 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/Eaves Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00L - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00L - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2849/B00D/R0014/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00M - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - Communal Space

No Asbestos

B00M - R0002 - Raised Platform

No Asbestos

B00M - R0003 - Movement

No Asbestos

B00M - R0004 - Movement

No Asbestos

B00M - R0005 - Movement

No Asbestos

B00M - R0006 - Hall Chair Store

No Asbestos

B00M - R0007 - Communal/Performance Store

No Asbestos

B00M - R0008 - P.E. Store

No Asbestos

B00M - R0009 - Toilet - Lobby

No Asbestos

B00M - R0010 - Toilets - Girls

No Asbestos

B00M - R0011 - Sound Cupboard

No Asbestos

B00M - R0012 - Toilet - Lobby

No Asbestos

B00M - R0013 - Toilets - Boys

No Asbestos

B00M - R0014 - Cleaning Distributed Store

No Asbestos

B00M - R0015 - Plant

No Asbestos

B00M - R0016 - Disabled Shower/Toilet

No Asbestos

B00M - R0017 - Main Switch Board

No Asbestos

B00M - R0018 - Plant

No Asbestos

B00M - R0019 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11085 - Learning Unit - Standard With P.A.A. : Placement Date - 7/08/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11296 - Learning Unit - Standard With P.A.A. : Placement Date - 21/01/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D15729 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 10/01/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15926 - Learning Unit - Standard With P.A.A. : Placement Date - 2/03/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15972 - Learning Unit - Standard With P.A.A. : Placement Date - 8/01/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D16290 - Learning Unit - Standard With P.A.A. : Placement Date - 13/01/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D17946 - Learning Unit - Standard With P.A.A. : Placement Date - 8/01/2007

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

2849_ASB_150514_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017