


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Portland Central School (2897)
Region : Western NSW
State Electorate : Bathurst
Local Government Area : Lithgow

Initial Survey : Noel Arnold & Associates : 27 - May - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1985 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00A - R0001 - General Assistant/Bulk Store

No Asbestos

B00A - R0002 - General Assistant/Bulk Store

No Asbestos

B00A - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - General Assistant/Bulk Store

No Asbestos

B00A - R0007 - Withdrawal Space - 1hb

No Asbestos

B00A - R0008 - Withdrawal Space - 1hb

No Asbestos

B00A - R0009 - General Assistant/Bulk Store

No Asbestos

B00A - R0010 - Home Base

No Asbestos

B00A - R0011 - Home Base

No Asbestos

B00A - R0012 - General Assistant/Bulk Store

No Asbestos

B00A - R0013 - Withdrawal Space - 1hb

No Asbestos

B00A - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0015 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities/Art - 1985 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00B - R0001 - Toilets - Girls

No Asbestos

B00B - R0002 - Kiln Room

No Asbestos

B00B - R0003 - Toilets - Boys

No Asbestos

B00B - R0004 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1985 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00C - R0001 - Home Base

No Asbestos

B00C - R0002 - General Assistant/Bulk Store

No Asbestos

B00C - R0003 - General Assistant/Bulk Store

No Asbestos

B00C - R0004 - General Assistant/Bulk Store

No Asbestos

B00C - R0005 - Withdrawal Space - 1hb

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Home Base

No Asbestos

B00C - R0008 - Withdrawal Space - 1hb

No Asbestos

B00C - R0009 - General Assistant/Bulk Store

No Asbestos

B00C - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0011 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1985 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Canteen

No Asbestos

B00D - R0003 - Canteen Office/Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Administration/General Learning - 1950 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2897/B00F/Eaves Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior**B00F - R0001 - General Learning Space**

No Asbestos

B00F - R0002 - General Learning Space

No Asbestos

B00F - R0003 - Art Learning Space

No Asbestos

B00F - R0004 - Kiln Room

No Asbestos

B00F - R0005 - Cleaning Supplies

No Asbestos

B00F - R0006 - Clerical Office

No Asbestos

B00F - R0007 - Principal

No Asbestos

B00F - R0008 - General Storeroom

No Asbestos

B00F - R0009 - General Storeroom

No Asbestos

B00F - R0010 - Duplicating Workroom

No Asbestos

B00F - R0011 - General Storeroom

No Asbestos

B00F - R0012 - Staff Toilet

No Asbestos

B00F - R0013 - Movement

No Asbestos

B00F - R0014 - Movement

No Asbestos

B00F - R0015 - Community Clinic

No Asbestos

B00F - R0016 - Movement

No Asbestos

B00F - R0017 - Music Store

No Asbestos

B00F - R0018 - Computer Learning Space

No Asbestos

B00F - R0019 - Computer Learning Space

No Asbestos

B00F - R0020 - General Learning Space

No Asbestos

B00F - R0021 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00F - R0022 - Staff Room

No Asbestos

B00F - R0023 - Movement

No Asbestos

B00F - R0024 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

2897/B00F/R0032/Ceiling Structures/Linings/S9

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00F - R0025 - Cleaning Distributed Store

No Asbestos

B00F - R0026 - Staff Toilet

No Asbestos

B00F - R0027 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

2897/B00F/R0032/Ceiling Structures/Linings/S9

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00F - R0028 - Deputy Principal

No Asbestos

B00F - R0029 - Withdrawal Space - 1hb

No Asbestos

B00F - R0030 - Interview

No Asbestos

B00F - R0031 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

2897/B00F/R0031/Ceiling Structures/Linings/S8

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00F - R0032 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

2897/B00F/R0032/Ceiling Structures/Linings/S9

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00F - R9001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library - 1913 - Brick/Block (Brick/Block)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00G - R0001 - Seminar/Study

No Asbestos

B00G - R0002 - Librarian

No Asbestos

B00G - R0003 - Reading Area

No Asbestos

B00G - R0004 - Communications Room

No Asbestos

B00G - R0005 - Movement

No Asbestos

B00G - R0006 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Multi Purpose Facilities - 1984 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00H - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2897/B00H/R0006/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00H - R0002 - Communal Space

No Asbestos

B00H - R0003 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 2897/B00H/R0005/Partition Walls (Cubicles)/S15	No Asbestos Detected
----------------------------	---	----------------------

B00H - R0004 - Staff Kitchen

No Asbestos

B00H - R0005 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 2897/B00H/R0005/Partition Walls (Cubicles)/S15	No Asbestos Detected
----------------------------	---	----------------------

B00H - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2897/B00H/R0006/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00H - R0007 - No Access

Electrical Backing Board	Resinous Board 2897/B00H/R0007/Electrical Backing Board/S16	No Asbestos Detected
--------------------------	--	----------------------

B00H - R0008 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Staff Facilities - 1932 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2897/B00K/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior

B00K - R0001 - Staff Room Annexe

No Asbestos

B00K - R0002 - Staff Room Annexe

No Asbestos

B00K - R0003 - Staff Room Annexe

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities/Art - 1895 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2897/B00L/Eaves Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

Interior

B00L - R0001 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2897/B00L/R0001/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00L - R0003 - Shower/Change

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2897/B00L/R0001/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00L - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2897/B00L/R0001/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00L - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2897/B00L/R0001/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

Wall Linings Internal	Flat AC Sheeting	2897/B00L/R0005/Wall Linings Internal/S11				No Asbestos Detected
-----------------------	------------------	---	--	--	--	-----------------------------

Wall Cladding	Flat AC Sheeting	2897/B00L/R0005/Wall Cladding/S12				No Asbestos Detected
---------------	------------------	-----------------------------------	--	--	--	-----------------------------

B00L - R0006 - Darkroom Space

No Asbestos

B00L - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2897/B00L/R0001/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Administration - 1996 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00M - R0001 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0002 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0003 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0004 - No Access

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0005 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0006 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0007 - Cleaning Distributed Store

No Asbestos

B00M - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0009 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0012 - Staff Shower

No Asbestos

B00M - R0013 - Security Store

No Asbestos

B00M - R0014 - Community Clinic

No Asbestos

B00M - R0015 - Toilets - Girls

No Asbestos

B00M - R0016 - Toilets - Boys

No Asbestos

B00M - R0017 - Duplicating Workroom

No Asbestos

B00M - R0018 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0019 - Movement

No Asbestos

B00M - R0020 - Movement

No Asbestos

B00M - R0021 - Movement

No Asbestos

B00M - R0022 - Staff Kitchen

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00M - R0023 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0024 - Toilet - Lobby

No Asbestos

B00M - R0025 - Staff - Toilet

No Asbestos

B00M - R0026 - Toilet - Lobby

No Asbestos

B00M - R0027 - Staff - Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Other - 2006 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00N - R0001 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Science Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00P - R0001 - Laboratory L.S.

No Asbestos

B00P - R0002 - Preparation

No Asbestos

B00P - R0003 - Apparatus Storage

No Asbestos

B00P - R0004 - Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Technological & Applied Studies - 2011 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00Q - R0001 - Food Technology L.S.

No Asbestos

B00Q - R0002 - Food Technology L.S.

No Asbestos

B00Q - R0003 - Pantry

No Asbestos

B00Q - R0004 - Preparation

No Asbestos

B00Q - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Building Services/Agricultural Science - 2012 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00R - R0001 - Machine Storage

No Asbestos

B00R - R0002 - Sport Equipment Store

No Asbestos

B00R - R0003 - General Assistant/Bulk Store

No Asbestos

B00R - R0004 - Cleaning Distributed Store

No Asbestos

B00R - R0005 - Movement

No Asbestos

B00R - R0006 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - AG Plot Shed

Exterior

Ceiling Void	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2897/B00S/Eaves Linings/S6					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00T - AG Plot Shed

Exterior

Ceiling Void	No Asbestos Found				
Underfloor Voids - Slab on Ground	No Asbestos Found				
Wall Cladding	Flat AC Sheeting 2897/B00T/Wall Cladding/S13				No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00U - AG Plot Shed

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00U - Room+1 - Added Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 770 - D14622 - Technics - Metalwork/Heat Area/Store : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				17.28 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2

R2 - Materials Technology L.S.

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				91 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017