

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Primbee Public School (2904)
Region : Illawarra and South East
State Electorate : Wollongong
Local Government Area : Wollongong

Initial Survey : Noel Arnold & Associates : 14 - Apr - 2008
Reviewed By : Greencap-NAA : 02 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1950 - Steel (Steel)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00A - R0001 - General Storeroom

No Asbestos

B00A - R0002 - External Movement

No Asbestos

B00A - R0003 - General Storeroom

In-fill-panel	Flat AC Sheeting 2904/B00A/R0003/In-fill-panel/S6	No Asbestos Detected
---------------	--	-----------------------------

B00A - R0004 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles 2904/B00A/R0004/Floor Coverings Res/Textile/S7	No Asbestos Detected
-----------------------------	---	-----------------------------

B00A - R0005 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles 2904/B00A/R0004/Floor Coverings Res/Textile/S7	No Asbestos Detected
-----------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Staff Facilities - 1950 - Timber (Timber)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/Eaves Linings/S14				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction					
Wall Cladding	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					

Interior**B00B - R0001 - Movement**

In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					
Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

B00B - R0002 - Home Base

In-fill-panel	Flat AC Sheeting	2m	Panels behind heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0008/In-fill-panel/S10				Chrysotile (white asbestos)	

B00B - R0003 - General Storeroom

In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

B00B - R0004 - Movement

In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

B00B - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	
Electrical Mounting Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					

B00B - R0008 - Staff Room

In-fill-panel	Flat AC Sheeting	2m	Panels behind heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0008/In-fill-panel/S10				Chrysotile (white asbestos)	

B00B - R0009 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

B00B - R0010 - Staff Room Annexe

Ceiling Structures/Linings	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Administration - 1961 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00C/Eaves Linings/S15					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	22m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction					

Interior

B00C - R0001 - Home Base

No Asbestos

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0003 - General Storeroom

No Asbestos

B00C - R0004 - Home Base

No Asbestos

B00C - R0005 - Home Base Store

No Asbestos

B00C - R0006 - Movement

In-fill-panel	Flat AC Sheeting	15m	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00C/R0006/In-fill-panel/S13					Chrysotile (white asbestos)

B00C - R0007 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00C - R0010 - General Storeroom

No Asbestos

B00C - R0011 - Home Base

No Asbestos

B00C - R0012 - Home Base Store

No Asbestos

B00C - R0013 - Staff Toilet

No Asbestos

B00C - R0014 - Principal

No Asbestos

B00C - R0016 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00C/R9002/Wall Linings Internal/S12					Chrysotile (white asbestos)

B00C - R0017 - Movement

No Asbestos

B00C - R0018 - Movement

No Asbestos

B00C - R0019 - Movement

In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0020 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
B00C - R0021 - Movement						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00C/R9002/Wall Linings Internal/S12					Chrysotile (white asbestos)
B00C - R0022 - Stairs						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00C/R9002/Wall Linings Internal/S12					Chrysotile (white asbestos)
B00C - R0023 - Clerical Office/Workroom						
No Asbestos						
B00C - R0024 - Staff Room Annexe						
No Asbestos						
B00C - R9001 - General Assistant/Bulk Store						
Workbench	Compressed AC Sheet					No Asbestos Detected
	2904/B00C/R9001/Workbench/S11					
B00C - R9002 - Movement						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00C/R9002/Wall Linings Internal/S12					Chrysotile (white asbestos)
B00C - R9003 - Stairs						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2904/B00B/Wall Cladding/S8					
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00B/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	10m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00C/R9002/Wall Linings Internal/S12					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1961 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 2904/B00D/wall linings/S1					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 2904/B00D/Eaves Linings/S16	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior**B00D - R0001 - Cleaning Supplies**

Ceiling Structures/Linings	Flat AC Sheeting 2904/B00D/R0001/Ceiling Structures/Linings/S2	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting 2904/B00D/R0001/Wall Linings Internal/S3	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00D - R0002 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 2904/B00D/R0002/Partition Walls (Cubicles)/S4	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 2904/B00D/R0001/Ceiling Structures/Linings/S2	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00D - R0003 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 2904/B00D/R0001/Ceiling Structures/Linings/S2	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00D - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2904/B00D/R0001/Ceiling Structures/Linings/S2	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting 2904/B00D/R0001/Wall Linings Internal/S3	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00D - R0005 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 2904/B00D/R0002/Partition Walls (Cubicles)/S4	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 2904/B00D/R0001/Ceiling Structures/Linings/S2	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00D - R0006 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting 2904/B00D/R0001/Ceiling Structures/Linings/S2	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00D - R0007 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 2904/B00D/R0001/Ceiling Structures/Linings/S2	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00D - R0008 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 2904/B00D/R0001/Ceiling Structures/Linings/S2	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities - 1950 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00E - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Special Purpose/Other-Community Use - 1950 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Wall Cladding	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00F/Wall Cladding/S5					Chrysotile (white asbestos)

Interior

B00F - R0002 - Kiln Room

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	2904/B00F/Wall Cladding/S5					Chrysotile (white asbestos)

B00F - R0003 - Other-Community Use

Wall Linings Internal	Flat AC Sheeting	3.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2904/B00F/Wall Cladding/S5					Chrysotile (white asbestos)

B00F - R0004 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	2904/B00F/Wall Cladding/S5					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - Reading Area

No Asbestos

B00G - R0002 - Library Office/Workroom

No Asbestos

B00G - R0003 - K.L.A. Store

No Asbestos

B00G - R0004 - Communications Room

No Asbestos

B00G - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 804 - D11742 - FSU : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Canteen

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		54 m2

R2 - Covered Area

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		19 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017