

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** White Cliffs Public School (3435)  
**Region :** Western NSW  
**State Electorate :** Barwon  
**Local Government Area :** Central Darling

**Initial Survey :** Noel Arnold & Associates : 08 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Library - 1900 - Timber (Timber)**

**Exterior**

Ceiling Void	Non Accessible Area - No Access - No manhole in building
Underfloor Voids	No Asbestos Found

**Interior**

**B00A - R0001 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0002 - Home Base**

No Asbestos

**B00A - R0003 - Reading Area**

No Asbestos

**B00A - R0004 - Personal Effects Storage**

No Asbestos

**B00A - R0005 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration/General Learning - 1900 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

**Interior**

**B00B - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0002 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities/Staff Facilities - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	6m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3435/B00C/Eaves Linings/S1					<b>Chrysotile (white asbestos)</b>

**Interior**

**B00C - R0001 - Cleaning Supplies**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3435/B00C/R0004/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0002 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3435/B00C/R0004/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0003 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3435/B00C/R0004/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0004 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3435/B00C/R0004/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0005 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3435/B00C/R0004/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0006 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3435/B00C/R0004/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids                      No Asbestos Found

**Interior**

**B00D - R0001 - Home Base**

No Asbestos

**B00D - R0002 - Home Base Store**

No Asbestos

**B00D - R0003 - Practical Activities - 1hb**

No Asbestos

**B00D - R0004 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Communal Facilities - 2002 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00E - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017