


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wilcannia Central School (3442)
Region : Western NSW
State Electorate : Barwon
Local Government Area : Central Darling

Initial Survey : Noel Arnold & Associates : 08 - May - 2008
Reviewed By : Parsons Brinckerhoff : 09 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Building Services - 1986 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	AC Fragments/Debris 3442/B00A/Ceiling Void/S7					No Asbestos Detected

Interior

B00A - R0001 - General Assistant/Bulk Store

No Asbestos

B00A - R0002 - Cleaning Supplies

No Asbestos

B00A - R0003 - Community Clinic

No Asbestos

B00A - R0004 - Clinic-Toilets

No Asbestos

B00A - R0005 - Clinic-Waiting

No Asbestos

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Movement

No Asbestos

B00A - R0008 - Cleaning Supplies

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3442/B00A/R0008/Floor Coverings Res/Textile/S19					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00A - R0009 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 3442/B00A/R0009/Ceiling Structures/Linings/S11					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00A - R0010 - Main Switch Board

Ceiling Structures/Linings	Flat AC Sheeting 3442/B00A/R0009/Ceiling Structures/Linings/S11					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00A - R0011 - Plant

No Asbestos

B00A - R0012 - Duplicating Workroom

No Asbestos

B00A - R0013 - Interview

No Asbestos

B00A - R0014 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library/General Learning - 1986 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	AC Fragments/Debris 3442/B00D/Ceiling Void/S8					No Asbestos Detected

Interior

B00D - R0001 - Plant

No Asbestos

B00D - R0002 - Communications Room

No Asbestos

B00D - R0003 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 3442/B00D/R0003/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00D - R0004 - Cleaning Distributed Store

No Asbestos

B00D - R0005 - Communications Room

No Asbestos

B00D - R0006 - Movement

No Asbestos

B00D - R0007 - General Learning Space

No Asbestos

B00D - R0008 - General Learning Space

No Asbestos

B00D - R0009 - Computer Learning Space

No Asbestos

B00D - R0010 - Security Store

No Asbestos

B00D - R0011 - Reading Area

No Asbestos

B00D - R0012 - Telematics

No Asbestos

B00D - R0013 - Library Office/Workroom

No Asbestos

B00D - R0014 - Communications Room

No Asbestos

B00D - R0015 - Movement

No Asbestos

B00D - R0016 - Movement

No Asbestos

B00D - R0017 - Home Base

No Asbestos

B00D - R0018 - Security Store

No Asbestos

B00D - R0019 - Home Base Store

No Asbestos

B00D - R0020 - No Access

No Asbestos

B00D - R0021 - Home Base

No Asbestos

B00D - R0022 - Withdrawal Space - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00D - R0023 - Movement						
No Asbestos						
B00D - R0024 - Home Base						
No Asbestos						
B00D - R0025 - Movement						
No Asbestos						
B00D - R0026 - Movement						
No Asbestos						
B00D - R0027 - Movement						
No Asbestos						
B00D - R0028 - Movement						
No Asbestos						
B00D - R0029 - Movement						
No Asbestos						
B00D - R0030 - Movement						
No Asbestos						
B00D - R1001 - Withdrawal Space - 1hb						
No Asbestos						
B00D - R1002 - Withdrawal Space - 1hb						
No Asbestos						
B00D - R1003 - Distribution Board					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Flat AC Sheeting					
	3442/B00D/R0003/Ceiling Structures/Linings/S1					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	3442/B00D/R0003/Ceiling Structures/Linings/S1					No Asbestos Detected
B00D - R1004 - Plant						
No Asbestos						
B00D - R1005 - Movement						
No Asbestos						
B00D - R1006 - Staff Room						
No Asbestos						
B00D - R1007 - Staff Room Annexe						
No Asbestos						
B00D - R1008 - Movement						
No Asbestos						
B00D - R1009 - Withdrawal Space - 1hb						
No Asbestos						
B00D - R1010 - Staff Toilet						
No Asbestos						
B00D - R1011 - Staff Toilet						
No Asbestos						
B00D - R1012 - Plant						
Ceiling Structures/Linings	Flat AC Sheeting					
	3442/B00D/R1012/Ceiling Structures/Linings/S13					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Administration - 1874 - Sandstone (Sandstone)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 3442/B00F/Eaves Linings/S6					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B00F - R0001 - Entry Vestibule

No Asbestos

B00F - R0002 - Clerical Office/Workroom

No Asbestos

B00F - R0003 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles 3442/B00F/R0003/Floor Coverings Res/Textile/S3					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

B00F - R0004 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 3442/B00F/R0004/Wall Linings Internal/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3442/B00F/R0004/Wall Linings Internal/S4					No Asbestos Detected

B00F - R0005 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles 3442/B00F/R0003/Floor Coverings Res/Textile/S3					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

B00F - R0006 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 3442/B00F/R0006/Ceiling Structures/Linings/S15					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00F - R0007 - Staff Toilet

No Asbestos

B00F - R0008 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles 3442/B00F/R0003/Floor Coverings Res/Textile/S3					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

B00F - R0009 - Movement

No Asbestos

B00F - R0010 - Clerical Office

No Asbestos

B00F - R0011 - Clerical Office/Workroom

No Asbestos

B00F - R0012 - Principal

No Asbestos

B00F - R0013 - Interview

No Asbestos

B00F - R0014 - Deputy Principal

No Asbestos

B00F - R0015 - Plant

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Agricultural Science - 1986 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Electrical mounting board	Resinous Board	1Unit(s)	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No Access - No key on site						
Ceiling Void	No Asbestos Found					

Interior

B00G - R0001 - General Storeroom						
No Asbestos						
B00G - R0002 - General Storeroom						
No Asbestos						
B00G - R0003 - Staff Toilet						
No Asbestos						
B00G - R0004 - Staff Shower/Change						
No Asbestos						
B00G - R0005 - Movement						
No Asbestos						
B00G - R0006 - Movement						
Wall Linings Internal	Flat AC Sheeting	3442/B00G/R0006/Wall Linings Internal/S18			No Asbestos Detected	
B00G - R0007 - Movement						
No Asbestos						
B00G - R0008 - Class Tools Storage						
No Asbestos						
B00G - R0009 - No Access						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Building Services - 2000 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B001 - R0001 - Garden Store Room

No Asbestos

B001 - R0002 - Garden Store Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 2008 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00J - R0001 - Garden Store Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - General Learning - 2016 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00K - R0001 - Practical Activities - Pre**

No Asbestos

B00K - R0002 - Public Reception

No Asbestos

B00K - R0003 - Movement

No Asbestos

B00K - R0004 - Staff Toilet - Pre

No Asbestos

B00K - R0005 - Staff Toilet - Pre

No Asbestos

B00K - R0006 - Staff Toilet - Pre

No Asbestos

B00K - R0007 - Staff Room

No Asbestos

B00K - R0008 - Store

No Asbestos

B00K - R0009 - Practical Activities - Pre

No Asbestos

B00K - R0010 - Toilets - Boys/Girls - Pre

No Asbestos

B00K - R0011 - Laundry - Pre

No Asbestos

B00K - R0012 - Clerical Office - Pre

No Asbestos

B00K - R0013 - Store

No Asbestos

B00K - R0014 - Covered Area

No Asbestos

B00K - R0015 - External Movement

No Asbestos

B00K - R0016 - External Movement

No Asbestos

B00K - R0017 - Other-Vacant

No Asbestos

B00K - R0018 - Plant

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Storage - 2016 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00L - R0001 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00M - Residential Facilities - 1992 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00M - R0001 - Covered Area**

No Asbestos

B00M - R0002 - Residence - Movement

No Asbestos

B00M - R0003 - Residence - Lounge

No Asbestos

B00M - R0004 - Residence - Kitchen

No Asbestos

B00M - R0005 - Residence - Movement

No Asbestos

B00M - R0006 - Residence - Bedroom

No Asbestos

B00M - R0007 - Residence - Other

No Asbestos

B00M - R0008 - Residence - Bedroom

No Asbestos

B00M - R0009 - Residence - Other

No Asbestos

B00M - R0010 - Residence - Bedroom

No Asbestos

B00M - R0011 - Residence - Other

No Asbestos

B00M - R0012 - Residence - Bedroom

No Asbestos

B00M - R0013 - Residence - Other

No Asbestos

B00M - R0014 - Residence - Other

No Asbestos

B00M - R0015 - Residence - Bathroom

No Asbestos

B00M - R0016 - Residence - Movement

No Asbestos

B00M - R0017 - Residence - Other

No Asbestos

B00M - R0018 - Residence - Toilet

No Asbestos

B00M - R0019 - Residence - Other

No Asbestos

B00M - R0020 - Residence - Laundry

No Asbestos

B00M - R0021 - Residence - Other

No Asbestos

B00M - R0022 - Residence - Movement

No Asbestos

B00M - R0023 - Residence - Garage

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0B1 - Multi Purpose Facilities - 1986 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B0B1 - R0001 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 3442/B0E1/R0003/Partition Walls (Cubicles)/S2	No Asbestos Detected
----------------------------	--	----------------------

B0B1 - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 3442/B0E1/R0003/Partition Walls (Cubicles)/S2	No Asbestos Detected
----------------------------	--	----------------------

B0B1 - R0003 - Plant

Ceiling Structures/Linings	Flat AC Sheeting 3442/B00D/R0003/Ceiling Structures/Linings/S1	No Asbestos Detected
----------------------------	---	----------------------

B0B1 - R0004 - Movement

No Asbestos

B0B1 - R0005 - Staff Shower/Change

No Asbestos

B0B1 - R0006 - Garden Store

No Asbestos

B0B1 - R0007 - Plant

No Asbestos

B0B1 - R0008 - Other-Community Use

No Asbestos

B0B1 - R0009 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 3442/B0E1/R0003/Partition Walls (Cubicles)/S2	No Asbestos Detected
----------------------------	--	----------------------

B0B1 - R0010 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 3442/B0E1/R0003/Partition Walls (Cubicles)/S2	No Asbestos Detected
----------------------------	--	----------------------

B0B1 - R0011 - Sports Store

No Asbestos

B0B1 - R0012 - Plant

Ceiling Structures/Linings	Flat AC Sheeting 3442/B00D/R0003/Ceiling Structures/Linings/S1	No Asbestos Detected
----------------------------	---	----------------------

B0B1 - R0013 - Cleaning Distributed Store

No Asbestos

B0B1 - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0B1 - R0015 - Movement

No Asbestos

B0B1 - R0016 - General Storeroom

No Asbestos

B0B1 - R0017 - Multi-Purpose Space

No Asbestos

B0B1 - R0018 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 3442/B0E1/R0003/Partition Walls (Cubicles)/S2	No Asbestos Detected
----------------------------	--	----------------------

B0B1 - R0019 - Toilets - Boys

No Asbestos

B0B1 - R0020 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B0B1 - R0021 - Movement

No Asbestos

B0B1 - R0022 - Raised Platform

No Asbestos

B0B1 - R0023 - Movement

No Asbestos

B0B1 - R0024 - Movement

No Asbestos

B0B1 - R0025 - Movement

No Asbestos

B0B1 - R0026 - Movement

No Asbestos

B0B1 - R0027 - Movement

No Asbestos

B0B1 - R0028 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0B2 - Pupil Facilities - 1986 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	AC Fragments/Debris					No Asbestos Detected
	3442/B0B2/Ceiling Void/S9					

Interior

B0B2 - R0001 - Canteen

No Asbestos

B0B2 - R0002 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3442/B0B2/R0002/Ceiling Structures/Linings/S12					

B0B2 - R0003 - Canteen Office/Store

No Asbestos

B0B2 - R0004 - Distribution Board Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3442/B00D/R0003/Ceiling Structures/Linings/S1					

B0B2 - R0005 - Disabled Toilet

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3442/B0B2/R0005/Ceiling Structures/Linings/S17					

B0B2 - R0006 - Plant

No Asbestos

B0B2 - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0C1 - General Learning - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B0C1 - R0001 - Laboratory L.S.

No Asbestos

B0C1 - R0002 - Preparation

No Asbestos

B0C1 - R0003 - Plant

No Asbestos

B0C1 - R0004 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting
	3442/B00D/R0003/Ceiling Structures/Linings/S1

No Asbestos Detected

B0C1 - R0005 - Preparation - Materials

No Asbestos

B0C1 - R0006 - Food Technology L.S.

No Asbestos

B0C1 - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0C2 - Technological & Applied Studies - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B0C2 - R0001 - Distribution Board Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	3442/B00D/R0003/Ceiling Structures/Linings/S1	No Asbestos Detected
----------------------------	------------------	---	-----------------------------

B0C2 - R0002 - Resource/Project Store

No Asbestos

B0C2 - R0003 - Preparation - Materials

No Asbestos

B0C2 - R0004 - Plant

No Asbestos

B0C2 - R0005 - Materials Technology L.S.

No Asbestos

B0C2 - R0006 - Plant

No Asbestos

B0C2 - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0C3 - Art - 1986 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B0C3 - R0001 - Kiln Room

No Asbestos

B0C3 - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3442/B0C3/R0002/Ceiling Structures/Linings/S16	No Asbestos Detected
----------------------------	--	-----------------------------

B0C3 - R0003 - Plant

No Asbestos

B0C3 - R0004 - Art Learning Space

No Asbestos

B0C3 - R0005 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles 3442/B00F/R0003/Floor Coverings Res/Textile/S3	No Asbestos Detected
-----------------------------	---	-----------------------------

B0C3 - R0006 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles 3442/B00F/R0003/Floor Coverings Res/Textile/S3	No Asbestos Detected
-----------------------------	---	-----------------------------

B0C3 - R0007 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 3442/B0E1/R0003/Partition Walls (Cubicles)/S2	No Asbestos Detected
----------------------------	--	-----------------------------

B0C3 - R0008 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 3442/B0E1/R0003/Partition Walls (Cubicles)/S2	No Asbestos Detected
----------------------------	--	-----------------------------

B0C3 - R0009 - Darkroom Space

No Asbestos

B0C3 - R0010 - Seminar/Study

No Asbestos

B0C3 - R0011 - Cleaning Distributed Store

Non Accessible

B0C3 - R0012 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 3442/B00D/R0003/Ceiling Structures/Linings/S1	No Asbestos Detected
----------------------------	---	-----------------------------

B0C3 - R0013 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0E1 - General Learning - 1986 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B0E1 - R0001 - Movement

No Asbestos

B0E1 - R0002 - Cleaning Distributed Store

Non Accessible

B0E1 - R0003 - Toilets - Boys

Partition Walls (Cubicles) Compressed AC Sheet
 3442/B0E1/R0003/Partition Walls (Cubicles)/S2 **No Asbestos Detected**

B0E1 - R0004 - Home Base Store

No Asbestos

B0E1 - R0005 - Practical Activities - 1hb

No Asbestos

B0E1 - R0006 - Plant

No Asbestos

B0E1 - R0007 - Security Store

No Asbestos

B0E1 - R0008 - Home Base Store

No Asbestos

B0E1 - R0009 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting
 3442/B00D/R0003/Ceiling Structures/Linings/S1 **No Asbestos Detected**

B0E1 - R0010 - Home Base

No Asbestos

B0E1 - R0011 - Home Base

No Asbestos

B0E1 - R0012 - Movement

No Asbestos

B0E1 - R0013 - Withdrawal Space - 1hb

No Asbestos

B0E1 - R0014 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0E2 - General Learning - 1986 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	AC Fragments/Debris					No Asbestos Detected
	3442/B0E2/Ceiling Void/S10					

Interior

B0E2 - R0001 - Movement

No Asbestos

B0E2 - R0002 - Plant

No Asbestos

B0E2 - R0003 - Security Store

No Asbestos

B0E2 - R0004 - Distribution Board Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3442/B00D/R0003/Ceiling Structures/Linings/S1					

B0E2 - R0005 - Home Base Store

No Asbestos

B0E2 - R0006 - Practical Activities - 1hb

No Asbestos

B0E2 - R0007 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	3442/B0E1/R0003/Partition Walls (Cubicles)/S2					

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3442/B0E2/R0007/Ceiling Structures/Linings/S14					

B0E2 - R0008 - Home Base Store

No Asbestos

B0E2 - R0009 - Home Base

No Asbestos

B0E2 - R0010 - Home Base

No Asbestos

B0E2 - R0011 - Movement

No Asbestos

B0E2 - R0012 - Withdrawal Space - 1hb

No Asbestos

B0E2 - R0013 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D15530 - Learning Unit - Standard/Withdrawal : Placement Date - 22/03/2016

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

OS 601 - D15531 - Learning Unit - Standard/Withdrawal : Placement Date - 22/03/2016

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017