


# Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Warnervale Public School (4117)  
Region : Hunter/Central Coast  
State Electorate : Wyong  
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 29 - Mar - 2008  
Reviewed By : Grencap-NAA : 20 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00A - Administration/Staff Facilities - 2008 - Timber (Timber)**

**Exterior**

No Asbestos

**Interior**

**B00A - R0001 - Entry Vestibule**

No Asbestos

**B00A - R0002 - Movement**

No Asbestos

**B00A - R0003 - Sick Bay**

No Asbestos

**B00A - R0004 - Disabled Shower/Toilet**

No Asbestos

**B00A - R0005 - Interview/Office - Type 3**

No Asbestos

**B00A - R0006 - Interview**

No Asbestos

**B00A - R0007 - Deputy Principal**

No Asbestos

**B00A - R0008 - Staff Room**

No Asbestos

**B00A - R0009 - Staff Room Annexe**

No Asbestos

**B00A - R0010 - Staff Kitchen**

No Asbestos

**B00A - R0011 - Deputy Principal**

No Asbestos

**B00A - R0012 - Staff Toilet**

No Asbestos

**B00A - R0013 - Staff Toilet**

No Asbestos

**B00A - R0014 - Cleaning Distributed Store**

No Asbestos

**B00A - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0016 - Security Store**

No Asbestos

**B00A - R0017 - Principal**

No Asbestos

**B00A - R0018 - Clerical Office**

No Asbestos

**B00A - R0019 - Clerical Office/Workroom**

No Asbestos

**B00A - R0020 - Staff Toilet**

No Asbestos

**B00A - R0021 - External Movement**

No Asbestos

**B00A - R0022 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00B - Communal Facilities - 2008 - Timber (Timber)**

**Exterior**

No Asbestos

**Interior**

**B00B - R0001 - Communal Space**

No Asbestos

**B00B - R0002 - Raised Platform**

No Asbestos

**B00B - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0004 - General Storeroom**

No Asbestos

**B00B - R0005 - Hall Chair Store**

No Asbestos

**B00B - R0006 - P.E. Store**

No Asbestos

**B00B - R0007 - Toilet - Lobby**

No Asbestos

**B00B - R0008 - Toilets - Boys**

No Asbestos

**B00B - R0009 - Covered Outdoor Learning Area**

No Asbestos

**B00B - R0010 - Disabled Toilet**

No Asbestos

**B00B - R0011 - Clerical Office**

No Asbestos

**B00B - R0012 - Toilets - Girls**

No Asbestos

**B00B - R0013 - Toilet - Lobby**

No Asbestos

**B00B - R0014 - General Storeroom**

No Asbestos

**B00B - R0015 - Cleaning Distributed Store**

No Asbestos

**B00B - R0016 - Garden Store**

No Asbestos

**B00B - R0017 - General Assistant/Bulk Store**

No Asbestos

**B00B - R0018 - Sports Store**

No Asbestos

**B00B - R0019 - General Storeroom**

No Asbestos

**B00B - R0020 - Movement**

No Asbestos

**B00B - R0021 - Movement**

No Asbestos

**B00B - R0022 - External Movement**

No Asbestos

**B00B - R0023 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0024 - Ramp</b>						

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities - 2008 - Timber (Timber)**

**Exterior**

No Asbestos

**Interior**

**B00C - R0001 - Canteen**

No Asbestos

**B00C - R0002 - Canteen Office/Store**

No Asbestos

**B00C - R0003 - Drinking Facilities**

No Asbestos

**B00C - R0004 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00D - Library/Special Purpose - 2008 - Brick/Block (Brick/Block)**

**Exterior**

No Asbestos

**Interior**

**B00D - R0001 - Cleaning Distributed Store**

No Asbestos

**B00D - R0002 - Staff Toilet**

No Asbestos

**B00D - R0003 - Security Store**

No Asbestos

**B00D - R0004 - Plant**

No Asbestos

**B00D - R0005 - Library Office/Workroom**

No Asbestos

**B00D - R0006 - Special Programs Room**

No Asbestos

**B00D - R0007 - Reading Area**

No Asbestos

**B00D - R0008 - Special Programs Room**

No Asbestos

**B00D - R0009 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0010 - Security Store**

No Asbestos

**B00D - R0011 - Special Programs Room**

No Asbestos

**B00D - R0012 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 2008 - Timber (Timber)**

**Exterior**

No Asbestos

**Interior**

**B00E - R0001 - Home Base**

No Asbestos

**B00E - R0002 - Home Base Store**

No Asbestos

**B00E - R0003 - Practical Activities - 1hb**

No Asbestos

**B00E - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00E - R0005 - Home Base**

No Asbestos

**B00E - R0006 - Practical Activities - 1hb**

No Asbestos

**B00E - R0007 - Home Base Store**

No Asbestos

**B00E - R0008 - Home Base Store**

No Asbestos

**B00E - R0009 - Practical Activities - 1hb**

No Asbestos

**B00E - R0010 - Home Base**

No Asbestos

**B00E - R0011 - Withdrawal Space - 2hb**

No Asbestos

**B00E - R0012 - Home Base**

No Asbestos

**B00E - R0013 - Practical Activities - 1hb**

No Asbestos

**B00E - R0014 - Home Base Store**

No Asbestos

**B00E - R0015 - Home Base Store**

No Asbestos

**B00E - R0016 - Practical Activities - 1hb**

No Asbestos

**B00E - R0017 - Home Base**

No Asbestos

**B00E - R0018 - Withdrawal Space - 2hb**

No Asbestos

**B00E - R0019 - Home Base**

No Asbestos

**B00E - R0020 - Practical Activities - 1hb**

No Asbestos

**B00E - R0021 - Home Base Store**

No Asbestos

**B00E - R0022 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0023 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R0024 - Toilets - Girls</b>						
No Asbestos						
<b>B00E - R0025 - Toilets - Boys</b>						
No Asbestos						
<b>B00E - R0026 - Kiln Room</b>						
No Asbestos						
<b>B00E - R0027 - External Movement</b>						
No Asbestos						

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00F - General Learning - 2008 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

**Interior**

**B00F - R0001 - Home Base**

No Asbestos

**B00F - R0002 - Home Base Store**

No Asbestos

**B00F - R0003 - Practical Activities - 1hb**

No Asbestos

**B00F - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00F - R0005 - Home Base**

No Asbestos

**B00F - R0006 - Practical Activities - 1hb**

No Asbestos

**B00F - R0007 - Home Base Store**

No Asbestos

**B00F - R0008 - Home Base Store**

No Asbestos

**B00F - R0009 - Practical Activities - 1hb**

No Asbestos

**B00F - R0010 - Home Base**

No Asbestos

**B00F - R0011 - Withdrawal Space - 2hb**

No Asbestos

**B00F - R0012 - Home Base**

No Asbestos

**B00F - R0013 - Practical Activities - 1hb**

No Asbestos

**B00F - R0014 - Home Base Store**

No Asbestos

**B00F - R0015 - Disabled Shower/Toilet**

No Asbestos

**B00F - R0016 - Laundry - Pre**

No Asbestos

**B00F - R0017 - Toilets - Girls**

No Asbestos

**B00F - R0018 - Toilets - Boys**

No Asbestos

**B00F - R0019 - Cleaning Distributed Store**

No Asbestos

**B00F - R0020 - Distribution Board**

No Asbestos

Note: No inspection of live electrical installation.

**B00F - R0021 - External Movement**

No Asbestos

**B00F - R0022 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 2008 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

**Interior**

**B00G - R0001 - Home Base**

No Asbestos

**B00G - R0002 - Home Base Store**

No Asbestos

**B00G - R0003 - Practical Activities - 1hb**

No Asbestos

**B00G - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00G - R0005 - Home Base**

No Asbestos

**B00G - R0006 - Practical Activities - 1hb**

No Asbestos

**B00G - R0007 - Home Base Store**

No Asbestos

**B00G - R0008 - Home Base Store**

No Asbestos

**B00G - R0009 - Practical Activities - 1hb**

No Asbestos

**B00G - R0010 - Home Base**

No Asbestos

**B00G - R0011 - Withdrawal Space - 2hb**

No Asbestos

**B00G - R0012 - Home Base**

No Asbestos

**B00G - R0013 - Practical Activities - 1hb**

No Asbestos

**B00G - R0014 - Home Base Store**

No Asbestos

**B00G - R0015 - Home Base Store**

No Asbestos

**B00G - R0016 - Practical Activities - 1hb**

No Asbestos

**B00G - R0017 - Home Base**

No Asbestos

**B00G - R0018 - Withdrawal Space - 2hb**

No Asbestos

**B00G - R0019 - Home Base**

No Asbestos

**B00G - R0020 - Practical Activities - 1hb**

No Asbestos

**B00G - R0021 - Home Base Store**

No Asbestos

**B00G - R0022 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0023 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - R0024 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D11241 - Learning Unit - Standard With P.A.A. : Placement Date - 14/11/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D12150 - Learning Unit - Standard With P.A.A. : Placement Date - 12/01/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D12275 - Learning Unit - Standard With P.A.A. : Placement Date - 14/12/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D16033 - Learning Unit - Standard With P.A.A. : Placement Date - 17/10/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017