

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wakehurst Public School (4368)
Region : Northern Sydney
State Electorate : Davidson
Local Government Area : Warringah

Initial Survey : Noel Arnold & Associates : 12 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 13 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1967 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Eaves Linings	Flat AC Sheeting	100m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00B/Eaves Linings/S2				Chrysotile (white asbestos)	
Gable verge lining	Flat AC Sheeting	50m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/Gable verge lining/S18				Chrysotile (white asbestos)	

Interior**B00A - R0001 - Communications Room**

No Asbestos

B00A - R0002 - General Storeroom

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00D/R0004/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00A - R0005 - Library Office/Workroom

No Asbestos

B00A - R0006 - Seminar/Study

No Asbestos

B00A - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4368/B00A/R0008/Ceiling Structures/Linings/S13					

B00A - R0009 - Main Switch Board

Electrical Mounting Board	Flat AC Sheeting	4Unit	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4368/B00A/R0008/Ceiling Structures/Linings/S13					

B00A - R0010 - Movement

No Asbestos

B00A - R0012 - Sick Bay

Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0014/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	

B00A - R0013 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0014/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	

B00A - R0015 - Duplicating Workroom

No Asbestos

B00A - R0016 - Entry Vestibule

No Asbestos

B00A - R0017 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00D/R0004/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00A - R0018 - Principal						
No Asbestos						
B00A - R0019 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0023/Wall Linings Internal/S16				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0023/Wall Linings Internal/S16				Chrysotile (white asbestos)	
B00A - R0020 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0014/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	
B00A - R0021 - Deputy Principal						
No Asbestos						
B00A - R0022 - Clerical Office						
No Asbestos						
B00A - R0026 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0014/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	
B00A - R0027 - Reading Area						
No Asbestos						
B00A - R0028 - Seminar/Study						
No Asbestos						
B00A - R0029 - Staff Room						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0029/Recently Modified Space/S19				Chrysotile (white asbestos)	
B00A - R0030 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0030/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0030/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R0031 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0030/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting	12m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0030/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R0032 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0030/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting	5m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00A/R0030/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R0033 - Sick Bay						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - R0034 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1966 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 4368/B00B/Eaves Linings/S2	71m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable verge lining	Flat AC Sheeting	60m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Assumed Asbestos - Height Restriction >3m.

Interior**B00B - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4368/B00B/R0001/Ceiling Structures/Linings/S17	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	--------------	--------------------	---------	--

B00B - R0002 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting 4368/B00B/R0001/Ceiling Structures/Linings/S17	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	--------------	--------------------	---------	--

B00B - R0004 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting 4368/B00B/R0001/Ceiling Structures/Linings/S17	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	--------------	--------------------	---------	--

B00B - R0005 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting 4368/B00B/R0001/Ceiling Structures/Linings/S17	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	--------------	--------------------	---------	--

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - Home Base Store

No Asbestos

B00B - R0008 - General Storeroom

No Asbestos

B00B - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4368/B00B/R0020/Ceiling Structures/Linings/S1	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------	--------------------	---------	--

B00B - R0010 - General Storeroom

No Asbestos

B00B - R0011 - Movement

No Asbestos

B00B - R0012 - Personal Effects Storage

No Asbestos

B00B - R0013 - Home Base Store

No Asbestos

B00B - R0014 - Home Base

No Asbestos

B00B - R0015 - Home Base

No Asbestos

B00B - R0016 - Home Base Store

No Asbestos

B00B - R0017 - Personal Effects Storage

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Electrical Mounting Board	Flat AC Sheeting	1Unit	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

B00B - R0019 - Movement

No Asbestos

B00B - R0020 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

4368/B00B/R0020/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

B00B - R0021 - Movement

No Asbestos

B00B - R0022 - Personal Effects Storage

No Asbestos

B00B - R0023 - Sports Store

No Asbestos

B00B - R0024 - Home Base Store

No Asbestos

B00B - R0025 - Home Base

No Asbestos

B00B - R0026 - Home Base

No Asbestos

B00B - R0027 - Home Base Store

No Asbestos

B00B - R0028 - General Storeroom

No Asbestos

B00B - R0029 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

4368/B00B/R0020/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

B00B - R0030 - General Storeroom

No Asbestos

B00B - R0031 - Movement

No Asbestos

B00B - R0032 - Personal Effects Storage

No Asbestos

B00B - R0033 - Home Base Store

No Asbestos

B00B - R0034 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1967 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Eaves Linings	Flat AC Sheeting	71m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

Interior

B00C - R0004 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

B00C - R0005 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

B00C - R0010 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

B00C - R0011 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4368/B00E/R0008/Partition Walls (Cubicles)/S7					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting 4368/B00E/R0010/Wall Linings Internal/S8					No Asbestos Detected

B00C - R0012 - K.L.A. Store

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting 4368/B00E/R0010/Wall Linings Internal/S8					No Asbestos Detected

B00C - R0013 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 4368/B00E/R0008/Partition Walls (Cubicles)/S7					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting 4368/B00E/R0010/Wall Linings Internal/S8					No Asbestos Detected

B00C - R0014 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting 4368/B00E/R0010/Wall Linings Internal/S8					No Asbestos Detected

B00C - R0015 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00C/R0013/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1966 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 4368/B00D/Eaves Linings/S4	36m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Galbe verge lining	Flat AC Sheeting	40m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Assumed Asbestos - Height Restriction >3m.

Interior**B00D - R0001 - Uniform Shop**

No Asbestos

B00D - R0002 - General Storeroom

No Asbestos

B00D - R0003 - General Storeroom

No Asbestos

B00D - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
4368/B00D/R0004/Ceiling Structures/Linings/S3						

B00D - R0005 - Movement

No Asbestos

B00D - R0006 - Personal Effects Storage

No Asbestos

B00D - R0008 - General Storeroom

No Asbestos

B00D - R0009 - Home Base Store

No Asbestos

B00D - R0010 - Home Base

No Asbestos

B00D - R0011 - Home Base

No Asbestos

B00D - R0012 - Home Base Store

No Asbestos

B00D - R0013 - Craft Store

No Asbestos

B00D - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
4368/B00D/R0004/Ceiling Structures/Linings/S3						

B00D - R0015 - General Storeroom

No Asbestos

B00D - R0016 - Movement

No Asbestos

B00D - R0017 - Personal Effects Storage

No Asbestos

B00D - R0018 - Home Base Store

No Asbestos

B00D - R0019 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R9001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1966 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	15m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00D/Eaves Linings/S4					Chrysotile (white asbestos)

Interior

B00E - R0003 - Drinking Facilities

No Asbestos

B00E - R0004 - Drinking Facilities

No Asbestos

B00E - R0007 - Sports Store

No Asbestos

B00E - R0008 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	4368/B00E/R0008/Partition Walls (Cubicles)/S7					
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4368/B00E/R0010/Wall Linings Internal/S8					

B00E - R0009 - Hall Chair Store

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4368/B00E/R0010/Wall Linings Internal/S8					

B00E - R0010 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	4368/B00E/R0008/Partition Walls (Cubicles)/S7					
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4368/B00E/R0010/Wall Linings Internal/S8					

B00E - R0011 - Sports Store

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4368/B00E/R0010/Wall Linings Internal/S8					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1967 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00D/Eaves Linings/S4				Chrysotile (white asbestos)	
Gable verge lining	Flat AC Sheeting	40m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction >3m.					

Interior**B00F - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00D/R0004/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00F - R0002 - Movement

No Asbestos

B00F - R0003 - Personal Effects Storage

Wall Linings Internal	Flat AC Sheeting	1m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00F/R0003/Wall Linings Internal/S5				Chrysotile (white asbestos)	

B00F - R0004 - General Storeroom

No Asbestos

B00F - R0005 - Raised Platform

No Asbestos

B00F - R0006 - Communal Space

No Asbestos

B00F - R0007 - Communal Space

No Asbestos

B00F - R0008 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00F/R0015/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)	

B00F - R0009 - Personal Effects Storage

Wall Linings Internal	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00F/R0003/Wall Linings Internal/S5				Chrysotile (white asbestos)	

B00F - R0010 - Movement

No Asbestos

B00F - R0011 - Cleaning Distributed Store

No Asbestos

B00F - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4368/B00D/R0004/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00F - R0013 - Home Base Store

No Asbestos

B00F - R0014 - Personal Effects Storage

No Asbestos

B00F - R0015 - Toilets - Boys

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00F/R0015/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	
B00F - R0016 - Home Base						
No Asbestos						
B00F - R0017 - Home Base						
No Asbestos						
B00F - R0018 - Home Base Store						
No Asbestos						
B00F - R0019 - Cleaning Distributed Store						
Electrical Mounting Board	Flat AC Sheeting	1Unit	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00F - R0021 - Movement						
No Asbestos						
B00F - R0022 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00D/R0004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00F - R0023 - Outdoor Learning Area						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00D/Eaves Linings/S4					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1967 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Eaves Linings	Flat AC Sheeting 4368/B00B/Eaves Linings/S2	57m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable verge lining	Flat AC Sheeting Assumed Asbestos - Height Restriction >3m.	40m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Underfloor Voids	AC Fragments/Debris 4368/B00G/Underfloor Voids/S21	NA	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior**B00G - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4368/B00D/R0004/Ceiling Structures/Linings/S3	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------	--------------------	---------	--

B00G - R0002 - Movement

No Asbestos

B00G - R0003 - General Storeroom

No Asbestos

B00G - R0004 - General Storeroom

No Asbestos

B00G - R0005 - Out Of School Hours Care Centre

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Craft Store

No Asbestos

B00G - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4368/B00D/R0004/Ceiling Structures/Linings/S3	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------	--------------------	---------	--

B00G - R0009 - Home Base Store

No Asbestos

B00G - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4368/B00D/R0004/Ceiling Structures/Linings/S3	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------	--------------------	---------	--

B00G - R0011 - Personal Effects Storage

No Asbestos

B00G - R0012 - Home Base Store

No Asbestos

B00G - R0013 - Personal Effects Storage

Electrical Mounting Board	Flat AC Sheeting	1Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3) Assumed Asbestos - Electrical Hazard
---------------------------	------------------	-------	--------------	--------------------	---------	---

B00G - R0015 - Home Base Store

No Asbestos

B00G - R0016 - Home Base

No Asbestos

B00G - R0017 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00G - R0018 - General Storeroom						
No Asbestos						
B00G - R0019 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0024/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
B00G - R0020 - Deputy Principal						
No Asbestos						
B00G - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0026/Wall Linings Internal/S12					Chrysotile (white asbestos)	
B00G - R0022 - Craft Store						
Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0024/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
B00G - R0023 - K.L.A. Store						
Floor Coverings Res/Textile	Vinyl Tiles	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0024/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
B00G - R0024 - Distribution Board						
Note: No inspection of live electrical installation.						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0024/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
Electrical Mounting Board	Flat AC Sheeting	1Unit	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
Wall Linings Internal	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0024/Wall Linings Internal/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0024/Wall Linings Internal/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00G - R0025 - Staff Room						
No Asbestos						
B00G - R0026 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0026/Wall Linings Internal/S12					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4368/B00G/R0026/Wall Linings Internal/S12					Chrysotile (white asbestos)	
B00G - R0027 - Movement						
No Asbestos						
B00G - R0028 - Home Base						
No Asbestos						
B00G - R0029 - Home Base Store						
No Asbestos						
B00G - R0030 - Personal Effects Storage						
No Asbestos						
B00G - R0031 - Movement						
No Asbestos						
B00G - R0032 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)

4368/B00B/R0020/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

B00G - R0033 - Personal Effects Storage

No Asbestos

B00G - R0034 - Home Base Store

No Asbestos

B00G - R0035 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00H - R0001 - Communal Space**

No Asbestos

B00H - R0002 - Hall Chair Store

No Asbestos

B00H - R0003 - Communal/Performance Store

No Asbestos

B00H - R0004 - P.E. Store

No Asbestos

B00H - R0005 - Toilet - Lobby

No Asbestos

B00H - R0006 - Toilets - Girls

No Asbestos

B00H - R0007 - Toilets - Boys

No Asbestos

B00H - R0008 - Sound Cupboard

No Asbestos

B00H - R0009 - Toilet - Lobby

No Asbestos

B00H - R0010 - Plant

No Asbestos

B00H - R0011 - Cleaning Distributed Store

No Asbestos

B00H - R0012 - Access Shower/Toilet/Change

No Asbestos

B00H - R0013 - Main Switch Board

No Asbestos

B00H - R0014 - Movement

No Asbestos

B00H - R0015 - Raised Platform

No Asbestos

B00H - R0016 - Movement

No Asbestos

B00H - R0017 - Movement

No Asbestos

B00H - R0018 - Canteen

No Asbestos

B00H - R0019 - Canteen Office/Store

No Asbestos

B00H - R0020 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

4368_ASB_100913_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017