Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Engadine West Public School (4292)**
Region :	**Sydney**
State Electorate :	**Heathcote**
Local Government Area :	**Sutherland**

Initial Survey :	**Noel Arnold & Associates : 06 - May - 2008**
Reviewed By :	**Parsons Brinckerhoff : 28 - Aug - 2015**

4292 - Engadine West Public School
Site Plan (12504)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Administration/Staff Facilities - 1961 - Brick/Block (Brick/Block)

Exterior

Gable verge lining	Flat AC Sheeting	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/Gable verge lining/S18					**Chrysotile (white asbestos)**
In-fill-panel	Compressed AC Sheet	34m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/In-fill-panel/S19					**Chrysotile (white asbestos)**
Eaves Linings	Flat AC Sheeting	30m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/Eaves Linings/S17					**Chrysotile (white asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/R0009/Ceiling Structures/Linings/S27					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

B00A - R0002 - Clerical Office

No Asbestos

B00A - R0003 - Clerical Office/Workroom

Floor Coverings Res/Textile	Vinyl Tiles	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/R0003/Floor Coverings Res/Textile/S15					**Chrysotile (white asbestos)**

B00A - R0004 - Interview

No Asbestos

B00A - R0005 - Staff Room Annexe

No Asbestos

B00A - R0006 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles	26m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/R0003/Floor Coverings Res/Textile/S15					**Chrysotile (white asbestos)**

B00A - R0007 - Movement

No Asbestos

B00A - R0008 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/R0008/Partition Walls (Cubicles)/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00A - R0009 - Cleaning Distributed Store

No Asbestos

B00A - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0011 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/R0008/Partition Walls (Cubicles)/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00A - R0012 - Duplicating Workroom

No Asbestos

B00A - R0013 - Staff Room

No Asbestos

B00A - R0014 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	62m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/R0009/Ceiling Structures/Linings/S27					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

B00A - R0015 - Principal

No Asbestos

B00A - R0016 - Deputy Principal

No Asbestos

B00A - R0020 - Entry Vestibule

No Asbestos

B00A - R0021 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning - 1961 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/Eaves Linings/S17					**Chrysotile (white asbestos)**
Gable verge lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/Gable verge lining/S18					**Chrysotile (white asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	2m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4292/B00B/Underfloor Voids - Packing to Floor Joists/S23					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

Interior

B00B - R0001 - Movement
No Asbestos

B00B - R0002 - Main Switch Board
No Asbestos

B00B - R0003 - Deputy Principal
No Asbestos

B00B - R0004 - Movement
No Asbestos

B00B - R0005 - Movement
No Asbestos

B00B - R0006 - Personal Effects Storage
No Asbestos

B00B - R0007 - Movement
No Asbestos

B00B - R0008 - Home Base Store
No Asbestos

B00B - R0009 - Home Base
No Asbestos

B00B - R0010 - Practical Activities - 1hb
No Asbestos

B00B - R0011 - Home Base
No Asbestos

B00B - R0012 - Home Base Store
No Asbestos

B00B - R0013 - Personal Effects Storage
No Asbestos

B00B - R0014 - Movement
No Asbestos

B00B - R0015 - Movement
No Asbestos

B00B - R0016 - Personal Effects Storage
No Asbestos

B00B - R0017 - Home Base Store
No Asbestos

B00B - R0018 - Home Base
No Asbestos

B00B - R0019 - Practical Activities - 1hb
No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - R0020 - Home Base

No Asbestos

B00B - R0021 - Home Base Store

No Asbestos

B00B - R0022 - Personal Effects Storage

No Asbestos

B00B - R0023 - Movement

No Asbestos

B00B - R0024 - Movement

No Asbestos

B00B - R0025 - Cleaning Distributed Store

No Asbestos

B00B - R0026 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Pupil Facilities/Building Services - 1961 - Concrete (Concrete)

Exterior

Gable verge lining	Flat AC Sheeting	12m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Gable verge lining/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Flat AC Sheeting	30m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Eaves Linings/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Voids	AC Fragments/Debris					
	4292/B00C/Ceiling Voids/S22					**No Asbestos Detected**
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00C - R0002 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00C/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**

B00C - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00C/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**

B00C - R0005 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00C/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**

B00C - R0006 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00C/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**

B00C - R0007 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00C/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**
Partition Walls (Cubicles)	Compressed AC Sheet					
	4292/B00C/R0008/Partition Walls (Cubicles)/S6					**No Asbestos Detected**

B00C - R0008 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00C/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**
Partition Walls (Cubicles)	Compressed AC Sheet					
	4292/B00C/R0008/Partition Walls (Cubicles)/S6					**No Asbestos Detected**

B00C - R0009 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00C/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - General Learning/Pupil Facilities - 1977 - Brick/Block (Brick/Block)

Exterior

Gable verge lining	Flat AC Sheeting	40m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/Gable verge lining/S18					**Chrysotile (white asbestos)**
In-fill-panel	Compressed AC Sheet	52m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/In-fill-panel/S24					**Chrysotile (white asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00E - R0001 - Special Programs Room

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0003 - Communal Space

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0004 - Practical Activities - 1hb

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0005 - Home Base

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0006 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0007 - Cleaning Supplies

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0008 - Cleaning Supplies

Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/R0002/Floor Coverings Res/Textile/S3					**Chrysotile (white asbestos)**

B00E - R0009 - Staff Toilet

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0010 - Staff Toilet

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0011 - Movement

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00E - R0012 - Toilets - Girls

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Partition Walls (Cubicles)	Compressed AC Sheet	
	4292/B00E/R0012/Partition Walls (Cubicles)/S2	**No Asbestos Detected**

B00E - R0013 - Toilets - Boys

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Partition Walls (Cubicles)	Compressed AC Sheet					
	4292/B00E/R0012/Partition Walls (Cubicles)/S2					**No Asbestos Detected**
B00E - R0014 - Practical Activities - 3hb						
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00E - R0015 - Movement						
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00E - R0016 - Cleaning Distributed Store						
No Asbestos						
B00E - R0017 - Craft Store						
No Asbestos						
B00E - R0018 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/R0019/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**
B00E - R0019 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/R0019/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**
B00E - R0020 - Movement						
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0021/Ceiling Structures/Linings/S31					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/R0021/Floor Coverings Res/Textile/S30					**Chrysotile (white asbestos)**
B00E - R0021 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/R0021/Floor Coverings Res/Textile/S30					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0021/Ceiling Structures/Linings/S31					**No Asbestos Detected**
B00E - R0022 - External Movement						
No Asbestos						
B00E - R1001 - Home Base						
No Asbestos						
B00E - R1002 - Cleaning Distributed Store						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4292/B00E/R1002/Ceiling Structures/Linings/S25					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/R0002/Floor Coverings Res/Textile/S3					**Chrysotile (white asbestos)**
B00E - R1003 - General Storeroom						
No Asbestos						
B00E - R1004 - Home Base						
No Asbestos						
B00E - R1005 - Home Base						
No Asbestos						
B00E - R1006 - Home Base						
No Asbestos						
B00E - R1007 - Home Base						
No Asbestos						
B00E - R1008 - Distribution Board						Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/R1002/Ceiling Structures/Linings/S25					**Chrysotile (white asbestos)**
Electrical Backing Board	Resinous Board	1Unit	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4292/B00E/R1008/Electrical Backing Board/S32					**Chrysotile (white asbestos)**
B00E - R1009 - Movement						
No Asbestos						
B00E - R1010 - Home Base						
No Asbestos						
B00E - R1011 - Home Base						
No Asbestos						
B00E - R1012 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	71m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/R0019/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**
B00E - R1013 - Stairs						
No Asbestos						
B00E - R1014 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - General Learning/Library - 1961 - Brick/Block (Brick/Block)

Exterior

Gable verge lining	Flat AC Sheeting	60m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00A/Gable verge lining/S18					**Chrysotile (white asbestos)**
In-fill-panel	Compressed AC Sheet	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00E/In-fill-panel/S24					**Chrysotile (white asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00F - R0001 - Practical Activities - 1hb

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	
	4292/B00F/R0014/Floor Coverings Res/Textile/S10	**No Asbestos Detected**

B00F - R0002 - Home Base

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00F - R0003 - Movement

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0006 - Movement

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00F - R0007 - General Storeroom

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00F - R0008 - Staff Room Annexe

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00F - R0009 - Home Base

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00F - R0010 - Practical Activities - 1hb

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	
	4292/B00F/R0014/Floor Coverings Res/Textile/S10	**No Asbestos Detected**

B00F - R0011 - Security Store

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00F - R0012 - Garden Store

Ceiling Structures/Linings	Vermiculite	
	4292/B00E/R0012/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00F - R0013 - Home Base

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00F - R0014 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	4292/B00F/R0014/Floor Coverings Res/Textile/S10					**No Asbestos Detected**
B00F - R0015 - Sports Store						
No Asbestos						
B00F - R0016 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	4292/B00F/R0014/Floor Coverings Res/Textile/S10					**No Asbestos Detected**
B00F - R0017 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00F - R0018 - Movement						
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00F - R0019 - Movement						
No Asbestos						
B00F - R0020 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	4292/B00E/R0012/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00F - R1002 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/Build+1/Room+1/Ceiling Structures/Linings/S7					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R1003 - Distribution Board						Note: No inspection of live electrical installation.
Door Lining	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00F/R1003/Door lining/S8					**Chrysotile (white asbestos)**
B00F - R1014 - Stairs						
No Asbestos						
B00F - R1015 - Home Base						
No Asbestos						
B00F - R1016 - Practical Activities						
No Asbestos						
B00F - R1017 - General Storeroom						
No Asbestos						
B00F - R1018 - Practical Activities						
No Asbestos						
B00F - R1019 - Home Base						
No Asbestos						
B00F - R1020 - Movement						
No Asbestos						
B00F - R1021 - Special Programs Room						
No Asbestos						
B00F - R1022 - Special Programs Room						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00F - R1023 - Practical Activities						
No Asbestos						
B00F - R1024 - Home Base						
No Asbestos						
B00F - R1027 - Movement						
No Asbestos						
B00F - R1028 - Staff Toilet						
No Asbestos						
B00F - R1029 - Staff Toilet						
No Asbestos						
B00F - R1030 - Communications Cupboard						
No Asbestos						
B00F - R1031 - Practical Activities						
No Asbestos						
B00F - R1032 - Home Base						
No Asbestos						
B00F - R1033 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - General Learning - 1961 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Eaves Linings/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Gable verge lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Gable verge lining/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0001 - Outdoor Learning Area

No Asbestos

B00G - R0002 - Personal Effects Storage

No Asbestos

B00G - R0003 - Movement

No Asbestos

B00G - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/R0009/Ceiling Structures/Linings/S27					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

B00G - R0005 - Toilets - Boys/Girls

No Asbestos

B00G - R0006 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles	
	4292/B00G/R0006/Floor Coverings Res/Textile/S13	**No Asbestos Detected**

B00G - R0007 - Home Base

No Asbestos

B00G - R0008 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	
	4292/B00G/R0012/Floor Coverings Res/Textile/S12	**No Asbestos Detected**

B00G - R0009 - Movement

No Asbestos

B00G - R0010 - Movement

No Asbestos

B00G - R0011 - Toilets - Boys/Girls

No Asbestos

B00G - R0012 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	
	4292/B00G/R0012/Floor Coverings Res/Textile/S12	**No Asbestos Detected**

B00G - R0013 - Home Base

No Asbestos

B00G - R0014 - Personal Effects Storage

No Asbestos

B00G - R0015 - Movement

No Asbestos

B00G - R0016 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/R0009/Ceiling Structures/Linings/S27					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

B00G - R0017 - Personal Effects Storage

No Asbestos

B00G - R0018 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - Pupil Facilities - 1961 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Eaves Linings/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00H - R0001 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	43m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00H/R0003/Ceiling Structures/Linings/S28					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
In-fill-panel	Flat AC Sheeting	2m2	Above door	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00H/R0003/Ceiling Structures/Linings/S28					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00H/R0003/Partition Walls (Cubicles)/S4					**Chrysotile (white asbestos)**

B00H - R0002 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00H/R0003/Ceiling Structures/Linings/S28					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

B00H - R0003 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	47m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00H/R0003/Ceiling Structures/Linings/S28					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
In-fill-panel	Flat AC Sheeting	2m2	Above door	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00H/R0003/Ceiling Structures/Linings/S28					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00H/R0003/Partition Walls (Cubicles)/S4					**Chrysotile (white asbestos)**

B00H - R0004 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00H/R0003/Ceiling Structures/Linings/S28					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00I - General Learning - 1961 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	12m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Eaves Linings/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00I - R0001 - Movement

No Asbestos

B00I - R0002 - Home Base

No Asbestos

B00I - R0003 - Home Base

No Asbestos

B00I - R0004 - Practical Activities - 1hb

No Asbestos

B00I - Withdrawal Space - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00K - General Learning - 1961 - Brick/Veneer (Brick/Veneer)

Exterior

Gable verge lining	Flat AC Sheeting	18m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Gable verge lining/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Eaves Linings/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00K - R0001 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/R0003/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**

B00K - R0002 - Movement

No Asbestos

B00K - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/R0003/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**

B00K - R0004 - Staff Room Annexe

Floor Coverings Res/Textile	Vinyl Tiles	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/R0003/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**

B00K - R0005 - Home Base

No Asbestos

B00K - R0006 - Home Base Store

No Asbestos

B00K - R0007 - Practical Activities - 1hb

No Asbestos

B00K - R0008 - Movement

No Asbestos

B00K - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/R0009/Ceiling Structures/Linings/S27					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

B00K - R0010 - General Storeroom

No Asbestos

B00K - R0011 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00L - Pupil Facilities - 1961 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00K/Eaves Linings/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00L - R0001 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00L/R0002/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles					
	4292/B00L/R0003/Floor Coverings Res/Textile/S11					**No Asbestos Detected**

B00L - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00L/R0002/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**

B00L - R0003 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00L/R0002/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles					
	4292/B00L/R0003/Floor Coverings Res/Textile/S11					**No Asbestos Detected**

B00L - R0004 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00L/R0002/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**

B00L - R0005 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4292/B00L/R0002/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles					
	4292/B00L/R0003/Floor Coverings Res/Textile/S11					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00M - Communal Facilities/Pupil Facilities - 1977 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - Movement

No Asbestos

B00M - R0002 - Movement

No Asbestos

B00M - R0003 - Communal Space

No Asbestos

B00M - R0005 - Movement

No Asbestos

B00M - R0006 - Movement

No Asbestos

B00M - R0007 - Hall Chair Store

No Asbestos

B00M - R0008 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00M - R0009 - Plant

No Asbestos

B00M - R0010 - Canteen

No Asbestos

B00M - R0013 - Plant

No Asbestos

B00M - R0014 - Disabled Toilet

No Asbestos

B00M - R0015 - Lift

No Asbestos

B00M - R0016 - Raised Platform

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00N - Other - 2009 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00N - R0001 - Other-After School Care

No Asbestos

B00N - R0002 - Other-After School Care

No Asbestos

B00N - R0003 - Other-After School Care

No Asbestos

B00N - R0004 - Other-After School Care

No Asbestos

B00N - R0005 - Other-After School Care

No Asbestos

B00N - R0006 - Other-After School Care

No Asbestos

B00N - R0007 - Other-After School Care

No Asbestos

B00N - R0008 - Other-After School Care

No Asbestos

B00N - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00O - Communal Facilities - 2009 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00O - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00P - General Learning/Other - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00P - R0001 - Covered Outdoor Learning Area

No Asbestos

B00P - R0002 - Staff Toilet

No Asbestos

B00P - R0003 - Cleaning Distributed Store

No Asbestos

B00P - R0004 - Raised Platform

No Asbestos

B00P - R0005 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00P - R0006 - Reading Area

No Asbestos

B00P - R0007 - K.L.A. Store

No Asbestos

B00P - R0008 - Communications Room

No Asbestos

B00P - R0009 - Library Office/Workroom

No Asbestos

B00P - R0010 - Home Base

No Asbestos

B00P - R0011 - Home Base Store

No Asbestos

B00P - R0012 - Withdrawal Space - 1hb

No Asbestos

B00P - R0013 - Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D11114 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 6/12/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017