Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Marie Bashir Public School (4652)**
Region :	**South Western Sydney**
State Electorate :	**Strathfield**
Local Government Area :	**Strathfield**

Initial Survey :	**Parsons Brinckerhoff : 03 - Jan - 2017**
Reviewed By :	**Parsons Brinckerhoff : 03 - Jan - 2017**

4652 - Marie Bashir Public School
Site Plan (14780)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Pre-School Facilities - 1970 - Concrete Framed (Concrete Framed)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00A - M1001 - Plant

No Asbestos

B00A - M1002 - Garden Store

No Asbestos

B00A - M1003 - Stairs

No Asbestos

B00A - M1004 - Movement

No Asbestos

B00A - M1005 - Communal/Performance Store

No Asbestos

B00A - M1006 - Toilets - Boys

No Asbestos

B00A - M1007 - Handwashing Facilities

No Asbestos

B00A - M1008 - Stairs

No Asbestos

B00A - M1009 - Stairs

No Asbestos

B00A - R0001 - Other

Floor Coverings Res/Textile	Vinyl Sheet	180m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0001/Floor Covering/S16				**No asbestos detected , ,**	

B00A - R0002 - General Storeroom

No Asbestos

B00A - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0001/Floor Covering/S16				**No asbestos detected , ,**	

B00A - R0004 - Movement

Floor Coverings Res/Textile	Vinyl Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0001/Floor Covering/S16				**No asbestos detected , ,**	

B00A - R0005 - Clerical Office

Ceiling Structures/Linings	Vermiculite	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15				**No asbestos detected , ,**	

B00A - R0006 - Clerical Office

Ceiling Structures/Linings	Vermiculite	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15				**No asbestos detected , ,**	

B00A - R0008 - Movement

Ceiling Structures/Linings	Vermiculite	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15				**No asbestos detected , ,**	

B00A - R0009 - Toilets - Boys

Partition Walls (Cubicles)	Compressed Asbestos Cement	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0009/Partition/S14				**Chrysotile (white asbestos) , ,**	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R0010 - Other						
Ceiling Structures/Linings	Vermiculite	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0011 - General Storeroom						
Ceiling Structures/Linings	Vermiculite	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0012 - General Storeroom						
No Asbestos						
B00A - R0013 - General Storeroom						
No Asbestos						
B00A - R0014 - General Storeroom						
Ceiling Structures/Linings	Vermiculite	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0015 - Stairs						
No Asbestos						
B00A - R0016 - Other						
Ceiling Structures/Linings	Vermiculite	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0017 - Practical Activities						
Ceiling Structures/Linings	Vermiculite					
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected**
B00A - R0018 - Other						
Ceiling Structures/Linings	Vermiculite	115m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0019 - Other						
Ceiling Structures/Linings	Vermiculite	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0020 - Practical Activities						
Ceiling Structures/Linings	Vermiculite	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0021 - Toilets - Girls						
No Asbestos						
B00A - R0022 - Practical Activities						
Ceiling Structures/Linings	Vermiculite	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0023 - Movement						
Ceiling Structures/Linings	Vermiculite	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0024 - Stairs						
No Asbestos						
B00A - R0025 - Other						
Sink Pad	Bitumous Product	7 units	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad/S20					**No asbestos detected , ,**
Sink Pad	Adhesive	7 units	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad Adhesive/S21					**Chrysotile (white asbestos) , ,**
B00A - R0026 - Kitchen - Pre						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Sink Pad	Bitumous Product	1 Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad/S20					**No asbestos detected , ,**
Sink Pad	Adhesive	1 Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad Adhesive/S21					**Chrysotile (white asbestos) , ,**
B00A - R0027 - Other						
Sink Pad	Bitumous Product	1 Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad/S20					**No asbestos detected , ,**
Sink Pad	Adhesive	1 Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad Adhesive/S21					**Chrysotile (white asbestos) , ,**
B00A - R0028 - Clerical Office						
No Asbestos						
B00A - R0029 - Other						
Sink Pad	Adhesive	4 units	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad Adhesive/S21					**Chrysotile (white asbestos) , ,**
Sink Pad	Bitumous Product	4 units	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad/S20					**No asbestos detected , ,**
B00A - R0030 - Laundry - Pre						
No Asbestos						
B00A - R0031 - Kiln Room						
Ceiling Structures/Linings	Vermiculite	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0032 - Other						
Ceiling Structures/Linings	Vermiculite	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
Sink Pad	Bitumous Product	3 units	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad/S20					**No asbestos detected , ,**
Sink Pad	Adhesive	3 units	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad Adhesive/S21					**Chrysotile (white asbestos) , ,**
B00A - R0033 - Clerical Office						
Ceiling Structures/Linings	Vermiculite	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0034 - Movement						
Ceiling Structures/Linings	Vermiculite	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0008/Ceiling Coating/S15					**No asbestos detected , ,**
B00A - R0035 - Other						
No Asbestos						
B00A - R0036 - Movement						
No Asbestos						
B00A - R0037 - Other						
No Asbestos						
B00A - R0038 - Other						
No Asbestos						
B00A - R0039 - Other						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
Partition Walls (Cubicles)	Compressed Asbestos Cement	5m2	East & North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0009/Partition/S14					Chrysotile (white asbestos) , ,
B00A - R0040 - Other						
Heat-proof Mat	Flat Asbestos Sheet	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0041/Benchtop/S18					No asbestos detected , ,
Partition Walls (Cubicles)	Compressed Asbestos Cement	5m2	West & North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0009/Partition/S14					Chrysotile (white asbestos) , ,
B00A - R0041 - Other						
Floor Coverings Res/Textile	Vinyl Sheet	200m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0001/Floor Covering/S16					No asbestos detected , ,
Bench tops	Compressed Asbestos Cement	5 m2	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0041/Benchtop/S18					No asbestos detected , ,
Metal topped benches	Compressed Asbestos Cement	11m2	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0041/Metal Benchtop/S19					No asbestos detected , ,
B00A - R0042 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0001/Floor Covering/S16					No asbestos detected , ,
Wall Linings Internal	Flat Asbestos Sheet	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0043/Wall/S17					No asbestos detected , ,
B00A - R0043 - Other						
Floor Coverings Res/Textile	Vinyl Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0001/Floor Covering/S16					No asbestos detected , ,
Wall Linings Internal	Flat Asbestos Sheet	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0043/Wall/S17					No asbestos detected , ,
B00A - R0044 - Other						
No Asbestos						
B00A - R0045 - Other						
No Asbestos						
B00A - R0046 - Plant						
No Asbestos						
B00A - R0047 - Plant						
No Asbestos						
B00A - R0048 - Plant						
No Asbestos						
B00A - R0049 - Plant						
No Asbestos						
B00A - R0050 - Plant						
No Asbestos						
B00A - R0051 - External Movement						
No Asbestos						
B00A - R0052 - External Movement						
No Asbestos						
B00A - R0053 - Other						
No Asbestos						
B00A - R1001 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R1002 - Movement						
No Asbestos						
B00A - R1003 - Movement						
No Asbestos						
B00A - R1005 - Stairs						
No Asbestos						
B00A - R1006 - Stairs						
No Asbestos						
B00A - R1007 - Raised Platform						
No Asbestos						
B00A - R1008 - Communal Space						
No Asbestos						
B00A - R1009 - Chair Storeroom						
No Asbestos						
B00A - R1010 - General Storeroom						
No Asbestos						
B00A - R1011 - Movement						
No Asbestos						
B00A - R1012 - External Movement						
Ceiling Structures/Linings	Flat Asbestos Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0043/Wall/S17				**No asbestos detected , ,**	
B00A - R1013 - Stairs						
No Asbestos						
B00A - R1014 - External Movement						
No Asbestos						
B00A - R1015 - General Storeroom						
No Asbestos						
B00A - R1016 - External Movement						
No Asbestos						
B00A - R1017 - External Movement						
No Asbestos						
B00A - R1018 - Servery Covered Area						
Sink Pad	Bitumous Product	1 Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad/S20				**No asbestos detected , ,**	
Sink Pad	Adhesive	1 Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00A/R0032/Sink Pad Adhesive/S21				**Chrysotile (white asbestos) , ,**	
B00A - R1019 - Handwashing Facilities						
No Asbestos						
B00A - R1020 - Movement						
No Asbestos						
B00A - R1021 - Disabled Toilet						
No Asbestos						
B00A - R1022 - Toilets - Girls						
No Asbestos						
B00A - R1023 - Stairs						
No Asbestos						
B00A - R1024 - Movement						
No Asbestos						
B00A - R1025 - Movement						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

No Asbestos

B00A - R1026 - Movement

No Asbestos

B00A - R1027 - Change - Type 2

No Asbestos

B00A - R1028 - Change - Type 2

No Asbestos

B00A - R1029 - Toilets - Boys

No Asbestos

B00A - R1030 - Toilets - Girls

No Asbestos

B00A - R2001 - Communal Space

No Asbestos

B00A - R2002 - General Storeroom

No Asbestos

B00A - R2003 - General Storeroom

No Asbestos

B00A - R2004 - Movement

No Asbestos

B00A - R2005 - Plant

No Asbestos

B00A - R2006 - Stairs

No Asbestos

B00A - R2007 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Administration/Pre-School Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	75m2	Various Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0052/Ceiling/S04					Chrysotile (white asbestos), Crocidolite (blue asbestos) , ,
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00B - R0001 - General Storeroom

No Asbestos

B00B - R0002 - Clerical Office/Workroom

No Asbestos

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - General Storeroom

No Asbestos

B00B - R0005 - Clerical Office - Pre

No Asbestos

B00B - R0006 - General Storeroom - Pre

No Asbestos

B00B - R0007 - Other

No Asbestos

B00B - R0008 - Entry Vestibule

No Asbestos

B00B - R0009 - Clerical Office - Pre

No Asbestos

B00B - R0010 - Sick Bay

No Asbestos

B00B - R0011 - Sick Bay

No Asbestos

B00B - R0012 - Toilets-Unisex

No Asbestos

B00B - R0013 - Sick Bay

No Asbestos

B00B - R0014 - Movement

No Asbestos

B00B - R0015 - Movement

No Asbestos

B00B - R0016 - Interview

No Asbestos

B00B - R0017 - Principal

No Asbestos

B00B - R0018 - Staff Toilet

No Asbestos

B00B - R0019 - Disabled Toilet

No Asbestos

B00B - R0020 - Staff Toilet - Pre

No Asbestos

B00B - R0021 - Kitchen - Pre

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
No Asbestos						
B00B - R0022 - Staff Room						
No Asbestos						
B00B - R0023 - Movement						
Electrical Dist Board	Compressed Bitumous Board	2 Units	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Assumed Positive - Not Sampled					
B00B - R0024 - Distribution Board						Note: No inspection of live electrical installation.
Electrical Mounting Board	Compressed Bitumous Board	2 Units	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	Not Sampled Sealed Unit					**Assumed Positive , ,**
B00B - R0025 - Deputy Principal						
No Asbestos						
B00B - R0026 - Special Programs Room						
No Asbestos						
B00B - R0027 - Practical Activities						
Ceiling Structures/Linings	Flat Asbestos sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0054/Ceiling/S03					**No asbestos detected , ,**
B00B - R0028 - Home Base						
Ceiling Structures/Linings	Flat Asbestos sheet	95m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0054/Ceiling/S03					**No asbestos detected , ,**
B00B - R0029 - Practical Activities						
Ceiling Structures/Linings	Flat Asbestos sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0054/Ceiling/S03					**No asbestos detected , ,**
B00B - R0030 - Home Base						
Ceiling Structures/Linings	Flat Asbestos sheet	95m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0054/Ceiling/S03					**No asbestos detected , ,**
B00B - R0031 - Practical Activities						
Ceiling Structures/Linings	Flat Asbestos sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0054/Ceiling/S03					**No asbestos detected , ,**
B00B - R0032 - Home Base						
Ceiling Structures/Linings	Flat Asbestos sheet	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0054/Ceiling/S03					**No asbestos detected , ,**
B00B - R0033 - Home Base						
Ceiling Structures/Linings	Flat Asbestos sheet	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0054/Ceiling/S03					**No asbestos detected , ,**
B00B - R0034 - Home Base						
Ceiling Structures/Linings	Flat Asbestos sheet	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0054/Ceiling/S03					**No asbestos detected , ,**
B00B - R0035 - Home Base						
No Asbestos						
B00B - R0036 - Withdrawal Space - 2hb						
No Asbestos						
B00B - R0037 - Home Base						
No Asbestos						
B00B - R0038 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00B - R0039 - Other						
No Asbestos						
B00B - R0040 - Other						
Infil Panel	Flat Asbestos sheet	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0040/Infill panel/S05				**No asbestos detected , ,**	
B00B - R0041 - Movement						
No Asbestos						
B00B - R0042 - Toilets - Girls						
No Asbestos						
B00B - R0043 - Movement						
No Asbestos						
B00B - R0044 - Toilets - Boys						
No Asbestos						
B00B - R0048 - Other						
No Asbestos						
B00B - R0049 - Other						
No Asbestos						
B00B - R0050 - External Movement						
No Asbestos						
B00B - R0051 - Other						
No Asbestos						
B00B - R0052 - External Movement						
Ceiling Structures/Linings	Flat Asbestos sheet	40m2	East Middle Section	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0052/Ceiling/S04				**Chrysotile (white asbestos), Crocidolite (blue asbestos) , ,**	
B00B - R0053 - General Storeroom						
No Asbestos						
B00B - R0054 - Toilets-Unisex						
No Asbestos						
B00B - R0055 - External Stairs						
No Asbestos						
B00B - R0056 - Stairs						
No Asbestos						
B00B - R0057 - General Storeroom						
No Asbestos						
B00B - R0058 - General Storeroom						
No Asbestos						
B00B - R0059 - External Stairs						
No Asbestos						
B00B - R0060 - External Stairs						
No Asbestos						
B00B - R0061 - External Movement						
No Asbestos						
B00B - R1001 - Other						
No Asbestos						
B00B - R1002 - Other						
No Asbestos						
B00B - R1003 - Other						
Electrical Mounting Board	Compressed Bitumous Board	2 Units	South East	Good Condition (1)	Low (1)	Low Priority (2-3)
	Not Sampled Sealed Unit				**Assumed Positive , ,**	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R1006/Floor Covering/S06					**No asbestos detected , ,**
Fume Hood	Flat Asbestos sheet	2 Units	North &South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R1003/Fumehood/S07					**Chrysotile (white asbestos), Crocidolite (blue asbestos), Amosite (brown asbestos) , ,**
B00B - R1004 - Other						
No Asbestos						
B00B - R1005 - External Movement						
Ceiling Structures/Linings	Flat Asbestos sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0052/Ceiling/S04					**Chrysotile (white asbestos), Crocidolite (blue asbestos) , ,**
B00B - R1006 - Other						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R1006/Floor Covering/S06					**No asbestos detected , ,**
Thermacon Heater	Insulation	1 unit	South West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Not Sampled Sealed Unit					**Assumed Positive , ,**
B00B - R1007 - Other						
No Asbestos						
B00B - R1008 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R1006/Floor Covering/S06					**No asbestos detected , ,**
B00B - R1009 - Other						
Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R1006/Floor Covering/S06					**No asbestos detected , ,**
B00B - R1010 - Other						
No Asbestos						
B00B - R1011 - Other						
No Asbestos						
B00B - R1012 - Other						
No Asbestos						
B00B - R1013 - Other						
No Asbestos						
B00B - R1014 - Other						
No Asbestos						
B00B - R1015 - Other						
No Asbestos						
B00B - R1016 - Other						
No Asbestos						
B00B - R1017 - Raised Platform						
No Asbestos						
B00B - R1018 - Other						
No Asbestos						
B00B - R1019 - Other						
No Asbestos						
B00B - R1020 - Other						
No Asbestos						
B00B - R1021 - Stairs						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
Ceiling Structures/Linings	Flat Asbestos sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0052/Ceiling/S04					Chrysotile (white asbestos), Crocidolite (blue asbestos) , ,
B00B - R1022 - External Stairs						
Infil Panel	Flat Asbestos sheet	6m2	North & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R1022/Infill panel/S08					**No asbestos detected , ,**
B00B - R1023 - External Movement						
Ceiling Structures/Linings	Flat Asbestos sheet	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R0052/Ceiling/S04					Chrysotile (white asbestos), Crocidolite (blue asbestos) , ,
B00B - R1024 - External Movement						
No Asbestos						
B00B - R9001 - Other						
No Asbestos						
B00B - R9002 - Other						
No Asbestos						
B00B - R9003 - Other						
Ceiling Structures/Linings	Vermiculite	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R9004/Ceiling Coating/S02					**No asbestos detected , ,**
B00B - R9004 - Other						
Ceiling Structures/Linings	Vermiculite	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R9004/Ceiling Coating/S02					**No asbestos detected , ,**
B00B - R9005 - Other						
No Asbestos						
B00B - R9006 - Change - Type 2						
No Asbestos						
B00B - R9007 - Toilets - Girls						
No Asbestos						
B00B - R9008 - Movement						
No Asbestos						
B00B - R9009 - Handwashing Facilities						
No Asbestos						
B00B - R9010 - Other						
No Asbestos						
B00B - R9011 - Movement						
No Asbestos						
B00B - R9012 - Other						
No Asbestos						
B00B - R9013 - External Movement						
No Asbestos						
B00B - R9014 - Other						
Packing to beams	Flat Asbestos sheet	0.2m2	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R9014/Packing/S01					**No asbestos detected , ,**
B00B - R9015 - Other						
Packing to beams	Flat Asbestos sheet	0.2m2	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00B/R9014/Packing/S01					**No asbestos detected , ,**
B00B - R9016 - Other						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00B - R9017 - Other

No Asbestos

B00B - R9018 - Movement

No Asbestos

B00B - R9019 - Other

No Asbestos

B00B - R9020 - Other

No Asbestos

B00B - R9021 - Other

No Asbestos

B00B - R9022 - Movement

No Asbestos

B00B - R9023 - Movement

No Asbestos

B00B - R9024 - Other

No Asbestos

B00B - R9025 - External Stairs

No Asbestos

B00B - R9026 - External Movement

No Asbestos

B00B - R9027 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Library/Pre-School Facilities - 1970 - Concrete Framed (Concrete Framed)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00C - R0001 - Other

Ceiling Structures/Linings	Vermiculite	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00C/R0001/Ceiling Coating/S09					**No asbestos detected , ,**

B00C - R0002 - Other

Ceiling Structures/Linings	Vermiculite	135m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00C/R0001/Ceiling Coating/S09					**No asbestos detected , ,**

B00C - R0003 - External Movement

No Asbestos

B00C - R0004 - External Movement

No Asbestos

B00C - R0005 - External Stairs

No Asbestos

B00C - R0006 - No Access

No Asbestos

B00C - R1001 - External Movement

No Asbestos

B00C - R1002 - General Storeroom

No Asbestos

B00C - R1003 - Other

No Asbestos

B00C - R1004 - Other

No Asbestos

B00C - R1005 - Other

No Asbestos

B00C - R1006 - Reading Area

No Asbestos

B00C - R1007 - Other

No Asbestos

B00C - R1008 - Toilets-Unisex

No Asbestos

B00C - R1009 - Movement

No Asbestos

B00C - R1010 - Other

No Asbestos

B00C - R1011 - Stairs

No Asbestos

B00C - R1012 - External Stairs

No Asbestos

B00C - R1013 - External Stairs

Ceiling Structures/Linings	Flat Asbestos Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00C/R00+1/Ceiling/S11					**Chrysotile (white asbestos) , ,**

B00C - R2001 - Seminar/Study

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B00C - R2002 - Seminar/Study

No Asbestos

B00C - R2003 - Other

No Asbestos

B00C - R2004 - Computer Room

No Asbestos

B00C - R2005 - Other

No Asbestos

B00C - R2006 - Movement

No Asbestos

B00C - R2007 - Other

No Asbestos

B00C - R2008 - Other

No Asbestos

B00C - R2009 - Other

No Asbestos

B00C - R2010 - Other

No Asbestos

B00C - R2011 - Movement

No Asbestos

B00C - R2012 - Other

No Asbestos

B00C - R2013 - External Stairs

Expansion Joint	Mastic	3m	Window	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00C/R2013/Expansion Joint/S10					**No asbestos detected , ,**

B00C - R2014 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00D - Other - 1970 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00D - R0002 - Home Base

Ceiling Structures/Linings	Vermiculite	130m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00D/R0003/Ceiling Coating/S13					**No asbestos detected , ,**

B00D - R0003 - Staff Room

Ceiling Structures/Linings	Vermiculite	26m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00D/R0003/Ceiling Coating/S13					**No asbestos detected , ,**

B00D - R0004 - General Storeroom

No Asbestos

B00D - R0005 - Toilet - Lobby

No Asbestos

B00D - R0006 - Toilets - Girls

Partition Walls (Cubicles)	Compressed Asbestos Cement	10m2	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00D/R0006/Partition/S12					**Chrysotile (white asbestos) , ,**

B00D - R0007 - Other

No Asbestos

B00D - R0008 - Toilets - Boys

Partition Walls (Cubicles)	Compressed Asbestos Cement	8m2	Various	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00D/R0006/Partition/S12					**Chrysotile (white asbestos) , ,**

B00D - R0009 - Toilet - Lobby

No Asbestos

B00D - R0010 - External Movement

No Asbestos

B00D - R0011 - External Movement

No Asbestos

B00D - R0012 - External Stairs

No Asbestos

B00D - R0013 - External Stairs

No Asbestos

B00D - R1001 - Home Base

Ceiling Structures/Linings	Vermiculite	120m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00D/R0003/Ceiling Coating/S13					**No asbestos detected , ,**

B00D - R1002 - General Storeroom

Ceiling Structures/Linings	Vermiculite	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00D/R0003/Ceiling Coating/S13					**No asbestos detected , ,**

B00D - R1003 - Home Base

Ceiling Structures/Linings	Vermiculite	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00D/R0003/Ceiling Coating/S13					**No asbestos detected , ,**

B00D - R1004 - Home Base

Ceiling Structures/Linings	Vermiculite	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4652/B00D/R0003/Ceiling Coating/S13					**No asbestos detected , ,**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00D - R1005 - External Movement

No Asbestos

B00D - R1006 - External Stairs

No Asbestos

B00D - R1007 - External Stairs

No Asbestos

B00D - R1008 - External Stairs

No Asbestos

B00D - R1009 - External Stairs

No Asbestos

B00D - R2001 - Home Base

No Asbestos

B00D - R2002 - General Storeroom

No Asbestos

B00D - R2003 - Home Base

No Asbestos

B00D - R2004 - Home Base

No Asbestos

B00D - R2005 - External Movement

No Asbestos

B00D - R2006 - External Stairs

No Asbestos

B00D - R2007 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017