Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Rydalmere Public School (3020)**
Region :	**Western Sydney**
State Electorate :	**Parramatta**
Local Government Area :	**Parramatta**

Initial Survey :	**Noel Arnold & Associates : 21 - Jan - 2008**
Reviewed By :	**Parsons Brinckerhoff : 03 - May - 2015**

3020 - Rydalmere Public School
Site Plan (11542)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Administration - 1959 - Brick/Block (Brick/Block)

Exterior

Gable verge lining	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Gable verge lining/S24					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Eaves Linings/S23					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Staff Room Annexe

No Asbestos

B00A - R0002 - Sick Bay

Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Room+1/Floor Coverings Res/Textile/S21					**Chrysotile (white asbestos)**

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/R0004/Ceiling Structures/Linings/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00A - R0006 - Entry Vestibule

No Asbestos

B00A - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/R0004/Ceiling Structures/Linings/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00A - R0009 - Principal

No Asbestos

B00A - R0010 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/R0010/Wall Linings Internal/S22					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00A - R0011 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3020/B00A/Room+1/Floor Coverings Res/Textile/S21					**Chrysotile (white asbestos)**

B00A - R0012 - Interview

No Asbestos

B00A - R0013 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Room+1/Floor Coverings Res/Textile/S21					**Chrysotile (white asbestos)**

B00A - R0014 - Staff Room

No Asbestos

B00A - R0015 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/R0010/Wall Linings Internal/S22					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R0016 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/R0010/Wall Linings Internal/S22					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00A - R0017 - Duplicating Workroom						
No Asbestos						
B00A - R0018 - Clerical Office						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning - 1957 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/Eaves Linings/S25					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Gable verge lining	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Gable verge lining/S24					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Wall Cladding	Flat AC Sheeting					
	3020/B00F/Wall Cladding/S26					**No Asbestos Detected**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - Movement

Wall Linings Internal	Flat AC Sheeting	6m2	East facing, West facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00B/R0001/Wall Linings Internal/S15					**Chrysotile (white asbestos)**

B00B - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles	20m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00B/R0003/Floor Coverings Res/Textile/S16					**Chrysotile (white asbestos)**

B00B - R0003 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles	47m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00B/R0003/Floor Coverings Res/Textile/S16					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Other-Community Use - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Eaves Linings/S23					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Gable verge lining	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Gable verge lining/S24					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Home Base Store

No Asbestos

B00C - R0002 - Personal Effects Storage

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Communal Space

No Asbestos

B00C - R0006 - Music Store

No Asbestos

B00C - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	
	3020/B00C/R0008/Ceiling Structures/Linings/S14	**No Asbestos Detected**

B00C - R0009 - Home Base

No Asbestos

B00C - R0010 - Home Base Store

No Asbestos

B00C - R0011 - Personal Effects Storage

No Asbestos

B00C - R0012 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - General Learning - 1959 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Cleaning Supplies

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	3020/B00D/R0001/Floor Coverings Res/Textile/S19					**Chrysotile (white asbestos)**

B00D - R0002 - Movement

No Asbestos

B00D - R0003 - Home Base

No Asbestos

B00D - R0004 - Home Base

No Asbestos

B00D - R0005 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - General Learning - 1958 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/Eaves Linings/S25					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Gable verge lining	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Gable verge lining/S24					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Wall Cladding	Flat AC Sheeting					
	3020/B00F/Wall Cladding/S26					**No Asbestos Detected**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00E/R0009/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

B00E - R0002 - Personal Effects Storage

No Asbestos

B00E - R0003 - Home Base

No Asbestos

B00E - R0007 - Movement

No Asbestos

B00E - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00E/R0009/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

B00E - R0011 - Deputy Principal

No Asbestos

B00E - R0012 - Staff Toilet

No Asbestos

B00E - R0013 - Community Clinic

No Asbestos

B00E - R0014 - General Storeroom

No Asbestos

B00E - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00E/R0009/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

B00E - R0016 - Movement

No Asbestos

B00E - R0017 - Staff Room

No Asbestos

B00E - R0018 - Covered Outdoor Learning Area

No Asbestos

B00E - R0019 - Home Base

No Asbestos

B00E - R0020 - Practical Activities - 1hb

No Asbestos

B00E - R0021 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00E - R0022 - Home Base Store						
No Asbestos						
B00E - R0023 - Home Base Store						
No Asbestos						
B00E - R0024 - Home Base						
No Asbestos						
B00E - R0025 - Practical Activities - 1hb						
No Asbestos						
B00E - R0026 - Withdrawal Space - 1hb						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - General Learning - 1959 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting	70m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/Eaves Linings/S25					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Gable verge lining	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Gable verge lining/S24					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Wall Cladding	Flat AC Sheeting					
	3020/B00F/Wall Cladding/S26					**No Asbestos Detected**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00E/R0009/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

B00F - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00E/R0009/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

B00F - R0009 - Movement

No Asbestos

B00F - R0010 - Home Base

No Asbestos

B00F - R0011 - Practical Activities - 1hb

No Asbestos

B00F - R0012 - Withdrawal Space - 2hb

No Asbestos

B00F - R0013 - Home Base Store

No Asbestos

B00F - R0014 - Practical Activities - 1hb

No Asbestos

B00F - R0015 - Home Base

No Asbestos

B00F - R0016 - Practical Activities - 1hb

No Asbestos

B00F - R0017 - Home Base

No Asbestos

B00F - R0018 - Movement

No Asbestos

B00F - R0019 - Home Base Store

No Asbestos

B00F - R0020 - Withdrawal Space - 2hb

No Asbestos

B00F - R0021 - Practical Activities - 1hb

No Asbestos

B00F - R0022 - Home Base

No Asbestos

B00F - R9001 - Canteen Office/Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/R9002/Ceiling Structures/Linings/S4					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R9002 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/R9002/Ceiling Structures/Linings/S4					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R9003 - Canteen						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/R9002/Ceiling Structures/Linings/S4					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R9004 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/R9002/Ceiling Structures/Linings/S4					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R9005 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/R9002/Ceiling Structures/Linings/S4					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R9007 - Sports Store						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00F/R9002/Ceiling Structures/Linings/S4					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R9008 - Canteen Covered Area						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - Library - 1963 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00G/Eaves Linings/S11					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0001 - Library Office/Workroom

No Asbestos

B00G - R0002 - Reading Area

No Asbestos

B00G - R0003 - Reading Area

No Asbestos

B00G - R0005 - External Movement

No Asbestos

B00G - R0007 - General Storeroom

No Asbestos

B00G - R0008 - Communications Room

Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00G/R0008/Floor Coverings Res/Textile/S13					**Chrysotile (white asbestos)**

B00G - R0009 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	3020/B00G/R0009/Floor Coverings Res/Textile/S27					**No Asbestos Detected**

B00G - R0010 - K.L.A. Store

No Asbestos

B00G - R0011 - Movement

No Asbestos

B00G - R0012 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - Pre-School Facilities - 1960 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/Eaves Linings/S5					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Movement

No Asbestos

B00H - R0002 - Staff Room - Pre

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0010/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00H - R0005 - Home Base - Pre

Floor Coverings Res/Textile	Vinyl Tiles					
	3020/B00H/R0010/Floor Coverings Res/Textile/S7					**No Asbestos Detected**
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0010/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00H - R0006 - General Storeroom - Pre

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0010/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00H - R0007 - Toilets - Boys/Girls

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0010/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00H - R0008 - Kitchen - Pre

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0010/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Wall Linings Internal	Flat AC Sheeting	20m2	North facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0008/Wall Linings Internal/S9					**Chrysotile (white asbestos)**

B00H - R0009 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0009/Wall Linings Internal/S8					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0010/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00H - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0010/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles					
	3020/B00H/R0010/Floor Coverings Res/Textile/S7					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00H - R0011 - Home Base - Pre						
Wall Linings Internal	Flat AC Sheeting	4m2	South east low level only	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0009/Wall Linings Internal/S8					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00H/R0010/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00H - R9001 - Security Store						
Wall Linings Internal	Flat AC Sheeting					
	3020/B00H/R9001/Wall Linings Internal/S10					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00M - Pupil Facilities/Administration - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	15m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00A/Eaves Linings/S23					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00M - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00M/R0004/Partition Walls (Cubicles)/S18					**Chrysotile (white asbestos)**

B00M - R0002 - General Storeroom

No Asbestos

B00M - R0003 - Movement

No Asbestos

B00M - R0004 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3020/B00M/R0004/Partition Walls (Cubicles)/S18					**Chrysotile (white asbestos)**

B00M - R0005 - Security Store

Ceiling Structures/Linings	Flat AC Sheeting					
	3020/B00M/R0005/Ceiling Structures/Linings/S28					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017